




EUT Mode


802.11ax HE20 106RU54

Plot on 6415 MHz




11:55:37 AM 05/15/2025

Plot on 6515 MHz




11:54:57 AM 05/16/2025

Plot on 6855 MHz



04:16:27 PM 05/16/2025


Plot on 6875 MHz



05:31:41 PM 05/16/2025



Plot on 7115 MHz






MIMO <Ant. 1+2(1)>


EUT Mode

802.11ax HE40 FullIRU


Plot on 5965 MHz




Plot on 6205 MHz



Plot on 6405 MHz




Plot on 6445 MHz







Plot on 6485 MHz




Plot on 6525 MHz




Plot on 6565 MHz




Plot on 6685 MHz



Plot on 6845 MHz




Plot on 6885 MHz







Plot on 6925 MHz



Plot on 7005 MHz



Plot on 7085 MHz






EUT Mode


802.11ax HE40 242RU61

Plot on 5965 MHz




11:58:06 AM 05/19/2025

Plot on 6205 MHz




12:13:39 PM 05/19/2025

Plot on 6445 MHz



12:33:34 PM 05/19/2025


Plot on 6565 MHz




02:28:11 PM 05/19/2025



Plot on 6685 MHz



Plot on 6925 MHz






EUT Mode


802.11ax HE40 242RU62

Plot on 6405 MHz




12:25:04 PM 05/19/2025

Plot on 6485 MHz




02:10:51 PM 05/19/2025

Plot on 6525 MHz



02:18:33 PM 05/19/2025


Plot on 6845 MHz




02:59:07 PM 05/19/2025




Plot on 6885 MHz



Plot on 7005 MHz



Plot on 7085 MHz






MIMO <Ant. 1+2(2)>


EUT Mode

802.11ax HE40 FullIRU


Plot on 5965 MHz




Plot on 6205 MHz



Plot on 6405 MHz




Plot on 6445 MHz







Plot on 6485 MHz




Plot on 6525 MHz




Plot on 6565 MHz




Plot on 6685 MHz



Plot on 6845 MHz




Plot on 6885 MHz







Plot on 6925 MHz



Plot on 7005 MHz



Plot on 7085 MHz






EUT Mode


802.11ax HE40 242RU61

Plot on 5965 MHz




11:59:20 AM 05/19/2025

Plot on 6205 MHz




12:14:34 PM 05/19/2025

Plot on 6445 MHz



12:34:15 PM 05/19/2025


Plot on 6565 MHz




02:29:27 PM 05/19/2025



Plot on 6685 MHz



Plot on 6925 MHz







EUT Mode

802.11ax HE40 242RU62


Plot on 6405 MHz




Plot on 6485 MHz



Plot on 6525 MHz




Plot on 6845 MHz






Plot on 6885 MHz



Plot on 7005 MHz



Plot on 7085 MHz

