





Band5-5MHz-QPSK-20425-1RB#0-Range1:30~1000MHz




Band5-5MHz-QPSK-20425-1RB#0-Range2:1000~10000MHz




Band5-5MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



Band5-5MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz




Band5-5MHz-QPSK-20625-1RB#0-Range1:30~1000MHz




Band5-5MHz-QPSK-20625-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-5MHz-16QAM-20425-1RB#0-Range1:30~1000MHz




Band5-5MHz-16QAM-20425-1RB#0-Range2:1000~10000MHz




Band5-5MHz-16QAM-20525-1RB#0-Range1:30~1000MHz



Band5-5MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz




Band5-5MHz-16QAM-20625-1RB#0-Range1:30~1000MHz




Band5-5MHz-16QAM-20625-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-10MHz-QPSK-20450-1RB#0-Range1:30~1000MHz




Band5-10MHz-QPSK-20450-1RB#0-Range2:1000~10000MHz




Band5-10MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



Band5-10MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz




Band5-10MHz-QPSK-20600-1RB#0-Range1:30~1000MHz




Band5-10MHz-QPSK-20600-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-10MHz-16QAM-20450-1RB#0-Range1:30~1000MHz




Band5-10MHz-16QAM-20450-1RB#0-Range2:1000~10000MHz




Band5-10MHz-16QAM-20525-1RB#0-Range1:30~1000MHz



Band5-10MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz




Band5-10MHz-16QAM-20600-1RB#0-Range1:30~1000MHz




Band5-10MHz-16QAM-20600-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-1.4MHz-QPSK-23017-1RB#0-Range1:30~1000MHz




Band12-1.4MHz-QPSK-23017-1RB#0-Range2:1000~10000MHz




Band12-1.4MHz-QPSK-23095-1RB#0-Range1:30~1000MHz



Band12-1.4MHz-QPSK-23095-1RB#0-Range2:1000~10000MHz




Band12-1.4MHz-QPSK-23173-1RB#0-Range1:30~1000MHz




Band12-1.4MHz-QPSK-23173-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-1.4MHz-16QAM-23017-1RB#0-Range1:30~1000MHz




Band12-1.4MHz-16QAM-23017-1RB#0-Range2:1000~10000MHz




Band12-1.4MHz-16QAM-23095-1RB#0-Range1:30~1000MHz



Band12-1.4MHz-16QAM-23095-1RB#0-Range2:1000~10000MHz




Band12-1.4MHz-16QAM-23173-1RB#0-Range1:30~1000MHz




Band12-1.4MHz-16QAM-23173-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-3MHz-QPSK-23025-1RB#0-Range1:30~1000MHz




Band12-3MHz-QPSK-23025-1RB#0-Range2:1000~10000MHz




Band12-3MHz-QPSK-23095-1RB#0-Range1:30~1000MHz



Band12-3MHz-QPSK-23095-1RB#0-Range2:1000~10000MHz




Band12-3MHz-QPSK-23165-1RB#0-Range1:30~1000MHz




Band12-3MHz-QPSK-23165-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-3MHz-16QAM-23025-1RB#0-Range1:30~1000MHz




Band12-3MHz-16QAM-23025-1RB#0-Range2:1000~10000MHz




Band12-3MHz-16QAM-23095-1RB#0-Range1:30~1000MHz



Band12-3MHz-16QAM-23095-1RB#0-Range2:1000~10000MHz




Band12-3MHz-16QAM-23165-1RB#0-Range1:30~1000MHz




Band12-3MHz-16QAM-23165-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-5MHz-QPSK-23035-1RB#0-Range1:30~1000MHz




Band12-5MHz-QPSK-23035-1RB#0-Range2:1000~10000MHz




Band12-5MHz-QPSK-23095-1RB#0-Range1:30~1000MHz



Band12-5MHz-QPSK-23095-1RB#0-Range2:1000~10000MHz




Band12-5MHz-QPSK-23155-1RB#0-Range1:30~1000MHz




Band12-5MHz-QPSK-23155-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-5MHz-16QAM-23035-1RB#0-Range1:30~1000MHz




Band12-5MHz-16QAM-23035-1RB#0-Range2:1000~10000MHz




Band12-5MHz-16QAM-23095-1RB#0-Range1:30~1000MHz



Band12-5MHz-16QAM-23095-1RB#0-Range2:1000~10000MHz




Band12-5MHz-16QAM-23155-1RB#0-Range1:30~1000MHz




Band12-5MHz-16QAM-23155-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-10MHz-QPSK-23060-1RB#0-Range1:30~1000MHz




Band12-10MHz-QPSK-23060-1RB#0-Range2:1000~10000MHz




Band12-10MHz-QPSK-23095-1RB#0-Range1:30~1000MHz



Band12-10MHz-QPSK-23095-1RB#0-Range2:1000~10000MHz




Band12-10MHz-QPSK-23130-1RB#0-Range1:30~1000MHz




Band12-10MHz-QPSK-23130-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-10MHz-16QAM-23060-1RB#0-Range1:30~1000MHz




Band12-10MHz-16QAM-23060-1RB#0-Range2:1000~10000MHz




Band12-10MHz-16QAM-23095-1RB#0-Range1:30~1000MHz



Band12-10MHz-16QAM-23095-1RB#0-Range2:1000~10000MHz




Band12-10MHz-16QAM-23130-1RB#0-Range1:30~1000MHz




Band12-10MHz-16QAM-23130-1RB#0-Range2:1000~10000MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band13-5MHz-QPSK-23205-1RB#0-Range1:30~1000MHz




Band13-5MHz-QPSK-23205-1RB#0-Range2:1000~10000MHz




Band13-5MHz-QPSK-23205-1RB#0-Range3:1559~1610MHz



Band13-5MHz-QPSK-23230-1RB#0-Range1:30~1000MHz




Band13-5MHz-QPSK-23230-1RB#0-Range2:1000~10000MHz




Band13-5MHz-QPSK-23230-1RB#0-Range3:1559~1610MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band13-5MHz-QPSK-23255-1RB#0-Range1:30~1000MHz




Band13-5MHz-QPSK-23255-1RB#0-Range2:1000~10000MHz




Band13-5MHz-QPSK-23255-1RB#0-Range3:1559~1610MHz



Band13-5MHz-16QAM-23205-1RB#0-Range1:30~1000MHz




Band13-5MHz-16QAM-23205-1RB#0-Range2:1000~10000MHz




Band13-5MHz-16QAM-23205-1RB#0-Range3:1559~1610MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band13-5MHz-16QAM-23230-1RB#0-Range1:30~1000MHz




Band13-5MHz-16QAM-23230-1RB#0-Range2:1000~10000MHz




Band13-5MHz-16QAM-23230-1RB#0-Range3:1559~1610MHz



Band13-5MHz-16QAM-23255-1RB#0-Range1:30~1000MHz




Band13-5MHz-16QAM-23255-1RB#0-Range2:1000~10000MHz




Band13-5MHz-16QAM-23255-1RB#0-Range3:1559~1610MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band13-10MHz-QPSK-23230-1RB#0-Range1:30~1000MHz




Band13-10MHz-QPSK-23230-1RB#0-Range2:1000~10000MHz




Band13-10MHz-QPSK-23230-1RB#0-Range3:1559~1610MHz



Band13-10MHz-16QAM-23230-1RB#0-Range1:30~1000MHz




Band13-10MHz-16QAM-23230-1RB#0-Range2:1000~10000MHz




Band13-10MHz-16QAM-23230-1RB#0-Range3:1559~1610MHz


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band17-5MHz-QPSK-23755-1RB#0-Range1:30~1000MHz




Band17-5MHz-QPSK-23755-1RB#0-Range2:1000~10000MHz




Band17-5MHz-QPSK-23790-1RB#0-Range1:30~1000MHz



Band17-5MHz-QPSK-23790-1RB#0-Range2:1000~10000MHz



Band17-5MHz-QPSK-23825-1RB#0-Range1:30~1000MHz



Band17-5MHz-QPSK-23825-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch