





Restrict Band NVNT ac160 5250MHz Ant4 Peak



Restrict Band NVNT ac160 5250MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ac160 5250MHz Ant4 Peak



Restrict Band NVNT ac160 5250MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT ax20 5180MHz Ant4 Peak




Restrict Band NVNT ax20 5180MHz Ant4 Average





Restrict Band NVNT ax20 5240MHz Ant4 Peak



Restrict Band NVNT ax20 5240MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ax40 5190MHz Ant4 Peak



Restrict Band NVNT ax40 5190MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT ax40 5230MHz Ant4 Peak




Restrict Band NVNT ax40 5230MHz Ant4 Average






Restrict Band NVNT ax80 5210MHz Ant4 Peak




Restrict Band NVNT ax80 5210MHz Ant4 Average





Restrict Band NVNT ax80 5210MHz Ant4 Peak



Restrict Band NVNT ax80 5210MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ax160 5250MHz Ant4 Peak



Restrict Band NVNT ax160 5250MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ax160 5250MHz Ant4 Peak



Restrict Band NVNT ax160 5250MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT be20 5180MHz Ant4 Peak



Restrict Band NVNT be20 5180MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT be20 5240MHz Ant4 Peak



Restrict Band NVNT be20 5240MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT be40 5190MHz Ant4 Peak



Restrict Band NVNT be40 5190MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT be40 5230MHz Ant4 Peak




Restrict Band NVNT be40 5230MHz Ant4 Average






Restrict Band NVNT be80 5210MHz Ant4 Peak




Restrict Band NVNT be80 5210MHz Ant4 Average






Restrict Band NVNT be80 5210MHz Ant4 Peak




Restrict Band NVNT be80 5210MHz Ant4 Average





Restrict Band NVNT be160 5250MHz Ant4 Peak



Restrict Band NVNT be160 5250MHz Ant4 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT be160 5250MHz Ant4 Peak



Restrict Band NVNT be160 5250MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5180	Ant5	4500	-51.1	6.49	50.62	Peak	68.2	Pass
NVNT	a	5180	Ant5	4500	-59.07	6.49	42.65	Average	54	Pass
NVNT	a	5180	Ant5	5148.2	-44.5	6.49	57.22	Peak	68.2	Pass
NVNT	a	5180	Ant5	5149.6	-50.17	6.49	51.55	Average	54	Pass
NVNT	a	5180	Ant5	5150	-45.99	6.49	55.73	Peak	68.2	Pass
NVNT	a	5180	Ant5	5150	-49.34	6.49	52.38	Average	54	Pass
NVNT	a	5240	Ant5	5350	-49.9	6.49	51.82	Peak	68.2	Pass
NVNT	a	5240	Ant5	5350	-57.21	6.49	44.51	Average	54	Pass
NVNT	a	5240	Ant5	5401.68	-47.74	6.49	53.98	Peak	68.2	Pass
NVNT	a	5240	Ant5	5437.2	-56.86	6.49	44.86	Average	54	Pass
NVNT	a	5240	Ant5	5460	-50.26	6.49	51.46	Peak	68.2	Pass
NVNT	a	5240	Ant5	5460	-57.16	6.49	44.56	Average	54	Pass
NVNT	n20	5180	Ant5	4500	-50.58	6.49	51.14	Peak	68.2	Pass
NVNT	n20	5180	Ant5	4500	-59.12	6.49	42.6	Average	54	Pass
NVNT	n20	5180	Ant5	5149.6	-44.96	6.49	56.76	Peak	68.2	Pass
NVNT	n20	5180	Ant5	5148.9	-51.51	6.49	50.21	Average	54	Pass
NVNT	n20	5180	Ant5	5150	-47.76	6.49	53.96	Peak	68.2	Pass
NVNT	n20	5180	Ant5	5150	-50.99	6.49	50.73	Average	54	Pass
NVNT	n20	5240	Ant5	5350	-51.66	6.49	50.06	Peak	68.2	Pass
NVNT	n20	5240	Ant5	5350	-57.38	6.49	44.34	Average	54	Pass
NVNT	n20	5240	Ant5	5389.44	-46.96	6.49	54.76	Peak	68.2	Pass
NVNT	n20	5240	Ant5	5455.2	-56.69	6.49	45.03	Average	54	Pass
NVNT	n20	5240	Ant5	5460	-50.48	6.49	51.24	Peak	68.2	Pass
NVNT	n20	5240	Ant5	5460	-56.96	6.49	44.76	Average	54	Pass
NVNT	n40	5190	Ant5	4500	-51.14	6.49	50.58	Peak	68.2	Pass
NVNT	n40	5190	Ant5	4500	-58.92	6.49	42.8	Average	54	Pass
NVNT	n40	5190	Ant5	5145.32	-45.57	6.49	56.15	Peak	68.2	Pass
NVNT	n40	5190	Ant5	5149.7	-50.04	6.49	51.68	Average	54	Pass
NVNT	n40	5190	Ant5	5150	-44.88	6.49	56.84	Peak	68.2	Pass
NVNT	n40	5190	Ant5	5150	-49.6	6.49	52.12	Average	54	Pass
NVNT	n40	5230	Ant5	5350	-51.18	6.49	50.54	Peak	68.2	Pass
NVNT	n40	5230	Ant5	5350	-57.08	6.49	44.64	Average	54	Pass
NVNT	n40	5230	Ant5	5440.29	-46.77	6.49	54.95	Peak	68.2	Pass
NVNT	n40	5230	Ant5	5395.2	-56.62	6.49	45.1	Average	54	Pass
NVNT	n40	5230	Ant5	5460	-50.8	6.49	50.92	Peak	68.2	Pass
NVNT	n40	5230	Ant5	5460	-56.89	6.49	44.83	Average	54	Pass
NVNT	ac20	5180	Ant5	4500	-52.58	6.49	49.14	Peak	68.2	Pass
NVNT	ac20	5180	Ant5	4500	-58.17	6.49	43.55	Average	54	Pass
NVNT	ac20	5180	Ant5	5149.6	-42.31	6.49	59.41	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5180	Ant5	5149.6	-49.57	6.49	52.15	Average	54	Pass
NVNT	ac20	5180	Ant5	5150	-45.21	6.49	56.51	Peak	68.2	Pass
NVNT	ac20	5180	Ant5	5150	-49.68	6.49	52.04	Average	54	Pass
NVNT	ac20	5240	Ant5	5350	-50.72	6.49	51	Peak	68.2	Pass
NVNT	ac20	5240	Ant5	5350	-56.9	6.49	44.82	Average	54	Pass
NVNT	ac20	5240	Ant5	5406.72	-47.66	6.49	54.06	Peak	68.2	Pass
NVNT	ac20	5240	Ant5	5425.68	-56.32	6.49	45.4	Average	54	Pass
NVNT	ac20	5240	Ant5	5460	-47.85	6.49	53.87	Peak	68.2	Pass
NVNT	ac20	5240	Ant5	5460	-56.88	6.49	44.84	Average	54	Pass
NVNT	ac40	5190	Ant5	4500	-52.83	6.49	48.89	Peak	68.2	Pass
NVNT	ac40	5190	Ant5	4500	-58.82	6.49	42.9	Average	54	Pass
NVNT	ac40	5190	Ant5	5149.7	-45.49	6.49	56.23	Peak	68.2	Pass
NVNT	ac40	5190	Ant5	5149.7	-50.61	6.49	51.11	Average	54	Pass
NVNT	ac40	5190	Ant5	5150	-46.47	6.49	55.25	Peak	68.2	Pass
NVNT	ac40	5190	Ant5	5150	-50.34	6.49	51.38	Average	54	Pass
NVNT	ac40	5230	Ant5	5350	-49.45	6.49	52.27	Peak	68.2	Pass
NVNT	ac40	5230	Ant5	5350	-57.06	6.49	44.66	Average	54	Pass
NVNT	ac40	5230	Ant5	5404.65	-46.78	6.49	54.94	Peak	68.2	Pass
NVNT	ac40	5230	Ant5	5439.75	-56.78	6.49	44.94	Average	54	Pass
NVNT	ac40	5230	Ant5	5460	-49.02	6.49	52.7	Peak	68.2	Pass
NVNT	ac40	5230	Ant5	5460	-57.08	6.49	44.64	Average	54	Pass
NVNT	ac80	5210	Ant5	5350	-50.39	6.49	51.33	Peak	68.2	Pass
NVNT	ac80	5210	Ant5	5350	-56.63	6.49	45.09	Average	54	Pass
NVNT	ac80	5210	Ant5	5445.48	-47.63	6.49	54.09	Peak	68.2	Pass
NVNT	ac80	5210	Ant5	5421.72	-56.13	6.49	45.59	Average	54	Pass
NVNT	ac80	5210	Ant5	5460	-49.78	6.49	51.94	Peak	68.2	Pass
NVNT	ac80	5210	Ant5	5460	-56.72	6.49	45	Average	54	Pass
NVNT	ac80	5210	Ant5	4500	-52.37	6.49	49.35	Peak	68.2	Pass
NVNT	ac80	5210	Ant5	4500	-58.8	6.49	42.92	Average	54	Pass
NVNT	ac80	5210	Ant5	5137.53	-44.61	6.49	57.11	Peak	68.2	Pass
NVNT	ac80	5210	Ant5	5144.64	-50.02	6.49	51.7	Average	54	Pass
NVNT	ac80	5210	Ant5	5150	-46.02	6.49	55.7	Peak	68.2	Pass
NVNT	ac80	5210	Ant5	5150	-50.4	6.49	51.32	Average	54	Pass
NVNT	ac160	5250	Ant5	5350	-50.47	6.49	51.25	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5350	-55.22	6.49	46.5	Average	54	Pass
NVNT	ac160	5250	Ant5	5381.19	-46.67	6.49	55.05	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5392.29	-54.67	6.49	47.05	Average	54	Pass
NVNT	ac160	5250	Ant5	5460	-49.2	6.49	52.52	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5460	-56.32	6.49	45.4	Average	54	Pass
NVNT	ac160	5250	Ant5	4500	-51.02	6.49	50.7	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	4500	-58.7	6.49	43.02	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac160	5250	Ant5	5127.9	-44.93	6.49	56.79	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5126.99	-50.6	6.49	51.12	Average	54	Pass
NVNT	ac160	5250	Ant5	5150	-48.71	6.49	53.01	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5150	-52.99	6.49	48.73	Average	54	Pass
NVNT	ax20	5180	Ant5	4500	-51.25	6.49	50.47	Peak	68.2	Pass
NVNT	ax20	5180	Ant5	4500	-58.69	6.49	43.03	Average	54	Pass
NVNT	ax20	5180	Ant5	5145.4	-44.15	6.49	57.57	Peak	68.2	Pass
NVNT	ax20	5180	Ant5	5148.9	-49.92	6.49	51.8	Average	54	Pass
NVNT	ax20	5180	Ant5	5150	-49.15	6.49	52.57	Peak	68.2	Pass
NVNT	ax20	5180	Ant5	5150	-50.5	6.49	51.22	Average	54	Pass
NVNT	ax20	5240	Ant5	5350	-51.15	6.49	50.57	Peak	68.2	Pass
NVNT	ax20	5240	Ant5	5350	-56.44	6.49	45.28	Average	54	Pass
NVNT	ax20	5240	Ant5	5430.48	-47.37	6.49	54.35	Peak	68.2	Pass
NVNT	ax20	5240	Ant5	5452.8	-55.89	6.49	45.83	Average	54	Pass
NVNT	ax20	5240	Ant5	5460	-50.82	6.49	50.9	Peak	68.2	Pass
NVNT	ax20	5240	Ant5	5460	-56.41	6.49	45.31	Average	54	Pass
NVNT	ax40	5190	Ant5	4500	-51.96	6.49	49.76	Peak	68.2	Pass
NVNT	ax40	5190	Ant5	4500	-58.44	6.49	43.28	Average	54	Pass
NVNT	ax40	5190	Ant5	5145.32	-44.81	6.49	56.91	Peak	68.2	Pass
NVNT	ax40	5190	Ant5	5148.97	-50.5	6.49	51.22	Average	54	Pass
NVNT	ax40	5190	Ant5	5150	-47.73	6.49	53.99	Peak	68.2	Pass
NVNT	ax40	5190	Ant5	5150	-50.17	6.49	51.55	Average	54	Pass
NVNT	ax40	5230	Ant5	5350	-49.16	6.49	52.56	Peak	68.2	Pass
NVNT	ax40	5230	Ant5	5350	-56.29	6.49	45.43	Average	54	Pass
NVNT	ax40	5230	Ant5	5401.41	-46.28	6.49	55.44	Peak	68.2	Pass
NVNT	ax40	5230	Ant5	5441.64	-56.02	6.49	45.7	Average	54	Pass
NVNT	ax40	5230	Ant5	5460	-50.49	6.49	51.23	Peak	68.2	Pass
NVNT	ax40	5230	Ant5	5460	-56.35	6.49	45.37	Average	54	Pass
NVNT	ax80	5210	Ant5	5350	-50.32	6.49	51.4	Peak	68.2	Pass
NVNT	ax80	5210	Ant5	5350	-56.91	6.49	44.81	Average	54	Pass
NVNT	ax80	5210	Ant5	5457.69	-46.21	6.49	55.51	Peak	68.2	Pass
NVNT	ax80	5210	Ant5	5417.76	-56.07	6.49	45.65	Average	54	Pass
NVNT	ax80	5210	Ant5	5460	-50.7	6.49	51.02	Peak	68.2	Pass
NVNT	ax80	5210	Ant5	5460	-56.55	6.49	45.17	Average	54	Pass
NVNT	ax80	5210	Ant5	4500	-52.12	6.49	49.6	Peak	68.2	Pass
NVNT	ax80	5210	Ant5	4500	-58.83	6.49	42.89	Average	54	Pass
NVNT	ax80	5210	Ant5	5148.59	-44.45	6.49	57.27	Peak	68.2	Pass
NVNT	ax80	5210	Ant5	5148.59	-49.41	6.49	52.31	Average	54	Pass
NVNT	ax80	5210	Ant5	5150	-44.31	6.49	57.41	Peak	68.2	Pass
NVNT	ax80	5210	Ant5	5150	-49.36	6.49	52.36	Average	54	Pass
NVNT	ax160	5250	Ant5	5350	-48.48	6.49	53.24	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ax160	5250	Ant5	5350	-54.65	6.49	47.07	Average	54	Pass
NVNT	ax160	5250	Ant5	5456.3	-46.31	6.49	55.41	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	5364.91	-54.43	6.49	47.29	Average	54	Pass
NVNT	ax160	5250	Ant5	5460	-50.7	6.49	51.02	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	5460	-56.15	6.49	45.57	Average	54	Pass
NVNT	ax160	5250	Ant5	4500	-50.96	6.49	50.76	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	4500	-58.56	6.49	43.16	Average	54	Pass
NVNT	ax160	5250	Ant5	5124.26	-42.99	6.49	58.73	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	5148.83	-48.81	6.49	52.91	Average	54	Pass
NVNT	ax160	5250	Ant5	5150	-45.48	6.49	56.24	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	5150	-50.31	6.49	51.41	Average	54	Pass
NVNT	be20	5180	Ant5	4500	-50.71	6.49	51.01	Peak	68.2	Pass
NVNT	be20	5180	Ant5	4500	-58.58	6.49	43.14	Average	54	Pass
NVNT	be20	5180	Ant5	5149.6	-46.49	6.49	55.23	Peak	68.2	Pass
NVNT	be20	5180	Ant5	5147.5	-50.04	6.49	51.68	Average	54	Pass
NVNT	be20	5180	Ant5	5150	-48.06	6.49	53.66	Peak	68.2	Pass
NVNT	be20	5180	Ant5	5150	-50.62	6.49	51.1	Average	54	Pass
NVNT	be20	5240	Ant5	5350	-50.38	6.49	51.34	Peak	68.2	Pass
NVNT	be20	5240	Ant5	5350	-56.85	6.49	44.87	Average	54	Pass
NVNT	be20	5240	Ant5	5445.12	-46.71	6.49	55.01	Peak	68.2	Pass
NVNT	be20	5240	Ant5	5442	-56.06	6.49	45.66	Average	54	Pass
NVNT	be20	5240	Ant5	5460	-49.83	6.49	51.89	Peak	68.2	Pass
NVNT	be20	5240	Ant5	5460	-56.5	6.49	45.22	Average	54	Pass
NVNT	be40	5190	Ant5	4500	-52.88	6.49	48.84	Peak	68.2	Pass
NVNT	be40	5190	Ant5	4500	-58.58	6.49	43.14	Average	54	Pass
NVNT	be40	5190	Ant5	5148.24	-43.73	6.49	57.99	Peak	68.2	Pass
NVNT	be40	5190	Ant5	5149.7	-49.94	6.49	51.78	Average	54	Pass
NVNT	be40	5190	Ant5	5150	-43.63	6.49	58.09	Peak	68.2	Pass
NVNT	be40	5190	Ant5	5150	-49.67	6.49	52.05	Average	54	Pass
NVNT	be40	5230	Ant5	5350	-50.38	6.49	51.34	Peak	68.2	Pass
NVNT	be40	5230	Ant5	5350	-56.23	6.49	45.49	Average	54	Pass
NVNT	be40	5230	Ant5	5368.74	-47.66	6.49	54.06	Peak	68.2	Pass
NVNT	be40	5230	Ant5	5358.75	-56.12	6.49	45.6	Average	54	Pass
NVNT	be40	5230	Ant5	5460	-49.92	6.49	51.8	Peak	68.2	Pass
NVNT	be40	5230	Ant5	5460	-56.48	6.49	45.24	Average	54	Pass
NVNT	be80	5210	Ant5	5350	-51.34	6.49	50.38	Peak	68.2	Pass
NVNT	be80	5210	Ant5	5350	-56.8	6.49	44.92	Average	54	Pass
NVNT	be80	5210	Ant5	5402.91	-46.39	6.49	55.33	Peak	68.2	Pass
NVNT	be80	5210	Ant5	5453.4	-55.85	6.49	45.87	Average	54	Pass
NVNT	be80	5210	Ant5	5460	-48.43	6.49	53.29	Peak	68.2	Pass
NVNT	be80	5210	Ant5	5460	-56.54	6.49	45.18	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




NVNT	be80	5210	Ant5	4500	-51.96	6.49	49.76	Peak	68.2	Pass
NVNT	be80	5210	Ant5	4500	-58.42	6.49	43.3	Average	54	Pass
NVNT	be80	5210	Ant5	5148.59	-45.2	6.49	56.52	Peak	68.2	Pass
NVNT	be80	5210	Ant5	5146.22	-50.14	6.49	51.58	Average	54	Pass
NVNT	be80	5210	Ant5	5150	-47.06	6.49	54.66	Peak	68.2	Pass
NVNT	be80	5210	Ant5	5150	-50.2	6.49	51.52	Average	54	Pass
NVNT	be160	5250	Ant5	5350	-49.35	6.49	52.37	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5350	-54.79	6.49	46.93	Average	54	Pass
NVNT	be160	5250	Ant5	5394.14	-45.81	6.49	55.91	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5350.85	-54.76	6.49	46.96	Average	54	Pass
NVNT	be160	5250	Ant5	5460	-50.21	6.49	51.51	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5460	-56.16	6.49	45.56	Average	54	Pass
NVNT	be160	5250	Ant5	4500	-50.83	6.49	50.89	Peak	68.2	Pass
NVNT	be160	5250	Ant5	4500	-58.54	6.49	43.18	Average	54	Pass
NVNT	be160	5250	Ant5	5130.63	-44.4	6.49	57.32	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5126.99	-49.18	6.49	52.54	Average	54	Pass
NVNT	be160	5250	Ant5	5150	-44.57	6.49	57.15	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5150	-50.73	6.49	50.99	Average	54	Pass






Restrict Band NVNT a 5180MHz Ant5 Peak




Restrict Band NVNT a 5180MHz Ant5 Average





Restrict Band NVNT a 5240MHz Ant5 Peak



Restrict Band NVNT a 5240MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT n20 5180MHz Ant5 Peak




Restrict Band NVNT n20 5180MHz Ant5 Average





Restrict Band NVNT n20 5240MHz Ant5 Peak



Restrict Band NVNT n20 5240MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT n40 5190MHz Ant5 Peak



Restrict Band NVNT n40 5190MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT n40 5230MHz Ant5 Peak



Restrict Band NVNT n40 5230MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ac20 5180MHz Ant5 Peak



Restrict Band NVNT ac20 5180MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT ac20 5240MHz Ant5 Peak




Restrict Band NVNT ac20 5240MHz Ant5 Average






Restrict Band NVNT ac40 5190MHz Ant5 Peak




Restrict Band NVNT ac40 5190MHz Ant5 Average





Restrict Band NVNT ac40 5230MHz Ant5 Peak



Restrict Band NVNT ac40 5230MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT ac80 5210MHz Ant5 Peak




Restrict Band NVNT ac80 5210MHz Ant5 Average





Restrict Band NVNT ac80 5210MHz Ant5 Peak



Restrict Band NVNT ac80 5210MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ac160 5250MHz Ant5 Peak



Restrict Band NVNT ac160 5250MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ac160 5250MHz Ant5 Peak



Restrict Band NVNT ac160 5250MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT ax20 5180MHz Ant5 Peak




Restrict Band NVNT ax20 5180MHz Ant5 Average






Restrict Band NVNT ax20 5240MHz Ant5 Peak




Restrict Band NVNT ax20 5240MHz Ant5 Average





Restrict Band NVNT ax40 5190MHz Ant5 Peak



Restrict Band NVNT ax40 5190MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ax40 5230MHz Ant5 Peak



Restrict Band NVNT ax40 5230MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT ax80 5210MHz Ant5 Peak




Restrict Band NVNT ax80 5210MHz Ant5 Average





Restrict Band NVNT ax80 5210MHz Ant5 Peak



Restrict Band NVNT ax80 5210MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ax160 5250MHz Ant5 Peak



Restrict Band NVNT ax160 5250MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ax160 5250MHz Ant5 Peak



Restrict Band NVNT ax160 5250MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT be20 5180MHz Ant5 Peak




Restrict Band NVNT be20 5180MHz Ant5 Average






Restrict Band NVNT be20 5240MHz Ant5 Peak




Restrict Band NVNT be20 5240MHz Ant5 Average





Restrict Band NVNT be40 5190MHz Ant5 Peak



Restrict Band NVNT be40 5190MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT be40 5230MHz Ant5 Peak



Restrict Band NVNT be40 5230MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT be80 5210MHz Ant5 Peak




Restrict Band NVNT be80 5210MHz Ant5 Average





Restrict Band NVNT be80 5210MHz Ant5 Peak



Restrict Band NVNT be80 5210MHz Ant5 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Restrict Band NVNT be160 5250MHz Ant5 Peak




Restrict Band NVNT be160 5250MHz Ant5 Average





Restrict Band NVNT be160 5250MHz Ant5 Peak



Restrict Band NVNT be160 5250MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity




B.5 Frequency Stability

Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	a	5180	Ant1	5179.94	-60000	-11.58	25	Pass
NVNT	a	5200	Ant1	5199.94	-60000	-11.54	25	Pass
NVNT	a	5240	Ant1	5239.96	-40000	-7.63	25	Pass
NVNT	n20	5180	Ant1	5179.96	-40000	-7.72	25	Pass
NVNT	n20	5200	Ant1	5199.98	-20000	-3.85	25	Pass
NVNT	n20	5240	Ant1	5239.96	-40000	-7.63	25	Pass
NVNT	n40	5190	Ant1	5189.92	-80000	-15.41	25	Pass
NVNT	n40	5230	Ant1	5229.96	-40000	-7.65	25	Pass
NVNT	ac20	5180	Ant1	5179.98	-20000	-3.86	25	Pass
NVNT	ac20	5200	Ant1	5199.94	-60000	-11.54	25	Pass
NVNT	ac20	5240	Ant1	5239.98	-20000	-3.82	25	Pass
NVNT	ac40	5190	Ant1	5190	0	0	25	Pass
NVNT	ac40	5230	Ant1	5229.96	-40000	-7.65	25	Pass
NVNT	ac80	5210	Ant1	5209.92	-80000	-15.36	25	Pass
NVNT	ac160	5250	Ant1	5250	0	0	25	Pass
NVNT	ax20	5180	Ant1	5179.96	-40000	-7.72	25	Pass
NVNT	ax20	5200	Ant1	5199.96	-40000	-7.69	25	Pass
NVNT	ax20	5240	Ant1	5239.96	-40000	-7.63	25	Pass
NVNT	ax40	5190	Ant1	5189.96	-40000	-7.71	25	Pass
NVNT	ax40	5230	Ant1	5229.96	-40000	-7.65	25	Pass
NVNT	ax80	5210	Ant1	5210	0	0	25	Pass
NVNT	ax160	5250	Ant1	5250	0	0	25	Pass
NVNT	be20	5180	Ant1	5179.96	-40000	-7.72	25	Pass
NVNT	be20	5200	Ant1	5199.96	-40000	-7.69	25	Pass
NVNT	be20	5240	Ant1	5239.96	-40000	-7.63	25	Pass
NVNT	be40	5190	Ant1	5189.96	-40000	-7.71	25	Pass
NVNT	be40	5230	Ant1	5229.96	-40000	-7.65	25	Pass
NVNT	be80	5210	Ant1	5210	0	0	25	Pass
NVNT	be160	5250	Ant1	5250	0	0	25	Pass






Freq. Stability NVNT a 5180MHz Ant1




Freq. Stability NVNT a 5200MHz Ant1






Freq. Stability NVNT a 5240MHz Ant1




Freq. Stability NVNT n20 5180MHz Ant1






Freq. Stability NVNT n20 5200MHz Ant1




Freq. Stability NVNT n20 5240MHz Ant1





Freq. Stability NVNT n40 5190MHz Ant1



Freq. Stability NVNT n40 5230MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Freq. Stability NVNT ac20 5180MHz Ant1




Freq. Stability NVNT ac20 5200MHz Ant1





Freq. Stability NVNT ac20 5240MHz Ant1



Freq. Stability NVNT ac40 5190MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity