






Freq. Stability NVNT n20 5200MHz Ant5




Freq. Stability NVNT n20 5240MHz Ant5






Freq. Stability NVNT n40 5190MHz Ant5




Freq. Stability NVNT n40 5230MHz Ant5






Freq. Stability NVNT ac20 5180MHz Ant5




Freq. Stability NVNT ac20 5200MHz Ant5





Freq. Stability NVNT ac20 5240MHz Ant5



Freq. Stability NVNT ac40 5190MHz Ant5




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Freq. Stability NVNT ac40 5230MHz Ant5



Freq. Stability NVNT ac80 5210MHz Ant5




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Freq. Stability NVNT ac160 5250MHz Ant5



Freq. Stability NVNT ax20 5180MHz Ant5




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Freq. Stability NVNT ax20 5200MHz Ant5




Freq. Stability NVNT ax20 5240MHz Ant5





Freq. Stability NVNT ax40 5190MHz Ant5



Freq. Stability NVNT ax40 5230MHz Ant5




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Freq. Stability NVNT ax80 5210MHz Ant5




Freq. Stability NVNT ax160 5250MHz Ant5






Freq. Stability NVNT be20 5180MHz Ant5




Freq. Stability NVNT be20 5200MHz Ant5





Freq. Stability NVNT be20 5240MHz Ant5



Freq. Stability NVNT be40 5190MHz Ant5




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Freq. Stability NVNT be40 5230MHz Ant5



Freq. Stability NVNT be80 5210MHz Ant5





Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



B.6 Duty Cycle

Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5180	Ant1	96.53	0.15	0.72
NVNT	a	5200	Ant1	95.86	0.18	0.72
NVNT	a	5240	Ant1	96.53	0.15	0.72
NVNT	n20	5180	Ant1	96.3	0.16	0.77
NVNT	n20	5200	Ant1	95.56	0.2	0.78
NVNT	n20	5240	Ant1	96.27	0.17	0.78
NVNT	n40	5190	Ant1	92.65	0.33	1.59
NVNT	n40	5230	Ant1	91.3	0.4	1.59
NVNT	ac20	5180	Ant1	86.05	0.65	2.7
NVNT	ac20	5200	Ant1	84.09	0.75	2.7
NVNT	ac20	5240	Ant1	86.05	0.65	2.7
NVNT	ac40	5190	Ant1	77.78	1.09	4.76
NVNT	ac40	5230	Ant1	80.77	0.93	4.76
NVNT	ac80	5210	Ant1	68.42	1.65	7.69
NVNT	ac160	5250	Ant1	82.5	0.84	3.03
NVNT	ax20	5180	Ant1	87.5	0.58	2.86
NVNT	ax20	5200	Ant1	87.5	0.58	2.86
NVNT	ax20	5240	Ant1	87.5	0.58	2.86
NVNT	ax40	5190	Ant1	87.5	0.58	2.86
NVNT	ax40	5230	Ant1	87.8	0.56	2.78
NVNT	ax80	5210	Ant1	85	0.71	2.94
NVNT	ax160	5250	Ant1	82.5	0.84	3.03
NVNT	be20	5180	Ant1	87.5	0.58	2.86
NVNT	be20	5200	Ant1	87.8	0.56	2.78
NVNT	be20	5240	Ant1	87.8	0.56	2.78
NVNT	be40	5190	Ant1	87.8	0.56	2.78
NVNT	be40	5230	Ant1	87.8	0.56	2.78
NVNT	be80	5210	Ant1	85.37	0.69	2.86
NVNT	be160	5250	Ant1	87.5	0.58	2.86




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT a 5180MHz Ant1



Duty Cycle NVNT a 5200MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT a 5240MHz Ant1



Duty Cycle NVNT n20 5180MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT n20 5200MHz Ant1



Duty Cycle NVNT n20 5240MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT n40 5190MHz Ant1



Duty Cycle NVNT n40 5230MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT ac20 5180MHz Ant1




Duty Cycle NVNT ac20 5200MHz Ant1






Duty Cycle NVNT ac20 5240MHz Ant1




Duty Cycle NVNT ac40 5190MHz Ant1






Duty Cycle NVNT ac40 5230MHz Ant1




Duty Cycle NVNT ac80 5210MHz Ant1





Duty Cycle NVNT ac160 5250MHz Ant1



Duty Cycle NVNT ax20 5180MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT ax20 5200MHz Ant1



Duty Cycle NVNT ax20 5240MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT ax40 5190MHz Ant1




Duty Cycle NVNT ax40 5230MHz Ant1






Duty Cycle NVNT ax80 5210MHz Ant1




Duty Cycle NVNT ax160 5250MHz Ant1





Duty Cycle NVNT be20 5180MHz Ant1



Duty Cycle NVNT be20 5200MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT be20 5240MHz Ant1



Duty Cycle NVNT be40 5190MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT be40 5230MHz Ant1



Duty Cycle NVNT be80 5210MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity





Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5180	Ant2	95.86	0.18	0.72
NVNT	a	5200	Ant2	96.53	0.15	0.72
NVNT	a	5240	Ant2	96.55	0.15	0.71
NVNT	n20	5180	Ant2	96.3	0.16	0.77
NVNT	n20	5200	Ant2	95.56	0.2	0.78
NVNT	n20	5240	Ant2	95.56	0.2	0.78
NVNT	n40	5190	Ant2	97.4	0.11	0.53
NVNT	n40	5230	Ant2	96.89	0.14	0.53
NVNT	ac20	5180	Ant2	93.52	0.29	0.99
NVNT	ac20	5200	Ant2	95.28	0.21	0.99
NVNT	ac20	5240	Ant2	94.44	0.25	0.98
NVNT	ac40	5190	Ant2	95.15	0.22	1.02
NVNT	ac40	5230	Ant2	94.23	0.26	1.02
NVNT	ac80	5210	Ant2	91.18	0.4	1.61
NVNT	ac160	5250	Ant2	87.18	0.6	2.94
NVNT	ax20	5180	Ant2	94.32	0.25	1.2
NVNT	ax20	5200	Ant2	93.26	0.3	1.2
NVNT	ax20	5240	Ant2	94.32	0.25	1.2
NVNT	ax40	5190	Ant2	93.26	0.3	1.2
NVNT	ax40	5230	Ant2	94.38	0.25	1.19
NVNT	ax80	5210	Ant2	91.94	0.37	1.75
NVNT	ax160	5250	Ant2	85	0.71	2.94
NVNT	be20	5180	Ant2	83.33	0.79	2.86
NVNT	be20	5200	Ant2	87.5	0.58	2.86
NVNT	be20	5240	Ant2	87.5	0.58	2.86
NVNT	be40	5190	Ant2	93.33	0.3	1.19
NVNT	be40	5230	Ant2	92.31	0.35	1.19
NVNT	be80	5210	Ant2	92.06	0.36	1.72
NVNT	be160	5250	Ant2	87.5	0.58	2.86




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT a 5180MHz Ant2




Duty Cycle NVNT a 5200MHz Ant2






Duty Cycle NVNT a 5240MHz Ant2




Duty Cycle NVNT n20 5180MHz Ant2






Duty Cycle NVNT n20 5200MHz Ant2




Duty Cycle NVNT n20 5240MHz Ant2





Duty Cycle NVNT n40 5190MHz Ant2



Duty Cycle NVNT n40 5230MHz Ant2




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT ac20 5180MHz Ant2




Duty Cycle NVNT ac20 5200MHz Ant2





Duty Cycle NVNT ac20 5240MHz Ant2



Duty Cycle NVNT ac40 5190MHz Ant2




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT ac40 5230MHz Ant2



Duty Cycle NVNT ac80 5210MHz Ant2




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT ac160 5250MHz Ant2




Duty Cycle NVNT ax20 5180MHz Ant2





Duty Cycle NVNT ax20 5200MHz Ant2



Duty Cycle NVNT ax20 5240MHz Ant2




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT ax40 5190MHz Ant2




Duty Cycle NVNT ax40 5230MHz Ant2






Duty Cycle NVNT ax80 5210MHz Ant2




Duty Cycle NVNT ax160 5250MHz Ant2





Duty Cycle NVNT be20 5180MHz Ant2



Duty Cycle NVNT be20 5200MHz Ant2




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT be20 5240MHz Ant2



Duty Cycle NVNT be40 5190MHz Ant2




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT be40 5230MHz Ant2



Duty Cycle NVNT be80 5210MHz Ant2







Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5180	Ant3	95.86	0.18	0.72
NVNT	a	5200	Ant3	96.53	0.15	0.72
NVNT	a	5240	Ant3	95.86	0.18	0.72
NVNT	n20	5180	Ant3	95.59	0.2	0.77
NVNT	n20	5200	Ant3	95.56	0.2	0.78
NVNT	n20	5240	Ant3	96.3	0.16	0.77
NVNT	n40	5190	Ant3	97.4	0.11	0.53
NVNT	n40	5230	Ant3	96.89	0.14	0.53
NVNT	ac20	5180	Ant3	95.33	0.21	0.98
NVNT	ac20	5200	Ant3	95.33	0.21	0.98
NVNT	ac20	5240	Ant3	95.28	0.21	0.99
NVNT	ac40	5190	Ant3	95.15	0.22	1.02
NVNT	ac40	5230	Ant3	95.15	0.22	1.02
NVNT	ac80	5210	Ant3	92.65	0.33	1.59
NVNT	ac160	5250	Ant3	87.18	0.6	2.94
NVNT	ax20	5180	Ant3	87.5	0.58	2.86
NVNT	ax20	5200	Ant3	85	0.71	2.94
NVNT	ax20	5240	Ant3	87.5	0.58	2.86
NVNT	ax40	5190	Ant3	93.26	0.3	1.2
NVNT	ax40	5230	Ant3	94.38	0.25	1.19
NVNT	ax80	5210	Ant3	90.48	0.43	1.75
NVNT	ax160	5250	Ant3	85	0.71	2.94
NVNT	be20	5180	Ant3	87.8	0.56	2.78
NVNT	be20	5200	Ant3	85.37	0.69	2.86
NVNT	be20	5240	Ant3	87.8	0.56	2.78
NVNT	be40	5190	Ant3	94.38	0.25	1.19
NVNT	be40	5230	Ant3	94.38	0.25	1.19
NVNT	be80	5210	Ant3	85	0.71	2.94
NVNT	be160	5250	Ant3	85	0.71	2.94




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT a 5180MHz Ant3



Duty Cycle NVNT a 5200MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT a 5240MHz Ant3



Duty Cycle NVNT n20 5180MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT n20 5200MHz Ant3



Duty Cycle NVNT n20 5240MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT n40 5190MHz Ant3



Duty Cycle NVNT n40 5230MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT ac20 5180MHz Ant3



Duty Cycle NVNT ac20 5200MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT ac20 5240MHz Ant3



Duty Cycle NVNT ac40 5190MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT ac40 5230MHz Ant3



Duty Cycle NVNT ac80 5210MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT ac160 5250MHz Ant3




Duty Cycle NVNT ax20 5180MHz Ant3





Duty Cycle NVNT ax20 5200MHz Ant3



Duty Cycle NVNT ax20 5240MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT ax40 5190MHz Ant3




Duty Cycle NVNT ax40 5230MHz Ant3






Duty Cycle NVNT ax80 5210MHz Ant3




Duty Cycle NVNT ax160 5250MHz Ant3





Duty Cycle NVNT be20 5180MHz Ant3



Duty Cycle NVNT be20 5200MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT be20 5240MHz Ant3




Duty Cycle NVNT be40 5190MHz Ant3





Duty Cycle NVNT be40 5230MHz Ant3



Duty Cycle NVNT be80 5210MHz Ant3

