





Test Graphs

Freq. Stability NVNT a 5180MHz Ant5



Freq. Stability NVNT a 5200MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT a 5240MHz Ant5



Freq. Stability NVNT n20 5180MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n20 5200MHz Ant5



Freq. Stability NVNT n20 5240MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n40 5190MHz Ant5




Freq. Stability NVNT n40 5230MHz Ant5






Freq. Stability NVNT ac20 5180MHz Ant5




Freq. Stability NVNT ac20 5200MHz Ant5






Freq. Stability NVNT ac20 5240MHz Ant5




Freq. Stability NVNT ac40 5190MHz Ant5






Freq. Stability NVNT ac40 5230MHz Ant5




Freq. Stability NVNT ac80 5210MHz Ant5






Freq. Stability NVNT ax20 5180MHz Ant5



Freq. Stability NVNT ax20 5200MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5240MHz Ant5



Freq. Stability NVNT ax40 5190MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax40 5230MHz Ant5




Freq. Stability NVNT ax80 5210MHz Ant5






Freq. Stability NVNT be20 5180MHz Ant5




Freq. Stability NVNT be20 5200MHz Ant5






Freq. Stability NVNT be20 5240MHz Ant5




Freq. Stability NVNT be40 5190MHz Ant5






Freq. Stability NVNT be40 5230MHz Ant5




Freq. Stability NVNT be80 5210MHz Ant5





Freq. Stability NVNT ac160 5250MHz Ant5





Freq. Stability NVNT ax160 5250MHz Ant5







B.6 Duty Cycle


Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5180	Ant3	94.56	0.24	0.91
NVNT	a	5200	Ant3	94.65	0.24	0.91
NVNT	a	5240	Ant3	94.56	0.24	0.91
NVNT	n20	5180	Ant3	97.29	0.12	0.44
NVNT	n20	5200	Ant3	97.29	0.12	0.44
NVNT	n20	5240	Ant3	97.33	0.12	0.44
NVNT	n40	5190	Ant3	94.71	0.24	0.9
NVNT	n40	5230	Ant3	94.71	0.24	0.9
NVNT	ac20	5180	Ant3	97.3	0.12	0.44
NVNT	ac20	5200	Ant3	97.3	0.12	0.44
NVNT	ac20	5240	Ant3	97.34	0.12	0.44
NVNT	ac40	5190	Ant3	94.72	0.24	0.9
NVNT	ac40	5230	Ant3	94.81	0.23	0.9
NVNT	ac80	5210	Ant3	89.65	0.47	1.86
NVNT	ax20	5180	Ant3	97.3	0.12	0.44
NVNT	ax20	5200	Ant3	97.34	0.12	0.44
NVNT	ax20	5240	Ant3	97.34	0.12	0.44
NVNT	ax40	5190	Ant3	94.72	0.24	0.9
NVNT	ax40	5230	Ant3	94.72	0.24	0.9
NVNT	ax80	5210	Ant3	89.82	0.47	1.86
NVNT	be20	5180	Ant3	97.34	0.12	0.44
NVNT	be20	5200	Ant3	97.3	0.12	0.44
NVNT	be20	5240	Ant3	97.3	0.12	0.44
NVNT	be40	5190	Ant3	94.72	0.24	0.9
NVNT	be40	5230	Ant3	94.72	0.24	0.9
NVNT	be80	5210	Ant3	89.82	0.47	1.86
NVNT	ac160	5250	Ant3	41.94	3.77	5.49
NVNT	ax160	5250	Ant3	41.94	3.77	5.49
NVNT	be160	5250	Ant3	42.03	3.76	5.49






Test Graphs

Duty Cycle NVNT a 5180MHz Ant3




Duty Cycle NVNT a 5200MHz Ant3








Duty Cycle NVNT a 5240MHz Ant3




Duty Cycle NVNT n20 5180MHz Ant3








Duty Cycle NVNT n40 5190MHz Ant3




Duty Cycle NVNT n40 5230MHz Ant3






Duty Cycle NVNT ac20 5180MHz Ant3



Duty Cycle NVNT ac20 5200MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac20 5240MHz Ant3



Duty Cycle NVNT ac40 5190MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac40 5230MHz Ant3




Duty Cycle NVNT ac80 5210MHz Ant3






Duty Cycle NVNT ax20 5180MHz Ant3



Duty Cycle NVNT ax20 5200MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax20 5240MHz Ant3




Duty Cycle NVNT ax40 5190MHz Ant3






Duty Cycle NVNT ax40 5230MHz Ant3



Duty Cycle NVNT ax80 5210MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT be20 5180MHz Ant3




Duty Cycle NVNT be20 5200MHz Ant3






Duty Cycle NVNT be20 5240MHz Ant3




Duty Cycle NVNT be40 5190MHz Ant3






Duty Cycle NVNT be40 5230MHz Ant3




Duty Cycle NVNT be80 5210MHz Ant3





Duty Cycle NVNT ac160 5250MHz Ant3





Duty Cycle NVNT ax160 5250MHz Ant3








Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5180	Ant4	94.65	0.24	0.91
NVNT	a	5200	Ant4	94.56	0.24	0.91
NVNT	a	5240	Ant4	94.56	0.24	0.91
NVNT	n20	5180	Ant4	97.29	0.12	0.44
NVNT	n20	5200	Ant4	97.29	0.12	0.44
NVNT	n20	5240	Ant4	97.29	0.12	0.44
NVNT	n40	5190	Ant4	94.71	0.24	0.9
NVNT	n40	5230	Ant4	94.71	0.24	0.9
NVNT	ac20	5180	Ant4	97.34	0.12	0.44
NVNT	ac20	5200	Ant4	97.3	0.12	0.44
NVNT	ac20	5240	Ant4	97.34	0.12	0.44
NVNT	ac40	5190	Ant4	94.72	0.24	0.9
NVNT	ac40	5230	Ant4	94.81	0.23	0.9
NVNT	ac80	5210	Ant4	89.82	0.47	1.86
NVNT	ax20	5180	Ant4	97.34	0.12	0.44
NVNT	ax20	5200	Ant4	97.3	0.12	0.44
NVNT	ax20	5240	Ant4	97.34	0.12	0.44
NVNT	ax40	5190	Ant4	94.72	0.24	0.9
NVNT	ax40	5230	Ant4	94.72	0.24	0.9
NVNT	ax80	5210	Ant4	89.65	0.47	1.86
NVNT	be20	5180	Ant4	97.34	0.12	0.44
NVNT	be20	5200	Ant4	97.3	0.12	0.44
NVNT	be20	5240	Ant4	97.34	0.12	0.44
NVNT	be40	5190	Ant4	94.72	0.24	0.9
NVNT	be40	5230	Ant4	94.72	0.24	0.9
NVNT	be80	5210	Ant4	89.65	0.47	1.86
NVNT	ac160	5250	Ant4	41.94	3.77	5.49
NVNT	ax160	5250	Ant4	41.8	3.79	5.52
NVNT	be160	5250	Ant4	41.8	3.79	5.52






Test Graphs

Duty Cycle NVNT a 5180MHz Ant4




Duty Cycle NVNT a 5200MHz Ant4






Duty Cycle NVNT a 5240MHz Ant4




Duty Cycle NVNT n20 5180MHz Ant4






Duty Cycle NVNT n20 5200MHz Ant4




Duty Cycle NVNT n20 5240MHz Ant4






Duty Cycle NVNT n40 5190MHz Ant4




Duty Cycle NVNT n40 5230MHz Ant4






Duty Cycle NVNT ac20 5180MHz Ant4




Duty Cycle NVNT ac20 5200MHz Ant4






Duty Cycle NVNT ac20 5240MHz Ant4



Duty Cycle NVNT ac40 5190MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac40 5230MHz Ant4




Duty Cycle NVNT ac80 5210MHz Ant4






Duty Cycle NVNT ax20 5180MHz Ant4



Duty Cycle NVNT ax20 5200MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax20 5240MHz Ant4




Duty Cycle NVNT ax40 5190MHz Ant4






Duty Cycle NVNT ax40 5230MHz Ant4



Duty Cycle NVNT ax80 5210MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT be20 5180MHz Ant4



Duty Cycle NVNT be20 5200MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT be20 5240MHz Ant4




Duty Cycle NVNT be40 5190MHz Ant4






Duty Cycle NVNT be40 5230MHz Ant4



Duty Cycle NVNT be80 5210MHz Ant4



Duty Cycle NVNT ac160 5250MHz Ant4




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Duty Cycle NVNT ax160 5250MHz Ant4








Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5180	Ant5	94.65	0.24	0.91
NVNT	a	5200	Ant5	94.65	0.24	0.91
NVNT	a	5240	Ant5	94.56	0.24	0.91
NVNT	n20	5180	Ant5	97.29	0.12	0.44
NVNT	n20	5200	Ant5	97.29	0.12	0.44
NVNT	n20	5240	Ant5	97.29	0.12	0.44
NVNT	n40	5190	Ant5	94.71	0.24	0.9
NVNT	n40	5230	Ant5	94.71	0.24	0.9
NVNT	ac20	5180	Ant5	97.34	0.12	0.44
NVNT	ac20	5200	Ant5	97.34	0.12	0.44
NVNT	ac20	5240	Ant5	97.34	0.12	0.44
NVNT	ac40	5190	Ant5	94.72	0.24	0.9
NVNT	ac40	5230	Ant5	94.81	0.23	0.9
NVNT	ac80	5210	Ant5	89.8	0.47	1.86
NVNT	ax20	5180	Ant5	97.34	0.12	0.44
NVNT	ax20	5200	Ant5	97.3	0.12	0.44
NVNT	ax20	5240	Ant5	97.3	0.12	0.44
NVNT	ax40	5190	Ant5	94.81	0.23	0.9
NVNT	ax40	5230	Ant5	94.72	0.24	0.9
NVNT	ax80	5210	Ant5	89.82	0.47	1.86
NVNT	be20	5180	Ant5	97.34	0.12	0.44
NVNT	be20	5200	Ant5	97.34	0.12	0.44
NVNT	be20	5240	Ant5	97.34	0.12	0.44
NVNT	be40	5190	Ant5	94.72	0.24	0.9
NVNT	be40	5230	Ant5	94.72	0.24	0.9
NVNT	be80	5210	Ant5	89.65	0.47	1.86
NVNT	ac160	5250	Ant5	42.03	3.76	5.49
NVNT	ax160	5250	Ant5	41.94	3.77	5.49
NVNT	be160	5250	Ant5	41.8	3.79	5.52






Test Graphs

Duty Cycle NVNT a 5180MHz Ant5



Duty Cycle NVNT a 5200MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT a 5240MHz Ant5




Duty Cycle NVNT n20 5180MHz Ant5






Duty Cycle NVNT n20 5200MHz Ant5




Duty Cycle NVNT n20 5240MHz Ant5






Duty Cycle NVNT n40 5190MHz Ant5




Duty Cycle NVNT n40 5230MHz Ant5






Duty Cycle NVNT ac20 5180MHz Ant5




Duty Cycle NVNT ac20 5200MHz Ant5






Duty Cycle NVNT ac20 5240MHz Ant5




Duty Cycle NVNT ac40 5190MHz Ant5






Duty Cycle NVNT ac40 5230MHz Ant5



Duty Cycle NVNT ac80 5210MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax20 5180MHz Ant5



Duty Cycle NVNT ax20 5200MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax20 5240MHz Ant5



Duty Cycle NVNT ax40 5190MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax40 5230MHz Ant5



Duty Cycle NVNT ax80 5210MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT be20 5180MHz Ant5



Duty Cycle NVNT be20 5200MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT be20 5240MHz Ant5




Duty Cycle NVNT be40 5190MHz Ant5






Duty Cycle NVNT be40 5230MHz Ant5




Duty Cycle NVNT be80 5210MHz Ant5



Duty Cycle NVNT ac160 5250MHz Ant5





Duty Cycle NVNT ax160 5250MHz Ant5

