





Restrict Band NVNT be80 5290MHz Ant4 Peak




Restrict Band NVNT be80 5290MHz Ant4 Average




Restrict Band NVNT ac160 5250MHz Ant4 Peak





Restrict Band NVNT ac160 5250MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac160 5250MHz Ant4 Peak



Restrict Band NVNT ac160 5250MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax160 5250MHz Ant4 Peak




Restrict Band NVNT ax160 5250MHz Ant4 Average






Restrict Band NVNT ax160 5250MHz Ant4 Peak




Restrict Band NVNT ax160 5250MHz Ant4 Average






Restrict Band NVNT be160 5250MHz Ant4 Peak



Restrict Band NVNT be160 5250MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be160 5250MHz Ant4 Peak



Restrict Band NVNT be160 5250MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5260	Ant5	4500	-50.43	4.28	-	49.08	Peak	68.2	Pass
NVNT	a	5260	Ant5	4500	-58.62	4.28	0.24	41.13	Average	54	Pass
NVNT	a	5260	Ant5	5093.58	-45.71	4.28	-	53.80	Peak	68.2	Pass
NVNT	a	5260	Ant5	5063.16	-56.61	4.28	0.24	43.14	Average	54	Pass
NVNT	a	5260	Ant5	5150	-49.58	4.28	-	49.93	Peak	68.2	Pass
NVNT	a	5260	Ant5	5150	-57.63	4.28	0.24	42.12	Average	54	Pass
NVNT	a	5320	Ant5	5350	-48.01	4.28	-	51.50	Peak	68.2	Pass
NVNT	a	5320	Ant5	5350	-56.25	4.28	0.24	43.50	Average	54	Pass
NVNT	a	5320	Ant5	5350.4	-44.19	4.28	-	55.32	Peak	68.2	Pass
NVNT	a	5320	Ant5	5351.6	-56.22	4.28	0.24	43.53	Average	54	Pass
NVNT	a	5320	Ant5	5460	-48.61	4.28	-	50.90	Peak	68.2	Pass
NVNT	a	5320	Ant5	5460	-57.35	4.28	0.24	42.40	Average	54	Pass
NVNT	n20	5260	Ant5	4500	-49.34	4.28	-	50.17	Peak	68.2	Pass
NVNT	n20	5260	Ant5	4500	-58.56	4.28	0.12	41.07	Average	54	Pass
NVNT	n20	5260	Ant5	5134.92	-46.25	4.28	-	53.26	Peak	68.2	Pass
NVNT	n20	5260	Ant5	5123.22	-56.52	4.28	0.12	43.11	Average	54	Pass
NVNT	n20	5260	Ant5	5150	-49.9	4.28	-	49.61	Peak	68.2	Pass
NVNT	n20	5260	Ant5	5150	-57.43	4.28	0.12	42.20	Average	54	Pass
NVNT	n20	5320	Ant5	5350	-46.26	4.28	-	53.25	Peak	68.2	Pass
NVNT	n20	5320	Ant5	5350	-55.37	4.28	0.12	44.26	Average	54	Pass
NVNT	n20	5320	Ant5	5352.2	-43.8	4.28	-	55.71	Peak	68.2	Pass
NVNT	n20	5320	Ant5	5350	-55.37	4.28	0.12	44.26	Average	54	Pass
NVNT	n20	5320	Ant5	5460	-48.45	4.28	-	51.06	Peak	68.2	Pass
NVNT	n20	5320	Ant5	5460	-57.8	4.28	0.12	41.83	Average	54	Pass
NVNT	n40	5270	Ant5	4500	-50.87	4.28	-	48.64	Peak	68.2	Pass
NVNT	n40	5270	Ant5	4500	-58.33	4.28	0.24	41.42	Average	54	Pass
NVNT	n40	5270	Ant5	5100.21	-45.65	4.28	-	53.86	Peak	68.2	Pass
NVNT	n40	5270	Ant5	5123.7	-56.49	4.28	0.24	43.26	Average	54	Pass
NVNT	n40	5270	Ant5	5150	-47.16	4.28	-	52.35	Peak	68.2	Pass
NVNT	n40	5270	Ant5	5150	-56.99	4.28	0.24	42.76	Average	54	Pass
NVNT	n40	5310	Ant5	5350	-43.6	4.28	-	55.91	Peak	68.2	Pass
NVNT	n40	5310	Ant5	5350	-55.71	4.28	0.24	44.04	Average	54	Pass
NVNT	n40	5310	Ant5	5351.4	-41.13	4.28	-	58.38	Peak	68.2	Pass
NVNT	n40	5310	Ant5	5350.4	-55.63	4.28	0.24	44.12	Average	54	Pass
NVNT	n40	5310	Ant5	5460	-48.95	4.28	-	50.56	Peak	68.2	Pass
NVNT	n40	5310	Ant5	5460	-57.42	4.28	0.24	42.33	Average	54	Pass
NVNT	ac20	5260	Ant5	4500	-50.34	4.28	-	49.17	Peak	68.2	Pass





NVNT	ac20	5260	Ant5	4500	-58.68	4.28	0.12	40.95	Average	54	Pass
NVNT	ac20	5260	Ant5	4990.62	-45.8	4.28	-	53.71	Peak	68.2	Pass
NVNT	ac20	5260	Ant5	5088.9	-56.3	4.28	0.12	43.33	Average	54	Pass
NVNT	ac20	5260	Ant5	5150	-47.15	4.28	-	52.36	Peak	68.2	Pass
NVNT	ac20	5260	Ant5	5150	-56.95	4.28	0.12	42.68	Average	54	Pass
NVNT	ac20	5320	Ant5	5350	-46.59	4.28	-	52.92	Peak	68.2	Pass
NVNT	ac20	5320	Ant5	5350	-55.89	4.28	0.12	43.74	Average	54	Pass
NVNT	ac20	5320	Ant5	5351.6	-43.52	4.28	-	55.99	Peak	68.2	Pass
NVNT	ac20	5320	Ant5	5350	-55.89	4.28	0.12	43.74	Average	54	Pass
NVNT	ac20	5320	Ant5	5460	-47.58	4.28	-	51.93	Peak	68.2	Pass
NVNT	ac20	5320	Ant5	5460	-57.32	4.28	0.12	42.31	Average	54	Pass
NVNT	ac40	5270	Ant5	4500	-50.62	4.28	-	48.89	Peak	68.2	Pass
NVNT	ac40	5270	Ant5	4500	-58.39	4.28	0.24	41.36	Average	54	Pass
NVNT	ac40	5270	Ant5	5088.87	-46.16	4.28	-	53.35	Peak	68.2	Pass
NVNT	ac40	5270	Ant5	5052.42	-56.5	4.28	0.24	43.25	Average	54	Pass
NVNT	ac40	5270	Ant5	5150	-49.98	4.28	-	49.53	Peak	68.2	Pass
NVNT	ac40	5270	Ant5	5150	-57.12	4.28	0.24	42.63	Average	54	Pass
NVNT	ac40	5310	Ant5	5350	-44.34	4.28	-	55.17	Peak	68.2	Pass
NVNT	ac40	5310	Ant5	5350	-55.6	4.28	0.24	44.15	Average	54	Pass
NVNT	ac40	5310	Ant5	5350.2	-44.05	4.28	-	55.46	Peak	68.2	Pass
NVNT	ac40	5310	Ant5	5350.8	-55.24	4.28	0.24	44.51	Average	54	Pass
NVNT	ac40	5310	Ant5	5460	-48.95	4.28	-	50.56	Peak	68.2	Pass
NVNT	ac40	5310	Ant5	5460	-57.9	4.28	0.24	41.85	Average	54	Pass
NVNT	ac80	5290	Ant5	4500	-48.59	4.28	-	50.92	Peak	68.2	Pass
NVNT	ac80	5290	Ant5	4500	-58.46	4.28	0.47	41.52	Average	54	Pass
NVNT	ac80	5290	Ant5	5145.54	-43.96	4.28	-	55.55	Peak	68.2	Pass
NVNT	ac80	5290	Ant5	5149.89	-54.67	4.28	0.47	45.31	Average	54	Pass
NVNT	ac80	5290	Ant5	5150	-47	4.28	-	52.51	Peak	68.2	Pass
NVNT	ac80	5290	Ant5	5150	-54.67	4.28	0.47	45.31	Average	54	Pass
NVNT	ac80	5290	Ant5	5350	-45.86	4.28	-	53.65	Peak	68.2	Pass
NVNT	ac80	5290	Ant5	5350	-56.04	4.28	0.47	43.94	Average	54	Pass
NVNT	ac80	5290	Ant5	5350.75	-44.03	4.28	-	55.48	Peak	68.2	Pass
NVNT	ac80	5290	Ant5	5350.5	-55.58	4.28	0.47	44.40	Average	54	Pass
NVNT	ac80	5290	Ant5	5460	-50.5	4.28	-	49.01	Peak	68.2	Pass
NVNT	ac80	5290	Ant5	5460	-57.96	4.28	0.47	42.02	Average	54	Pass
NVNT	ax20	5260	Ant5	4500	-50.07	4.28	-	49.44	Peak	68.2	Pass
NVNT	ax20	5260	Ant5	4500	-58.61	4.28	0.12	41.02	Average	54	Pass
NVNT	ax20	5260	Ant5	5098.26	-46.2	4.28	-	53.31	Peak	68.2	Pass
NVNT	ax20	5260	Ant5	5066.28	-56.52	4.28	0.12	43.11	Average	54	Pass
NVNT	ax20	5260	Ant5	5150	-49.3	4.28	-	50.21	Peak	68.2	Pass
NVNT	ax20	5260	Ant5	5150	-57.48	4.28	0.12	42.15	Average	54	Pass





NVNT	ax20	5320	Ant5	5350	-43.31	4.28	-	56.20	Peak	68.2	Pass
NVNT	ax20	5320	Ant5	5350	-55.18	4.28	0.12	44.45	Average	54	Pass
NVNT	ax20	5320	Ant5	5351.6	-40.26	4.28	-	59.25	Peak	68.2	Pass
NVNT	ax20	5320	Ant5	5350	-55.18	4.28	0.12	44.45	Average	54	Pass
NVNT	ax20	5320	Ant5	5460	-49.07	4.28	-	50.44	Peak	68.2	Pass
NVNT	ax20	5320	Ant5	5460	-57.69	4.28	0.12	41.94	Average	54	Pass
NVNT	ax40	5270	Ant5	4500	-50.71	4.28	-	48.80	Peak	68.2	Pass
NVNT	ax40	5270	Ant5	4500	-58.78	4.28	0.24	40.97	Average	54	Pass
NVNT	ax40	5270	Ant5	4948.74	-46.04	4.28	-	53.47	Peak	68.2	Pass
NVNT	ax40	5270	Ant5	4777.02	-56.46	4.28	0.24	43.29	Average	54	Pass
NVNT	ax40	5270	Ant5	5150	-48.76	4.28	-	50.75	Peak	68.2	Pass
NVNT	ax40	5270	Ant5	5150	-56.88	4.28	0.24	42.87	Average	54	Pass
NVNT	ax40	5310	Ant5	5350	-46.75	4.28	-	52.76	Peak	68.2	Pass
NVNT	ax40	5310	Ant5	5350	-55.6	4.28	0.24	44.15	Average	54	Pass
NVNT	ax40	5310	Ant5	5352.2	-42.46	4.28	-	57.05	Peak	68.2	Pass
NVNT	ax40	5310	Ant5	5350.6	-55.49	4.28	0.24	44.26	Average	54	Pass
NVNT	ax40	5310	Ant5	5460	-50.18	4.28	-	49.33	Peak	68.2	Pass
NVNT	ax40	5310	Ant5	5460	-57.71	4.28	0.24	42.04	Average	54	Pass
NVNT	ax80	5290	Ant5	5350	-43.19	4.28	-	56.32	Peak	68.2	Pass
NVNT	ax80	5290	Ant5	5350	-55.68	4.28	0.47	44.30	Average	54	Pass
NVNT	ax80	5290	Ant5	5352.25	-42.57	4.28	-	56.94	Peak	68.2	Pass
NVNT	ax80	5290	Ant5	5350.75	-55.09	4.28	0.47	44.89	Average	54	Pass
NVNT	ax80	5290	Ant5	5460	-50.83	4.28	-	48.68	Peak	68.2	Pass
NVNT	ax80	5290	Ant5	5460	-57.69	4.28	0.47	42.29	Average	54	Pass
NVNT	ax80	5290	Ant5	4500	-49.47	4.28	-	50.04	Peak	68.2	Pass
NVNT	ax80	5290	Ant5	4500	-58.61	4.28	0.47	41.37	Average	54	Pass
NVNT	ax80	5290	Ant5	5145.54	-44.34	4.28	-	55.17	Peak	68.2	Pass
NVNT	ax80	5290	Ant5	5149.89	-54.82	4.28	0.47	45.16	Average	54	Pass
NVNT	ax80	5290	Ant5	5150	-46.79	4.28	-	52.72	Peak	68.2	Pass
NVNT	ax80	5290	Ant5	5150	-54.82	4.28	0.47	45.16	Average	54	Pass
NVNT	be20	5260	Ant5	4500	-48.63	4.28	-	50.88	Peak	68.2	Pass
NVNT	be20	5260	Ant5	4500	-58.6	4.28	0.12	41.03	Average	54	Pass
NVNT	be20	5260	Ant5	5099.04	-46.22	4.28	-	53.29	Peak	68.2	Pass
NVNT	be20	5260	Ant5	5061.6	-56.58	4.28	0.12	43.05	Average	54	Pass
NVNT	be20	5260	Ant5	5150	-49.24	4.28	-	50.27	Peak	68.2	Pass
NVNT	be20	5260	Ant5	5150	-57.39	4.28	0.12	42.24	Average	54	Pass
NVNT	be20	5320	Ant5	5350	-46.36	4.28	-	53.15	Peak	68.2	Pass
NVNT	be20	5320	Ant5	5350	-55.91	4.28	0.12	43.72	Average	54	Pass
NVNT	be20	5320	Ant5	5350.8	-44.06	4.28	-	55.45	Peak	68.2	Pass
NVNT	be20	5320	Ant5	5350	-55.91	4.28	0.12	43.72	Average	54	Pass
NVNT	be20	5320	Ant5	5460	-49.41	4.28	-	50.10	Peak	68.2	Pass





NVNT	be20	5320	Ant5	5460	-57.74	4.28	0.12	41.89	Average	54	Pass
NVNT	be40	5270	Ant5	4500	-48.66	4.28	-	50.85	Peak	68.2	Pass
NVNT	be40	5270	Ant5	4500	-58.59	4.28	0.24	41.16	Average	54	Pass
NVNT	be40	5270	Ant5	5109.12	-46.08	4.28	-	53.43	Peak	68.2	Pass
NVNT	be40	5270	Ant5	4806.18	-56.35	4.28	0.24	43.40	Average	54	Pass
NVNT	be40	5270	Ant5	5150	-47.52	4.28	-	51.99	Peak	68.2	Pass
NVNT	be40	5270	Ant5	5150	-57.69	4.28	0.24	42.06	Average	54	Pass
NVNT	be40	5310	Ant5	5350	-42.78	4.28	-	56.73	Peak	68.2	Pass
NVNT	be40	5310	Ant5	5350	-55.9	4.28	0.24	43.85	Average	54	Pass
NVNT	be40	5310	Ant5	5350	-42.78	4.28	-	56.73	Peak	68.2	Pass
NVNT	be40	5310	Ant5	5350.4	-55.41	4.28	0.24	44.34	Average	54	Pass
NVNT	be40	5310	Ant5	5460	-49.43	4.28	-	50.08	Peak	68.2	Pass
NVNT	be40	5310	Ant5	5460	-57.47	4.28	0.24	42.28	Average	54	Pass
NVNT	be80	5290	Ant5	5350	-41.92	4.28	-	57.59	Peak	68.2	Pass
NVNT	be80	5290	Ant5	5350	-55.21	4.28	0.47	44.77	Average	54	Pass
NVNT	be80	5290	Ant5	5350	-41.92	4.28	-	57.59	Peak	68.2	Pass
NVNT	be80	5290	Ant5	5350	-55.21	4.28	0.47	44.77	Average	54	Pass
NVNT	be80	5290	Ant5	5460	-50.18	4.28	-	49.33	Peak	68.2	Pass
NVNT	be80	5290	Ant5	5460	-57.68	4.28	0.47	42.30	Average	54	Pass
NVNT	be80	5290	Ant5	4500	-51.29	4.28	-	48.22	Peak	68.2	Pass
NVNT	be80	5290	Ant5	4500	-58.31	4.28	0.47	41.67	Average	54	Pass
NVNT	be80	5290	Ant5	5143.8	-44.59	4.28	-	54.92	Peak	68.2	Pass
NVNT	be80	5290	Ant5	5149.89	-54.45	4.28	0.47	45.53	Average	54	Pass
NVNT	be80	5290	Ant5	5150	-46.08	4.28	-	53.43	Peak	68.2	Pass
NVNT	be80	5290	Ant5	5150	-54.45	4.28	0.47	45.53	Average	54	Pass
NVNT	ac160	5250	Ant5	5350	-43.29	4.28	-	56.22	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5350	-64.39	4.28	3.76	38.88	Average	54	Pass
NVNT	ac160	5250	Ant5	5350.11	-43.29	4.28	-	56.22	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5401.91	-61.45	4.28	3.76	41.82	Average	54	Pass
NVNT	ac160	5250	Ant5	5460	-59.27	4.28	-	40.24	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5460	-67.42	4.28	3.76	35.85	Average	54	Pass
NVNT	ac160	5250	Ant5	4500	-60.2	4.28	-	39.31	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	4500	-68.18	4.28	3.76	35.09	Average	54	Pass
NVNT	ac160	5250	Ant5	5119.71	-51.51	4.28	-	48.00	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5145.19	-63.72	4.28	3.76	39.55	Average	54	Pass
NVNT	ac160	5250	Ant5	5150	-54.08	4.28	-	45.43	Peak	68.2	Pass
NVNT	ac160	5250	Ant5	5150	-64.1	4.28	3.76	39.17	Average	54	Pass
NVNT	ax160	5250	Ant5	5350	-44.1	4.28	-	55.41	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	5350	-64.56	4.28	3.77	38.72	Average	54	Pass
NVNT	ax160	5250	Ant5	5350.11	-44.1	4.28	-	55.41	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	5359.36	-61.46	4.28	3.77	41.82	Average	54	Pass






NVNT	ax160	5250	Ant5	5460	-58.67	4.28	-	40.84	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	5460	-67.7	4.28	3.77	35.58	Average	54	Pass
NVNT	ax160	5250	Ant5	4500	-60.69	4.28	-	38.82	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	4500	-68.59	4.28	3.77	34.69	Average	54	Pass
NVNT	ax160	5250	Ant5	5122.44	-50.37	4.28	-	49.14	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	5138.82	-63.28	4.28	3.77	40.00	Average	54	Pass
NVNT	ax160	5250	Ant5	5150	-50.89	4.28	-	48.62	Peak	68.2	Pass
NVNT	ax160	5250	Ant5	5150	-63.58	4.28	3.77	39.70	Average	54	Pass
NVNT	be160	5250	Ant5	5350	-44.76	4.28	-	54.75	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5350	-57.74	4.28	3.79	45.56	Average	54	Pass
NVNT	be160	5250	Ant5	5364.17	-43.03	4.28	-	56.48	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5408.2	-56.61	4.28	3.79	46.69	Average	54	Pass
NVNT	be160	5250	Ant5	5460	-48.67	4.28	-	50.84	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5460	-57.65	4.28	3.79	45.65	Average	54	Pass
NVNT	be160	5250	Ant5	4500	-50.79	4.28	-	48.72	Peak	68.2	Pass
NVNT	be160	5250	Ant5	4500	-58.57	4.28	3.79	44.73	Average	54	Pass
NVNT	be160	5250	Ant5	5147.01	-46.1	4.28	-	53.41	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5123.35	-56.47	4.28	3.79	46.83	Average	54	Pass
NVNT	be160	5250	Ant5	5150	-48.27	4.28	-	51.24	Peak	68.2	Pass
NVNT	be160	5250	Ant5	5150	-57.53	4.28	3.79	45.77	Average	54	Pass






Test Graphs

Restrict Band NVNT a 5260MHz Ant5 Peak



Restrict Band NVNT a 5260MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5320MHz Ant5 Peak



Restrict Band NVNT a 5320MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5260MHz Ant5 Peak



Restrict Band NVNT n20 5260MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5320MHz Ant5 Peak




Restrict Band NVNT n20 5320MHz Ant5 Average






Restrict Band NVNT n40 5270MHz Ant5 Peak



Restrict Band NVNT n40 5270MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5310MHz Ant5 Peak



Restrict Band NVNT n40 5310MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5260MHz Ant5 Peak



Restrict Band NVNT ac20 5260MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5320MHz Ant5 Peak



Restrict Band NVNT ac20 5320MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5270MHz Ant5 Peak



Restrict Band NVNT ac40 5270MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5310MHz Ant5 Peak




Restrict Band NVNT ac40 5310MHz Ant5 Average






Restrict Band NVNT ac80 5290MHz Ant5 Peak



Restrict Band NVNT ac80 5290MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant5 Peak




Restrict Band NVNT ac80 5290MHz Ant5 Average






Restrict Band NVNT ax20 5260MHz Ant5 Peak



Restrict Band NVNT ax20 5260MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5320MHz Ant5 Peak



Restrict Band NVNT ax20 5320MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5270MHz Ant5 Peak



Restrict Band NVNT ax40 5270MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5310MHz Ant5 Peak



Restrict Band NVNT ax40 5310MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant5 Peak




Restrict Band NVNT ax80 5290MHz Ant5 Average






Restrict Band NVNT ax80 5290MHz Ant5 Peak



Restrict Band NVNT ax80 5290MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be20 5260MHz Ant5 Peak



Restrict Band NVNT be20 5260MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be20 5320MHz Ant5 Peak



Restrict Band NVNT be20 5320MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be40 5270MHz Ant5 Peak



Restrict Band NVNT be40 5270MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be40 5310MHz Ant5 Peak




Restrict Band NVNT be40 5310MHz Ant5 Average






Restrict Band NVNT be80 5290MHz Ant5 Peak




Restrict Band NVNT be80 5290MHz Ant5 Average






Restrict Band NVNT be80 5290MHz Ant5 Peak



Restrict Band NVNT be80 5290MHz Ant5 Average



Restrict Band NVNT ac160 5250MHz Ant5 Peak




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT ac160 5250MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac160 5250MHz Ant5 Peak



Restrict Band NVNT ac160 5250MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax160 5250MHz Ant5 Peak



Restrict Band NVNT ax160 5250MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax160 5250MHz Ant5 Peak



Restrict Band NVNT ax160 5250MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be160 5250MHz Ant5 Peak



Restrict Band NVNT be160 5250MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be160 5250MHz Ant5 Peak



Restrict Band NVNT be160 5250MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



MIMO

Condition	Mode	Frequency (MHz)	Ant3 Power (dBm)	Ant4 Power (dBm)	Ant5 Power (dBm)	Gain (dBi)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	n20	5260	-51.6	-50.7	-49.34	9.05	58.60	Peak	68.2	Pass
NVNT	n20	5260	-58.39	-58.66	-58.56	9.05	50.51	Average	54	Pass
NVNT	n20	5260	-47.09	-46.22	-46.25	9.05	62.55	Peak	68.2	Pass
NVNT	n20	5260	-56.64	-56.57	-56.52	9.05	52.47	Average	54	Pass
NVNT	n20	5260	-47.74	-47.55	-49.9	9.05	60.77	Peak	68.2	Pass
NVNT	n20	5260	-57.26	-57.22	-57.43	9.05	51.75	Average	54	Pass
NVNT	n20	5320	-45.87	-45.69	-46.26	9.05	63.12	Peak	68.2	Pass
NVNT	n20	5320	-55.81	-56.06	-55.37	9.05	53.31	Average	54	Pass
NVNT	n20	5320	-43.52	-43.85	-43.8	9.05	65.33	Peak	68.2	Pass
NVNT	n20	5320	-55.42	-55.91	-55.37	9.05	53.49	Average	54	Pass
NVNT	n20	5320	-49.14	-49.81	-48.45	9.05	59.95	Peak	68.2	Pass
NVNT	n20	5320	-57.77	-58.05	-57.8	9.05	51.18	Average	54	Pass
NVNT	n40	5270	-50.03	-49.53	-50.87	9.05	58.94	Peak	68.2	Pass
NVNT	n40	5270	-58.08	-58.27	-58.33	9.05	50.82	Average	54	Pass
NVNT	n40	5270	-46.34	-46.16	-45.65	9.05	63.01	Peak	68.2	Pass
NVNT	n40	5270	-56.58	-56.5	-56.49	9.05	52.53	Average	54	Pass
NVNT	n40	5270	-48.19	-48.53	-47.16	9.05	61.13	Peak	68.2	Pass
NVNT	n40	5270	-57.09	-57.34	-56.99	9.05	51.91	Average	54	Pass
NVNT	n40	5310	-45.61	-44.31	-43.6	9.05	64.62	Peak	68.2	Pass
NVNT	n40	5310	-55.02	-55.24	-55.71	9.05	53.73	Average	54	Pass
NVNT	n40	5310	-42.34	-43.57	-41.13	9.05	66.82	Peak	68.2	Pass
NVNT	n40	5310	-55.02	-55.24	-55.63	9.05	53.76	Average	54	Pass
NVNT	n40	5310	-48.35	-48.88	-48.95	9.05	60.33	Peak	68.2	Pass
NVNT	n40	5310	-57.89	-57.4	-57.42	9.05	51.48	Average	54	Pass
NVNT	ac20	5260	-49.66	-51.53	-50.34	9.05	58.61	Peak	68.2	Pass
NVNT	ac20	5260	-58.84	-58.44	-58.68	9.05	50.40	Average	54	Pass
NVNT	ac20	5260	-46.18	-46.34	-45.8	9.05	62.95	Peak	68.2	Pass
NVNT	ac20	5260	-56.48	-56.61	-56.3	9.05	52.59	Average	54	Pass
NVNT	ac20	5260	-49.18	-49.12	-47.15	9.05	60.67	Peak	68.2	Pass
NVNT	ac20	5260	-57.2	-57.29	-56.95	9.05	51.90	Average	54	Pass
NVNT	ac20	5320	-44.48	-47.09	-46.59	9.05	63.15	Peak	68.2	Pass
NVNT	ac20	5320	-54.74	-54.84	-55.89	9.05	53.92	Average	54	Pass
NVNT	ac20	5320	-42.47	-41.56	-43.52	9.05	66.61	Peak	68.2	Pass
NVNT	ac20	5320	-54.74	-54.64	-55.89	9.05	53.99	Average	54	Pass
NVNT	ac20	5320	-49.85	-49.57	-47.58	9.05	60.17	Peak	68.2	Pass
NVNT	ac20	5320	-57.94	-57.47	-57.32	9.05	51.48	Average	54	Pass
NVNT	ac40	5270	-49.5	-49.57	-50.62	9.05	59.18	Peak	68.2	Pass
NVNT	ac40	5270	-58.88	-58.81	-58.39	9.05	50.36	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac40	5270	-46.4	-46.96	-46.16	9.05	62.55	Peak	68.2	Pass
NVNT	ac40	5270	-56.46	-56.44	-56.5	9.05	52.58	Average	54	Pass
NVNT	ac40	5270	-49.59	-49.25	-49.98	9.05	59.45	Peak	68.2	Pass
NVNT	ac40	5270	-57.28	-57.35	-57.12	9.05	51.80	Average	54	Pass
NVNT	ac40	5310	-46.07	-46.63	-44.34	9.05	63.48	Peak	68.2	Pass
NVNT	ac40	5310	-55.61	-56.36	-55.6	9.05	53.21	Average	54	Pass
NVNT	ac40	5310	-42.56	-42.44	-44.05	9.05	66.09	Peak	68.2	Pass
NVNT	ac40	5310	-55.61	-55.23	-55.24	9.05	53.69	Average	54	Pass
NVNT	ac40	5310	-50.65	-49.5	-48.95	9.05	59.41	Peak	68.2	Pass
NVNT	ac40	5310	-57.38	-57.56	-57.9	9.05	51.44	Average	54	Pass
NVNT	ac80	5290	-50.44	-51.23	-48.59	9.05	59.11	Peak	68.2	Pass
NVNT	ac80	5290	-58.72	-58.78	-58.46	9.05	50.40	Average	54	Pass
NVNT	ac80	5290	-44.24	-44.4	-43.96	9.05	64.85	Peak	68.2	Pass
NVNT	ac80	5290	-54.8	-55.65	-54.79	9.05	53.99	Average	54	Pass
NVNT	ac80	5290	-47.05	-47.13	-47	9.05	61.99	Peak	68.2	Pass
NVNT	ac80	5290	-54.83	-55.73	-54.69	9.05	53.99	Average	54	Pass
NVNT	ac80	5290	-46.68	-46.17	-45.86	9.05	62.83	Peak	68.2	Pass
NVNT	ac80	5290	-55.84	-56.4	-56.04	9.05	52.96	Average	54	Pass
NVNT	ac80	5290	-43.4	-41.14	-44.03	9.05	66.38	Peak	68.2	Pass
NVNT	ac80	5290	-55.53	-55.55	-55.58	9.05	53.50	Average	54	Pass
NVNT	ac80	5290	-49.89	-49.59	-50.5	9.05	59.07	Peak	68.2	Pass
NVNT	ac80	5290	-57.37	-58.17	-57.96	9.05	51.23	Average	54	Pass
NVNT	ax20	5260	-50	-51.09	-50.07	9.05	58.69	Peak	68.2	Pass
NVNT	ax20	5260	-58.61	-59	-58.61	9.05	50.31	Average	54	Pass
NVNT	ax20	5260	-46.31	-45.64	-46.2	9.05	63.01	Peak	68.2	Pass
NVNT	ax20	5260	-56.46	-56.57	-56.52	9.05	52.53	Average	54	Pass
NVNT	ax20	5260	-48.19	-47.63	-49.3	9.05	60.73	Peak	68.2	Pass
NVNT	ax20	5260	-57.05	-56.84	-57.48	9.05	51.93	Average	54	Pass
NVNT	ax20	5320	-47.61	-43.19	-43.31	9.05	64.77	Peak	68.2	Pass
NVNT	ax20	5320	-55.79	-55.52	-55.18	9.05	53.56	Average	54	Pass
NVNT	ax20	5320	-40.93	-41.12	-41.26	9.05	67.95	Peak	68.2	Pass
NVNT	ax20	5320	-55.1	-55.34	-55.18	9.05	53.84	Average	54	Pass
NVNT	ax20	5320	-49.15	-48.39	-49.07	9.05	60.19	Peak	68.2	Pass
NVNT	ax20	5320	-57.16	-57.43	-57.69	9.05	51.63	Average	54	Pass
NVNT	ax40	5270	-50.41	-49.51	-50.71	9.05	58.87	Peak	68.2	Pass
NVNT	ax40	5270	-58.44	-58.5	-58.78	9.05	50.48	Average	54	Pass
NVNT	ax40	5270	-45.89	-46.03	-46.04	9.05	63.06	Peak	68.2	Pass
NVNT	ax40	5270	-56.3	-56.3	-56.46	9.05	52.70	Average	54	Pass
NVNT	ax40	5270	-48.33	-49.08	-48.76	9.05	60.34	Peak	68.2	Pass
NVNT	ax40	5270	-56.9	-56.93	-56.88	9.05	52.15	Average	54	Pass
NVNT	ax40	5310	-45.43	-43.44	-46.75	9.05	64.06	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ax40	5310	-55.8	-55.46	-55.6	9.05	53.43	Average	54	Pass
NVNT	ax40	5310	-43.04	-43.44	-42.46	9.05	66.09	Peak	68.2	Pass
NVNT	ax40	5310	-55.8	-54.48	-55.49	9.05	53.83	Average	54	Pass
NVNT	ax40	5310	-50	-48.92	-50.18	9.05	59.39	Peak	68.2	Pass
NVNT	ax40	5310	-57.19	-57.83	-57.71	9.05	51.48	Average	54	Pass
NVNT	ax80	5290	-46.75	-43.43	-43.19	9.05	64.87	Peak	68.2	Pass
NVNT	ax80	5290	-56.04	-55.42	-55.68	9.05	53.34	Average	54	Pass
NVNT	ax80	5290	-44.47	-42.82	-42.57	9.05	65.84	Peak	68.2	Pass
NVNT	ax80	5290	-55.71	-55.21	-55.09	9.05	53.72	Average	54	Pass
NVNT	ax80	5290	-49.33	-49.43	-50.83	9.05	59.24	Peak	68.2	Pass
NVNT	ax80	5290	-57.32	-58.13	-57.69	9.05	51.35	Average	54	Pass
NVNT	ax80	5290	-49.45	-50.9	-49.47	9.05	59.16	Peak	68.2	Pass
NVNT	ax80	5290	-58.77	-58.83	-58.61	9.05	50.31	Average	54	Pass
NVNT	ax80	5290	-44.81	-45.25	-44.34	9.05	64.26	Peak	68.2	Pass
NVNT	ax80	5290	-54.53	-55.73	-55.84	9.05	53.72	Average	54	Pass
NVNT	ax80	5290	-47.17	-46.6	-46.79	9.05	62.20	Peak	68.2	Pass
NVNT	ax80	5290	-55.3	-54.6	-55.82	9.05	53.84	Average	54	Pass
NVNT	be20	5260	-50.31	-49.04	-48.63	9.05	59.78	Peak	68.2	Pass
NVNT	be20	5260	-58.52	-59.26	-58.6	9.05	50.27	Average	54	Pass
NVNT	be20	5260	-46.56	-46.38	-46.22	9.05	62.66	Peak	68.2	Pass
NVNT	be20	5260	-56.62	-56.48	-56.58	9.05	52.49	Average	54	Pass
NVNT	be20	5260	-47.06	-48.6	-49.24	9.05	60.85	Peak	68.2	Pass
NVNT	be20	5260	-57.77	-57.15	-57.39	9.05	51.62	Average	54	Pass
NVNT	be20	5320	-43.36	-47.78	-46.36	9.05	63.62	Peak	68.2	Pass
NVNT	be20	5320	-55.96	-55.88	-55.91	9.05	53.13	Average	54	Pass
NVNT	be20	5320	-42.25	-41.62	-44.06	9.05	66.52	Peak	68.2	Pass
NVNT	be20	5320	-55.5	-55.86	-55.91	9.05	53.30	Average	54	Pass
NVNT	be20	5320	-50.88	-49.33	-49.41	9.05	59.23	Peak	68.2	Pass
NVNT	be20	5320	-57.9	-57.9	-57.74	9.05	51.20	Average	54	Pass
NVNT	be40	5270	-51.32	-51.18	-48.66	9.05	58.84	Peak	68.2	Pass
NVNT	be40	5270	-58.36	-58.24	-58.59	9.05	50.65	Average	54	Pass
NVNT	be40	5270	-46.93	-45.55	-46.08	9.05	62.90	Peak	68.2	Pass
NVNT	be40	5270	-56.6	-56.5	-56.35	9.05	52.57	Average	54	Pass
NVNT	be40	5270	-49.56	-48.82	-47.52	9.05	60.50	Peak	68.2	Pass
NVNT	be40	5270	-57.44	-57.3	-57.69	9.05	51.58	Average	54	Pass
NVNT	be40	5310	-44.97	-43.24	-42.78	9.05	65.48	Peak	68.2	Pass
NVNT	be40	5310	-56.45	-55.77	-55.9	9.05	53.02	Average	54	Pass
NVNT	be40	5310	-43.41	-42.2	-42.78	9.05	66.28	Peak	68.2	Pass
NVNT	be40	5310	-55.56	-54.79	-55.41	9.05	53.81	Average	54	Pass
NVNT	be40	5310	-48.49	-48.83	-49.43	9.05	60.15	Peak	68.2	Pass
NVNT	be40	5310	-57.85	-57.78	-57.47	9.05	51.35	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	be80	5290	-47.17	-48.71	-41.92	9.05	64.14	Peak	68.2	Pass
NVNT	be80	5290	-55.92	-55.78	-55.21	9.05	53.42	Average	54	Pass
NVNT	be80	5290	-44.26	-44.66	-41.92	9.05	65.61	Peak	68.2	Pass
NVNT	be80	5290	-55.3	-55.56	-55.21	9.05	53.69	Average	54	Pass
NVNT	be80	5290	-48.54	-50.48	-50.18	9.05	59.40	Peak	68.2	Pass
NVNT	be80	5290	-57.58	-57.66	-57.68	9.05	51.41	Average	54	Pass
NVNT	be80	5290	-50.88	-50.15	-51.29	9.05	58.30	Peak	68.2	Pass
NVNT	be80	5290	-58.54	-58.22	-58.31	9.05	50.69	Average	54	Pass
NVNT	be80	5290	-45.24	-44.65	-44.59	9.05	64.23	Peak	68.2	Pass
NVNT	be80	5290	-54.87	-55.77	-54.89	9.05	53.89	Average	54	Pass
NVNT	be80	5290	-47.68	-46.79	-46.08	9.05	62.25	Peak	68.2	Pass
NVNT	be80	5290	-54.57	-55.72	-55.45	9.05	53.83	Average	54	Pass
NVNT	ac160	5250	-55.63	-53.94	-43.29	9.05	61.57	Peak	68.2	Pass
NVNT	ac160	5250	-63.8	-64.43	-64.39	9.05	44.85	Average	54	Pass
NVNT	ac160	5250	-45.11	-43.97	-43.29	9.05	64.99	Peak	68.2	Pass
NVNT	ac160	5250	-62.28	-62.24	-61.45	9.05	47.08	Average	54	Pass
NVNT	ac160	5250	-59.59	-56.8	-59.27	9.05	50.68	Peak	68.2	Pass
NVNT	ac160	5250	-67.38	-66.73	-67.42	9.05	41.88	Average	54	Pass
NVNT	ac160	5250	-60.19	-60.46	-60.2	9.05	48.77	Peak	68.2	Pass
NVNT	ac160	5250	-68.47	-68.79	-68.18	9.05	40.58	Average	54	Pass
NVNT	ac160	5250	-44.5	-47.44	-51.51	9.05	62.10	Peak	68.2	Pass
NVNT	ac160	5250	-58.98	-63.33	-63.72	9.05	47.61	Average	54	Pass
NVNT	ac160	5250	-47.62	-54.26	-54.08	9.05	58.25	Peak	68.2	Pass
NVNT	ac160	5250	-60.31	-64.03	-64.1	9.05	46.62	Average	54	Pass
NVNT	ax160	5250	-52.17	-53.28	-44.1	9.05	61.24	Peak	68.2	Pass
NVNT	ax160	5250	-64.31	-64.51	-64.56	9.05	44.59	Average	54	Pass
NVNT	ax160	5250	-44.31	-43.68	-44.1	9.05	65.03	Peak	68.2	Pass
NVNT	ax160	5250	-60.73	-60.97	-61.46	9.05	48.01	Average	54	Pass
NVNT	ax160	5250	-56.23	-58.27	-58.67	9.05	51.46	Peak	68.2	Pass
NVNT	ax160	5250	-67.03	-67.14	-67.7	9.05	41.77	Average	54	Pass
NVNT	ax160	5250	-59.42	-60.14	-60.69	9.05	49.00	Peak	68.2	Pass
NVNT	ax160	5250	-67.9	-68.82	-68.59	9.05	40.63	Average	54	Pass
NVNT	ax160	5250	-44.79	-49.97	-50.37	9.05	61.47	Peak	68.2	Pass
NVNT	ax160	5250	-58.02	-61.63	-63.28	9.05	48.65	Average	54	Pass
NVNT	ax160	5250	-49.55	-53.45	-50.89	9.05	58.04	Peak	68.2	Pass
NVNT	ax160	5250	-60.08	-62.24	-63.58	9.05	47.33	Average	54	Pass
NVNT	be160	5250	-42.49	-49.96	-44.76	9.05	64.27	Peak	68.2	Pass
NVNT	be160	5250	-57.73	-57.72	-57.74	9.05	51.32	Average	54	Pass
NVNT	be160	5250	-42.49	-43.64	-43.03	9.05	66.02	Peak	68.2	Pass
NVNT	be160	5250	-56.46	-56.09	-56.61	9.05	52.67	Average	54	Pass
NVNT	be160	5250	-49.12	-49.92	-48.67	9.05	59.84	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	be160	5250	-57.75	-57.83	-57.65	9.05	51.31	Average	54	Pass
NVNT	be160	5250	-50.15	-50.25	-50.79	9.05	58.66	Peak	68.2	Pass
NVNT	be160	5250	-58.8	-58.6	-58.57	9.05	50.39	Average	54	Pass
NVNT	be160	5250	-44.57	-46.03	-46.1	9.05	63.54	Peak	68.2	Pass
NVNT	be160	5250	-55.42	-56.31	-56.47	9.05	53.01	Average	54	Pass
NVNT	be160	5250	-47.15	-48.57	-48.27	9.05	61.10	Peak	68.2	Pass
NVNT	be160	5250	-55.94	-57.2	-57.53	9.05	52.21	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.
Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China
Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com
Scan code to check authenticity



C.5 Frequency Stability


Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	a	5260	Ant3	5259.98	-20000	-3.8	25	Pass
NVNT	a	5300	Ant3	5299.98	-20000	-3.77	25	Pass
NVNT	a	5320	Ant3	5319.98	-20000	-3.76	25	Pass
NVNT	n20	5260	Ant3	5259.98	-20000	-3.8	25	Pass
NVNT	n20	5300	Ant3	5299.98	-20000	-3.77	25	Pass
NVNT	n20	5320	Ant3	5319.98	-20000	-3.76	25	Pass
NVNT	n40	5270	Ant3	5270	0	0	25	Pass
NVNT	n40	5310	Ant3	5309.96	-40000	-7.53	25	Pass
NVNT	ac20	5260	Ant3	5259.98	-20000	-3.8	25	Pass
NVNT	ac20	5300	Ant3	5299.98	-20000	-3.77	25	Pass
NVNT	ac20	5320	Ant3	5319.98	-20000	-3.76	25	Pass
NVNT	ac40	5270	Ant3	5270	0	0	25	Pass
NVNT	ac40	5310	Ant3	5310	0	0	25	Pass
NVNT	ac80	5290	Ant3	5290	0	0	25	Pass
NVNT	ax20	5260	Ant3	5259.98	-20000	-3.8	25	Pass
NVNT	ax20	5300	Ant3	5299.98	-20000	-3.77	25	Pass
NVNT	ax20	5320	Ant3	5319.96	-40000	-7.52	25	Pass
NVNT	ax40	5270	Ant3	5270	0	0	25	Pass
NVNT	ax40	5310	Ant3	5310	0	0	25	Pass
NVNT	ax80	5290	Ant3	5290	0	0	25	Pass
NVNT	be20	5260	Ant3	5259.98	-20000	-3.8	25	Pass
NVNT	be20	5300	Ant3	5299.98	-20000	-3.77	25	Pass
NVNT	be20	5320	Ant3	5320	0	0	25	Pass
NVNT	be40	5270	Ant3	5269.96	-40000	-7.59	25	Pass
NVNT	be40	5310	Ant3	5310	0	0	25	Pass
NVNT	be80	5290	Ant3	5290	0	0	25	Pass
NVNT	ac160	5250	Ant3	5250	0	0	25	Pass
NVNT	ax160	5250	Ant3	5250	0	0	25	Pass
NVNT	be160	5250	Ant3	5250	0	0	25	Pass






Test Graphs

Freq. Stability NVNT a 5260MHz Ant3




Freq. Stability NVNT a 5300MHz Ant3






Freq. Stability NVNT a 5320MHz Ant3




Freq. Stability NVNT n20 5260MHz Ant3






Freq. Stability NVNT n20 5300MHz Ant3




Freq. Stability NVNT n20 5320MHz Ant3






Freq. Stability NVNT n40 5270MHz Ant3



Freq. Stability NVNT n40 5310MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5260MHz Ant3



Freq. Stability NVNT ac20 5300MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5320MHz Ant3



Freq. Stability NVNT ac40 5270MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac40 5310MHz Ant3



Freq. Stability NVNT ac80 5290MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5260MHz Ant3



Freq. Stability NVNT ax20 5300MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5320MHz Ant3




Freq. Stability NVNT ax40 5270MHz Ant3






Freq. Stability NVNT ax40 5310MHz Ant3



Freq. Stability NVNT ax80 5290MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be20 5260MHz Ant3




Freq. Stability NVNT be20 5300MHz Ant3






Freq. Stability NVNT be20 5320MHz Ant3



Freq. Stability NVNT be40 5270MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be40 5310MHz Ant3



Freq. Stability NVNT be80 5290MHz Ant3



Freq. Stability NVNT ac160 5250MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Freq. Stability NVNT ax160 5250MHz Ant3




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity





Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	a	5260	Ant4	5259.98	-20000	-3.8	25	Pass
NVNT	a	5300	Ant4	5299.98	-20000	-3.77	25	Pass
NVNT	a	5320	Ant4	5319.98	-20000	-3.76	25	Pass
NVNT	n20	5260	Ant4	5259.96	-40000	-7.6	25	Pass
NVNT	n20	5300	Ant4	5300	0	0	25	Pass
NVNT	n20	5320	Ant4	5319.98	-20000	-3.76	25	Pass
NVNT	n40	5270	Ant4	5269.96	-40000	-7.59	25	Pass
NVNT	n40	5310	Ant4	5309.96	-40000	-7.53	25	Pass
NVNT	ac20	5260	Ant4	5260	0	0	25	Pass
NVNT	ac20	5300	Ant4	5299.98	-20000	-3.77	25	Pass
NVNT	ac20	5320	Ant4	5319.98	-20000	-3.76	25	Pass
NVNT	ac40	5270	Ant4	5270	0	0	25	Pass
NVNT	ac40	5310	Ant4	5309.96	-40000	-7.53	25	Pass
NVNT	ac80	5290	Ant4	5290	0	0	25	Pass
NVNT	ax20	5260	Ant4	5259.98	-20000	-3.8	25	Pass
NVNT	ax20	5300	Ant4	5300	0	0	25	Pass
NVNT	ax20	5320	Ant4	5319.98	-20000	-3.76	25	Pass
NVNT	ax40	5270	Ant4	5269.96	-40000	-7.59	25	Pass
NVNT	ax40	5310	Ant4	5310	0	0	25	Pass
NVNT	ax80	5290	Ant4	5290	0	0	25	Pass
NVNT	be20	5260	Ant4	5259.98	-20000	-3.8	25	Pass
NVNT	be20	5300	Ant4	5299.96	-40000	-7.55	25	Pass
NVNT	be20	5320	Ant4	5319.98	-20000	-3.76	25	Pass
NVNT	be40	5270	Ant4	5270	0	0	25	Pass
NVNT	be40	5310	Ant4	5310	0	0	25	Pass
NVNT	be80	5290	Ant4	5290	0	0	25	Pass
NVNT	ac160	5250	Ant4	5250	0	0	25	Pass
NVNT	ax160	5250	Ant4	5250	0	0	25	Pass
NVNT	be160	5250	Ant4	5250	0	0	25	Pass




Shenzhen LCS Compliance Testing Laboratory Ltd.
Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China
Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com
Scan code to check authenticity




Test Graphs

Freq. Stability NVNT a 5260MHz Ant4




Freq. Stability NVNT a 5300MHz Ant4






Freq. Stability NVNT a 5320MHz Ant4



Freq. Stability NVNT n20 5260MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n20 5300MHz Ant4




Freq. Stability NVNT n20 5320MHz Ant4






Freq. Stability NVNT n40 5270MHz Ant4




Freq. Stability NVNT n40 5310MHz Ant4






Freq. Stability NVNT ac20 5260MHz Ant4




Freq. Stability NVNT ac20 5300MHz Ant4






Freq. Stability NVNT ac20 5320MHz Ant4




Freq. Stability NVNT ac40 5270MHz Ant4






Freq. Stability NVNT ac40 5310MHz Ant4



Freq. Stability NVNT ac80 5290MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5260MHz Ant4



Freq. Stability NVNT ax20 5300MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5320MHz Ant4




Freq. Stability NVNT ax40 5270MHz Ant4






Freq. Stability NVNT ax40 5310MHz Ant4



Freq. Stability NVNT ax80 5290MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be20 5260MHz Ant4



Freq. Stability NVNT be20 5300MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be20 5320MHz Ant4




Freq. Stability NVNT be40 5270MHz Ant4






Freq. Stability NVNT be40 5310MHz Ant4




Freq. Stability NVNT be80 5290MHz Ant4





Freq. Stability NVNT ac160 5250MHz Ant4





Freq. Stability NVNT ax160 5250MHz Ant4







Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	a	5260	Ant5	5259.98	-20000	-3.8	25	Pass
NVNT	a	5300	Ant5	5300	0	0	25	Pass
NVNT	a	5320	Ant5	5319.98	-20000	-3.76	25	Pass
NVNT	n20	5260	Ant5	5259.98	-20000	-3.8	25	Pass
NVNT	n20	5300	Ant5	5299.98	-20000	-3.77	25	Pass
NVNT	n20	5320	Ant5	5319.98	-20000	-3.76	25	Pass
NVNT	n40	5270	Ant5	5270	0	0	25	Pass
NVNT	n40	5310	Ant5	5309.96	-40000	-7.53	25	Pass
NVNT	ac20	5260	Ant5	5259.98	-20000	-3.8	25	Pass
NVNT	ac20	5300	Ant5	5299.98	-20000	-3.77	25	Pass
NVNT	ac20	5320	Ant5	5320	0	0	25	Pass
NVNT	ac40	5270	Ant5	5269.96	-40000	-7.59	25	Pass
NVNT	ac40	5310	Ant5	5310	0	0	25	Pass
NVNT	ac80	5290	Ant5	5290	0	0	25	Pass
NVNT	ax20	5260	Ant5	5259.96	-40000	-7.6	25	Pass
NVNT	ax20	5300	Ant5	5299.98	-20000	-3.77	25	Pass
NVNT	ax20	5320	Ant5	5320	0	0	25	Pass
NVNT	ax40	5270	Ant5	5269.96	-40000	-7.59	25	Pass
NVNT	ax40	5310	Ant5	5309.96	-40000	-7.53	25	Pass
NVNT	ax80	5290	Ant5	5290	0	0	25	Pass
NVNT	be20	5260	Ant5	5260	0	0	25	Pass
NVNT	be20	5300	Ant5	5299.98	-20000	-3.77	25	Pass
NVNT	be20	5320	Ant5	5319.98	-20000	-3.76	25	Pass
NVNT	be40	5270	Ant5	5270	0	0	25	Pass
NVNT	be40	5310	Ant5	5310	0	0	25	Pass
NVNT	be80	5290	Ant5	5290	0	0	25	Pass
NVNT	ac160	5250	Ant5	5250	0	0	25	Pass
NVNT	ax160	5250	Ant5	5250	0	0	25	Pass
NVNT	be160	5250	Ant5	5250	0	0	25	Pass

