





Restrict Band NVNT ax20 5745MHz Ant5 Peak



Restrict Band NVNT ax20 5745MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5825MHz Ant5 Peak



Restrict Band NVNT ax20 5825MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5755MHz Ant5 Peak



Restrict Band NVNT ax40 5755MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5795MHz Ant5 Peak



Restrict Band NVNT ax40 5795MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5775MHz Ant5 Peak



Restrict Band NVNT ax80 5775MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5775MHz Ant5 Peak



Restrict Band NVNT ax80 5775MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be20 5745MHz Ant5 Peak



Restrict Band NVNT be20 5745MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be20 5825MHz Ant5 Peak



Restrict Band NVNT be20 5825MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be40 5755MHz Ant5 Peak



Restrict Band NVNT be40 5755MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be40 5795MHz Ant5 Peak



Restrict Band NVNT be40 5795MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be80 5775MHz Ant5 Peak



Restrict Band NVNT be80 5775MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT be80 5775MHz Ant5 Peak



Restrict Band NVNT be80 5775MHz Ant5 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



MIMO

Condition	Mode	Frequency (MHz)	Ant3 Power (dBm)	Ant4 Power (dBm)	Ant5 Power (dBm)	Gain (dBi)	EIRP Power (dBm)	Detector	Limit (dBm)	Verdict
NVNT	n20	5745	-47.98	-47.95	-46.9	9.05	-33.76	Peak	-27	Pass
NVNT	n20	5745	-56.9	-56.9	-56.64	9.05	-42.99	Average	-27	Pass
NVNT	n20	5745	-46.84	-46.5	-46.54	9.05	-32.80	Peak	10	Pass
NVNT	n20	5745	-55.3	-54.47	-54.25	9.05	-40.83	Average	10	Pass
NVNT	n20	5745	-36.77	-32.4	-33.18	9.05	-19.92	Peak	15.6	Pass
NVNT	n20	5745	-46.12	-46.18	-44.59	9.05	-31.74	Average	15.6	Pass
NVNT	n20	5745	-25.18	-28.71	-24.43	9.05	-11.93	Peak	27	Pass
NVNT	n20	5745	-40.6	-38.17	-39.28	9.05	-25.42	Average	27	Pass
NVNT	n20	5825	-29.95	-33.8	-29.39	9.05	-16.84	Peak	27	Pass
NVNT	n20	5825	-44.99	-45.44	-45.76	9.05	-31.56	Average	27	Pass
NVNT	n20	5825	-37.77	-34.55	-38.06	9.05	-22.66	Peak	15.6	Pass
NVNT	n20	5825	-50.57	-50.47	-52.36	9.05	-37.23	Average	15.6	Pass
NVNT	n20	5825	-47.29	-45.92	-45.9	9.05	-32.50	Peak	10	Pass
NVNT	n20	5825	-55.24	-55	-54.62	9.05	-41.12	Average	10	Pass
NVNT	n20	5825	-47.41	-47.81	-46.09	9.05	-33.22	Peak	-27	Pass
NVNT	n20	5825	-55.39	-55.3	-55.73	9.05	-41.65	Average	-27	Pass
NVNT	n40	5755	-47.7	-47.71	-48.36	9.05	-34.09	Peak	-27	Pass
NVNT	n40	5755	-56.39	-56.96	-56.47	9.05	-42.78	Average	-27	Pass
NVNT	n40	5755	-42.2	-44.34	-43.24	9.05	-29.35	Peak	10	Pass
NVNT	n40	5755	-51.88	-53.13	-52.85	9.05	-38.77	Average	10	Pass
NVNT	n40	5755	-27.12	-26.07	-31.4	9.05	-13.84	Peak	15.6	Pass
NVNT	n40	5755	-39.28	-43.37	-45.19	9.05	-28.06	Average	15.6	Pass
NVNT	n40	5755	-27.52	-26.53	-28.33	9.05	-13.58	Peak	27	Pass
NVNT	n40	5755	-37.22	-39.32	-40.29	9.05	-24.93	Average	27	Pass
NVNT	n40	5795	-46.31	-46.39	-46.18	9.05	-32.47	Peak	27	Pass
NVNT	n40	5795	-54.09	-54.54	-54.6	9.05	-40.58	Average	27	Pass
NVNT	n40	5795	-46.57	-45.34	-47.99	9.05	-32.68	Peak	15.6	Pass
NVNT	n40	5795	-54.27	-55.34	-55.24	9.05	-41.10	Average	15.6	Pass
NVNT	n40	5795	-47.67	-48.22	-50.44	9.05	-34.80	Peak	10	Pass
NVNT	n40	5795	-57.06	-56.76	-57.82	9.05	-43.37	Average	10	Pass
NVNT	n40	5795	-47.57	-47.94	-48.57	9.05	-34.19	Peak	-27	Pass
NVNT	n40	5795	-57.29	-56.99	-56.99	9.05	-43.27	Average	-27	Pass
NVNT	ac20	5745	-49.29	-49.45	-48.52	9.05	-35.25	Peak	-27	Pass
NVNT	ac20	5745	-56.27	-56.41	-56.64	9.05	-42.62	Average	-27	Pass
NVNT	ac20	5745	-46.64	-45.25	-46.01	9.05	-32.11	Peak	10	Pass
NVNT	ac20	5745	-54.28	-55.03	-54.51	9.05	-40.77	Average	10	Pass
NVNT	ac20	5745	-33.41	-32.47	-31.84	9.05	-18.70	Peak	15.6	Pass
NVNT	ac20	5745	-45.9	-45.57	-45.39	9.05	-31.79	Average	15.6	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5745	-24.27	-23.54	-21.42	9.05	-9.08	Peak	27	Pass
NVNT	ac20	5745	-39.35	-38.76	-38.63	9.05	-25.08	Average	27	Pass
NVNT	ac20	5825	-31.37	-34.95	-33.25	9.05	-19.12	Peak	27	Pass
NVNT	ac20	5825	-44.94	-46.94	-47.15	9.05	-32.40	Average	27	Pass
NVNT	ac20	5825	-38.64	-40	-40.35	9.05	-25.78	Peak	15.6	Pass
NVNT	ac20	5825	-51.17	-51.45	-51.5	9.05	-37.55	Average	15.6	Pass
NVNT	ac20	5825	-46.46	-46.44	-45.68	9.05	-32.36	Peak	10	Pass
NVNT	ac20	5825	-55.24	-55.62	-55.11	9.05	-41.50	Average	10	Pass
NVNT	ac20	5825	-45.65	-46.66	-47.4	9.05	-32.69	Peak	-27	Pass
NVNT	ac20	5825	-55.23	-55.88	-55.43	9.05	-41.68	Average	-27	Pass
NVNT	ac40	5755	-50	-49.83	-49.13	9.05	-35.82	Peak	-27	Pass
NVNT	ac40	5755	-56.34	-56.58	-56.98	9.05	-42.80	Average	-27	Pass
NVNT	ac40	5755	-44.11	-43.41	-42.86	9.05	-29.61	Peak	10	Pass
NVNT	ac40	5755	-51.94	-53.38	-52.88	9.05	-38.87	Average	10	Pass
NVNT	ac40	5755	-29.35	-29.7	-28.86	9.05	-15.47	Peak	15.6	Pass
NVNT	ac40	5755	-39.82	-42.8	-44.99	9.05	-28.20	Average	15.6	Pass
NVNT	ac40	5755	-27.61	-29.52	-18.91	9.05	-8.99	Peak	27	Pass
NVNT	ac40	5755	-38.09	-40.96	-41.59	9.05	-26.11	Average	27	Pass
NVNT	ac40	5795	-45.17	-45.66	-45.3	9.05	-31.55	Peak	27	Pass
NVNT	ac40	5795	-54.04	-53.93	-55.04	9.05	-40.49	Average	27	Pass
NVNT	ac40	5795	-44.53	-45.73	-47.35	9.05	-31.90	Peak	15.6	Pass
NVNT	ac40	5795	-54.51	-54.55	-55.87	9.05	-41.11	Average	15.6	Pass
NVNT	ac40	5795	-49.74	-49.08	-48.83	9.05	-35.38	Peak	10	Pass
NVNT	ac40	5795	-57.55	-56.84	-57.28	9.05	-43.39	Average	10	Pass
NVNT	ac40	5795	-48.35	-49.85	-49.33	9.05	-35.31	Peak	-27	Pass
NVNT	ac40	5795	-57.12	-57.42	-57.02	9.05	-43.36	Average	-27	Pass
NVNT	ac80	5775	-33.12	-33.79	-39.19	9.05	-20.84	Peak	27	Pass
NVNT	ac80	5775	-43.99	-43.76	-47.77	9.05	-31.01	Average	27	Pass
NVNT	ac80	5775	-35.64	-34.44	-38.81	9.05	-22.12	Peak	15.6	Pass
NVNT	ac80	5775	-44.3	-44.7	-49.21	9.05	-31.76	Average	15.6	Pass
NVNT	ac80	5775	-41.61	-37.25	-44.72	9.05	-26.31	Peak	10	Pass
NVNT	ac80	5775	-50.6	-50.31	-53.99	9.05	-37.52	Average	10	Pass
NVNT	ac80	5775	-47.87	-47.17	-48.64	9.05	-34.03	Peak	-27	Pass
NVNT	ac80	5775	-56.9	-56.93	-57.03	9.05	-43.13	Average	-27	Pass
NVNT	ac80	5775	-46.93	-45.94	-47.01	9.05	-32.78	Peak	-27	Pass
NVNT	ac80	5775	-55.38	-55.57	-55.22	9.05	-41.57	Average	-27	Pass
NVNT	ac80	5775	-33.29	-34.44	-40.43	9.05	-21.32	Peak	10	Pass
NVNT	ac80	5775	-44.86	-44.38	-48.95	9.05	-31.82	Average	10	Pass
NVNT	ac80	5775	-29.02	-27.1	-31.85	9.05	-15.09	Peak	15.6	Pass
NVNT	ac80	5775	-39.82	-39.99	-44	9.05	-27.07	Average	15.6	Pass
NVNT	ac80	5775	-28.35	-28.7	-30.5	9.05	-15.27	Peak	27	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac80	5775	-40.34	-39.4	-42.18	9.05	-26.67	Average	27	Pass
NVNT	ax20	5745	-48.98	-50.13	-48.54	9.05	-35.35	Peak	-27	Pass
NVNT	ax20	5745	-56.72	-56.64	-56.53	9.05	-42.81	Average	-27	Pass
NVNT	ax20	5745	-45.65	-45.38	-46.34	9.05	-31.95	Peak	10	Pass
NVNT	ax20	5745	-54.63	-54.86	-54.41	9.05	-40.81	Average	10	Pass
NVNT	ax20	5745	-33.78	-33.75	-26.86	9.05	-16.32	Peak	15.6	Pass
NVNT	ax20	5745	-46.05	-45.81	-46.12	9.05	-32.17	Average	15.6	Pass
NVNT	ax20	5745	-22.49	-23.42	-23.71	9.05	-9.35	Peak	27	Pass
NVNT	ax20	5745	-39.2	-36.91	-38.61	9.05	-24.31	Average	27	Pass
NVNT	ax20	5825	-28.52	-36.67	-35.3	9.05	-18.13	Peak	27	Pass
NVNT	ax20	5825	-45.58	-46.23	-46.64	9.05	-32.31	Average	27	Pass
NVNT	ax20	5825	-40.52	-41.04	-38.67	9.05	-26.13	Peak	15.6	Pass
NVNT	ax20	5825	-51.77	-51.46	-51.87	9.05	-37.88	Average	15.6	Pass
NVNT	ax20	5825	-46.49	-47.17	-47.76	9.05	-33.29	Peak	10	Pass
NVNT	ax20	5825	-54.67	-55.19	-55.41	9.05	-41.26	Average	10	Pass
NVNT	ax20	5825	-48.25	-48.29	-48.84	9.05	-34.63	Peak	-27	Pass
NVNT	ax20	5825	-55.25	-55.43	-55.57	9.05	-41.59	Average	-27	Pass
NVNT	ax40	5755	-46.86	-47.82	-49.54	9.05	-34.12	Peak	-27	Pass
NVNT	ax40	5755	-56.56	-56.62	-56.65	9.05	-42.79	Average	-27	Pass
NVNT	ax40	5755	-42.96	-45.12	-45.58	9.05	-30.58	Peak	10	Pass
NVNT	ax40	5755	-51.96	-53.15	-52.84	9.05	-38.80	Average	10	Pass
NVNT	ax40	5755	-27.13	-31.74	-30.95	9.05	-15.62	Peak	15.6	Pass
NVNT	ax40	5755	-40.25	-42.27	-43.47	9.05	-27.97	Average	15.6	Pass
NVNT	ax40	5755	-27.06	-27.8	-22.3	9.05	-11.17	Peak	27	Pass
NVNT	ax40	5755	-37.2	-39.87	-41.03	9.05	-25.24	Average	27	Pass
NVNT	ax40	5795	-47.05	-43.65	-47.18	9.05	-31.81	Peak	27	Pass
NVNT	ax40	5795	-54.69	-54.35	-55	9.05	-40.85	Average	27	Pass
NVNT	ax40	5795	-41	-45.38	-45.53	9.05	-29.60	Peak	15.6	Pass
NVNT	ax40	5795	-55.1	-55.55	-55.61	9.05	-41.59	Average	15.6	Pass
NVNT	ax40	5795	-49.15	-48.84	-50.24	9.05	-35.55	Peak	10	Pass
NVNT	ax40	5795	-57.27	-57.53	-57.05	9.05	-43.46	Average	10	Pass
NVNT	ax40	5795	-49.93	-48.59	-50.16	9.05	-35.68	Peak	-27	Pass
NVNT	ax40	5795	-56.89	-57.73	-56.9	9.05	-43.33	Average	-27	Pass
NVNT	ax80	5775	-34.27	-32.61	-40.12	9.05	-20.87	Peak	27	Pass
NVNT	ax80	5775	-43.97	-43.56	-48.16	9.05	-30.98	Average	27	Pass
NVNT	ax80	5775	-36.55	-32.59	-39.2	9.05	-21.44	Peak	15.6	Pass
NVNT	ax80	5775	-43.79	-44.5	-49.48	9.05	-31.48	Average	15.6	Pass
NVNT	ax80	5775	-39.77	-42.73	-45.7	9.05	-28.26	Peak	10	Pass
NVNT	ax80	5775	-50.79	-50.87	-53.98	9.05	-37.83	Average	10	Pass
NVNT	ax80	5775	-49.04	-48.37	-48.91	9.05	-34.94	Peak	-27	Pass
NVNT	ax80	5775	-56.62	-56.85	-56.67	9.05	-42.89	Average	-27	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ax80	5775	-46.65	-47.65	-47.92	9.05	-33.55	Peak	-27	Pass
NVNT	ax80	5775	-54.5	-55.58	-55.49	9.05	-41.34	Average	-27	Pass
NVNT	ax80	5775	-35.93	-35.3	-39.92	9.05	-22.81	Peak	10	Pass
NVNT	ax80	5775	-45.07	-45.13	-49.07	9.05	-32.25	Average	10	Pass
NVNT	ax80	5775	-31.58	-29.65	-34.17	9.05	-17.60	Peak	15.6	Pass
NVNT	ax80	5775	-39.89	-40.51	-45.27	9.05	-27.50	Average	15.6	Pass
NVNT	ax80	5775	-26.91	-24.47	-28.33	9.05	-12.45	Peak	27	Pass
NVNT	ax80	5775	-39.66	-38.73	-43.51	9.05	-26.38	Average	27	Pass
NVNT	be20	5745	-48.78	-49.03	-49.62	9.05	-35.31	Peak	-27	Pass
NVNT	be20	5745	-56.79	-56.41	-56.91	9.05	-42.88	Average	-27	Pass
NVNT	be20	5745	-44.74	-46.45	-45.07	9.05	-31.54	Peak	10	Pass
NVNT	be20	5745	-54.89	-55.34	-54.39	9.05	-41.03	Average	10	Pass
NVNT	be20	5745	-33.33	-28.03	-30.57	9.05	-16.30	Peak	15.6	Pass
NVNT	be20	5745	-47.1	-44.51	-46.39	9.05	-32.04	Average	15.6	Pass
NVNT	be20	5745	-22.85	-27.27	-17.37	9.05	-6.90	Peak	27	Pass
NVNT	be20	5745	-38.79	-39.35	-38.84	9.05	-25.16	Average	27	Pass
NVNT	be20	5825	-32.81	-31.8	-33.23	9.05	-18.75	Peak	27	Pass
NVNT	be20	5825	-46.52	-47.34	-47.35	9.05	-33.23	Average	27	Pass
NVNT	be20	5825	-40.3	-38.09	-39.92	9.05	-25.50	Peak	15.6	Pass
NVNT	be20	5825	-51.16	-51.41	-51.92	9.05	-37.66	Average	15.6	Pass
NVNT	be20	5825	-45.4	-48.61	-46.94	9.05	-32.97	Peak	10	Pass
NVNT	be20	5825	-54.81	-55.12	-55.14	9.05	-41.20	Average	10	Pass
NVNT	be20	5825	-45.65	-47.63	-47.44	9.05	-32.99	Peak	-27	Pass
NVNT	be20	5825	-56.03	-55.46	-55.61	9.05	-41.87	Average	-27	Pass
NVNT	be40	5755	-47.24	-49.21	-49.31	9.05	-34.66	Peak	-27	Pass
NVNT	be40	5755	-56.01	-57	-56.82	9.05	-42.77	Average	-27	Pass
NVNT	be40	5755	-42.64	-45.38	-43.54	9.05	-29.89	Peak	10	Pass
NVNT	be40	5755	-51.73	-53.56	-52.95	9.05	-38.86	Average	10	Pass
NVNT	be40	5755	-30.29	-29.24	-28.29	9.05	-15.38	Peak	15.6	Pass
NVNT	be40	5755	-39.65	-42.81	-42.58	9.05	-27.61	Average	15.6	Pass
NVNT	be40	5755	-26.6	-28.3	-26.04	9.05	-13.06	Peak	27	Pass
NVNT	be40	5755	-36.84	-41.41	-42.32	9.05	-25.66	Average	27	Pass
NVNT	be40	5795	-45.26	-44.12	-46.3	9.05	-31.31	Peak	27	Pass
NVNT	be40	5795	-54	-54.4	-54.87	9.05	-40.59	Average	27	Pass
NVNT	be40	5795	-45.3	-46.53	-47.42	9.05	-32.51	Peak	15.6	Pass
NVNT	be40	5795	-54.8	-54.97	-55.58	9.05	-41.28	Average	15.6	Pass
NVNT	be40	5795	-50.63	-48.51	-49.52	9.05	-35.65	Peak	10	Pass
NVNT	be40	5795	-57.47	-57.41	-57.31	9.05	-43.57	Average	10	Pass
NVNT	be40	5795	-48.67	-49.41	-48.27	9.05	-34.94	Peak	-27	Pass
NVNT	be40	5795	-57.09	-56.62	-57.23	9.05	-43.15	Average	-27	Pass
NVNT	be80	5775	-32.45	-33.78	-39.84	9.05	-20.57	Peak	27	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	be80	5775	-43.37	-43.48	-48.24	9.05	-30.70	Average	27	Pass
NVNT	be80	5775	-35.24	-36.25	-39.87	9.05	-22.89	Peak	15.6	Pass
NVNT	be80	5775	-44.38	-44.58	-48.99	9.05	-31.71	Average	15.6	Pass
NVNT	be80	5775	-40.31	-36.71	-43.36	9.05	-25.48	Peak	10	Pass
NVNT	be80	5775	-50.98	-51.35	-53.32	9.05	-37.95	Average	10	Pass
NVNT	be80	5775	-49.31	-49.08	-49.15	9.05	-35.36	Peak	-27	Pass
NVNT	be80	5775	-57.23	-56.63	-57.09	9.05	-43.15	Average	-27	Pass
NVNT	be80	5775	-46.76	-47.97	-48.35	9.05	-33.82	Peak	-27	Pass
NVNT	be80	5775	-55.34	-55.69	-55.64	9.05	-41.73	Average	-27	Pass
NVNT	be80	5775	-35.88	-35.26	-38.51	9.05	-22.52	Peak	10	Pass
NVNT	be80	5775	-44.58	-44.47	-49.02	9.05	-31.75	Average	10	Pass
NVNT	be80	5775	-29.02	-30.35	-32.64	9.05	-16.60	Peak	15.6	Pass
NVNT	be80	5775	-40.77	-40.42	-44.35	9.05	-27.70	Average	15.6	Pass
NVNT	be80	5775	-28.89	-22.92	-27.11	9.05	-11.74	Peak	27	Pass
NVNT	be80	5775	-38.7	-39.51	-42.93	9.05	-26.21	Average	27	Pass





D.5 Frequency Stability


Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	a	5745	Ant3	5744.98	-20000	-3.48	25	Pass
NVNT	a	5785	Ant3	5784.98	-20000	-3.46	25	Pass
NVNT	a	5825	Ant3	5824.98	-20000	-3.43	25	Pass
NVNT	n20	5745	Ant3	5744.98	-20000	-3.48	25	Pass
NVNT	n20	5785	Ant3	5784.98	-20000	-3.46	25	Pass
NVNT	n20	5825	Ant3	5824.98	-20000	-3.43	25	Pass
NVNT	n40	5755	Ant3	5754.96	-40000	-6.95	25	Pass
NVNT	n40	5795	Ant3	5795	0	0	25	Pass
NVNT	ac20	5745	Ant3	5744.98	-20000	-3.48	25	Pass
NVNT	ac20	5785	Ant3	5785	0	0	25	Pass
NVNT	ac20	5825	Ant3	5824.98	-20000	-3.43	25	Pass
NVNT	ac40	5755	Ant3	5755	0	0	25	Pass
NVNT	ac40	5795	Ant3	5795	0	0	25	Pass
NVNT	ac80	5775	Ant3	5775	0	0	25	Pass
NVNT	ax20	5745	Ant3	5744.98	-20000	-3.48	25	Pass
NVNT	ax20	5785	Ant3	5784.98	-20000	-3.46	25	Pass
NVNT	ax20	5825	Ant3	5824.98	-20000	-3.43	25	Pass
NVNT	ax40	5755	Ant3	5755	0	0	25	Pass
NVNT	ax40	5795	Ant3	5794.96	-40000	-6.9	25	Pass
NVNT	ax80	5775	Ant3	5775	0	0	25	Pass
NVNT	be20	5745	Ant3	5744.98	-20000	-3.48	25	Pass
NVNT	be20	5785	Ant3	5784.96	-40000	-6.91	25	Pass
NVNT	be20	5825	Ant3	5824.98	-20000	-3.43	25	Pass
NVNT	be40	5755	Ant3	5755	0	0	25	Pass
NVNT	be40	5795	Ant3	5795	0	0	25	Pass
NVNT	be80	5775	Ant3	5775	0	0	25	Pass






Test Graphs

Freq. Stability NVNT a 5745MHz Ant3




Freq. Stability NVNT a 5785MHz Ant3






Freq. Stability NVNT a 5825MHz Ant3



Freq. Stability NVNT n20 5745MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n20 5785MHz Ant3



Freq. Stability NVNT n20 5825MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n40 5755MHz Ant3



Freq. Stability NVNT n40 5795MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5745MHz Ant3



Freq. Stability NVNT ac20 5785MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5825MHz Ant3




Freq. Stability NVNT ac40 5755MHz Ant3






Freq. Stability NVNT ac40 5795MHz Ant3



Freq. Stability NVNT ac80 5775MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5745MHz Ant3




Freq. Stability NVNT ax20 5785MHz Ant3






Freq. Stability NVNT ax20 5825MHz Ant3



Freq. Stability NVNT ax40 5755MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax40 5795MHz Ant3



Freq. Stability NVNT ax80 5775MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be20 5745MHz Ant3



Freq. Stability NVNT be20 5785MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be20 5825MHz Ant3



Freq. Stability NVNT be40 5755MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be40 5795MHz Ant3



Freq. Stability NVNT be80 5775MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	a	5745	Ant4	5745	0	0	25	Pass
NVNT	a	5785	Ant4	5785	0	0	25	Pass
NVNT	a	5825	Ant4	5825	0	0	25	Pass
NVNT	n20	5745	Ant4	5744.98	-20000	-3.48	25	Pass
NVNT	n20	5785	Ant4	5784.96	-40000	-6.91	25	Pass
NVNT	n20	5825	Ant4	5824.98	-20000	-3.43	25	Pass
NVNT	n40	5755	Ant4	5754.96	-40000	-6.95	25	Pass
NVNT	n40	5795	Ant4	5794.96	-40000	-6.9	25	Pass
NVNT	ac20	5745	Ant4	5744.98	-20000	-3.48	25	Pass
NVNT	ac20	5785	Ant4	5784.98	-20000	-3.46	25	Pass
NVNT	ac20	5825	Ant4	5824.98	-20000	-3.43	25	Pass
NVNT	ac40	5755	Ant4	5755	0	0	25	Pass
NVNT	ac40	5795	Ant4	5794.96	-40000	-6.9	25	Pass
NVNT	ac80	5775	Ant4	5775	0	0	25	Pass
NVNT	ax20	5745	Ant4	5744.98	-20000	-3.48	25	Pass
NVNT	ax20	5785	Ant4	5784.98	-20000	-3.46	25	Pass
NVNT	ax20	5825	Ant4	5824.96	-40000	-6.87	25	Pass
NVNT	ax40	5755	Ant4	5755	0	0	25	Pass
NVNT	ax40	5795	Ant4	5795	0	0	25	Pass
NVNT	ax80	5775	Ant4	5775	0	0	25	Pass
NVNT	be20	5745	Ant4	5744.98	-20000	-3.48	25	Pass
NVNT	be20	5785	Ant4	5785	0	0	25	Pass
NVNT	be20	5825	Ant4	5824.98	-20000	-3.43	25	Pass
NVNT	be40	5755	Ant4	5755	0	0	25	Pass
NVNT	be40	5795	Ant4	5795	0	0	25	Pass
NVNT	be80	5775	Ant4	5775	0	0	25	Pass






Test Graphs

Freq. Stability NVNT a 5745MHz Ant4



Freq. Stability NVNT a 5785MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT a 5825MHz Ant4



Freq. Stability NVNT n20 5745MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n20 5785MHz Ant4




Freq. Stability NVNT n20 5825MHz Ant4






Freq. Stability NVNT n40 5755MHz Ant4




Freq. Stability NVNT n40 5795MHz Ant4






Freq. Stability NVNT ac20 5745MHz Ant4



Freq. Stability NVNT ac20 5785MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5825MHz Ant4



Freq. Stability NVNT ac40 5755MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac40 5795MHz Ant4




Freq. Stability NVNT ac80 5775MHz Ant4






Freq. Stability NVNT ax20 5745MHz Ant4



Freq. Stability NVNT ax20 5785MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5825MHz Ant4




Freq. Stability NVNT ax40 5755MHz Ant4






Freq. Stability NVNT ax40 5795MHz Ant4




Freq. Stability NVNT ax80 5775MHz Ant4






Freq. Stability NVNT be20 5745MHz Ant4



Freq. Stability NVNT be20 5785MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be20 5825MHz Ant4



Freq. Stability NVNT be40 5755MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be40 5795MHz Ant4



Freq. Stability NVNT be80 5775MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	a	5745	Ant5	5745	0	0	25	Pass
NVNT	a	5785	Ant5	5784.98	-20000	-3.46	25	Pass
NVNT	a	5825	Ant5	5824.98	-20000	-3.43	25	Pass
NVNT	n20	5745	Ant5	5744.98	-20000	-3.48	25	Pass
NVNT	n20	5785	Ant5	5785	0	0	25	Pass
NVNT	n20	5825	Ant5	5824.96	-40000	-6.87	25	Pass
NVNT	n40	5755	Ant5	5755	0	0	25	Pass
NVNT	n40	5795	Ant5	5795	0	0	25	Pass
NVNT	ac20	5745	Ant5	5745	0	0	25	Pass
NVNT	ac20	5785	Ant5	5784.98	-20000	-3.46	25	Pass
NVNT	ac20	5825	Ant5	5824.98	-20000	-3.43	25	Pass
NVNT	ac40	5755	Ant5	5754.96	-40000	-6.95	25	Pass
NVNT	ac40	5795	Ant5	5795	0	0	25	Pass
NVNT	ac80	5775	Ant5	5775	0	0	25	Pass
NVNT	ax20	5745	Ant5	5744.98	-20000	-3.48	25	Pass
NVNT	ax20	5785	Ant5	5784.98	-20000	-3.46	25	Pass
NVNT	ax20	5825	Ant5	5824.96	-40000	-6.87	25	Pass
NVNT	ax40	5755	Ant5	5755	0	0	25	Pass
NVNT	ax40	5795	Ant5	5794.96	-40000	-6.9	25	Pass
NVNT	ax80	5775	Ant5	5775	0	0	25	Pass
NVNT	be20	5745	Ant5	5744.98	-20000	-3.48	25	Pass
NVNT	be20	5785	Ant5	5784.98	-20000	-3.46	25	Pass
NVNT	be20	5825	Ant5	5824.98	-20000	-3.43	25	Pass
NVNT	be40	5755	Ant5	5754.96	-40000	-6.95	25	Pass
NVNT	be40	5795	Ant5	5795	0	0	25	Pass
NVNT	be80	5775	Ant5	5775	0	0	25	Pass






Test Graphs

Freq. Stability NVNT a 5745MHz Ant5




Freq. Stability NVNT a 5785MHz Ant5






Freq. Stability NVNT a 5825MHz Ant5



Freq. Stability NVNT n20 5745MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n20 5785MHz Ant5




Freq. Stability NVNT n20 5825MHz Ant5






Freq. Stability NVNT n40 5755MHz Ant5




Freq. Stability NVNT n40 5795MHz Ant5






Freq. Stability NVNT ac20 5745MHz Ant5



Freq. Stability NVNT ac20 5785MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5825MHz Ant5



Freq. Stability NVNT ac40 5755MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac40 5795MHz Ant5



Freq. Stability NVNT ac80 5775MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5745MHz Ant5



Freq. Stability NVNT ax20 5785MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5825MHz Ant5




Freq. Stability NVNT ax40 5755MHz Ant5






Freq. Stability NVNT ax40 5795MHz Ant5




Freq. Stability NVNT ax80 5775MHz Ant5






Freq. Stability NVNT be20 5745MHz Ant5



Freq. Stability NVNT be20 5785MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be20 5825MHz Ant5



Freq. Stability NVNT be40 5755MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT be40 5795MHz Ant5



Freq. Stability NVNT be80 5775MHz Ant5



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



D.6 Duty Cycle


Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5745	Ant3	94.65	0.24	0.91
NVNT	a	5785	Ant3	94.56	0.24	0.91
NVNT	a	5825	Ant3	94.57	0.24	0.91
NVNT	n20	5745	Ant3	97.33	0.12	0.44
NVNT	n20	5785	Ant3	97.29	0.12	0.44
NVNT	n20	5825	Ant3	97.29	0.12	0.44
NVNT	n40	5755	Ant3	94.71	0.24	0.9
NVNT	n40	5795	Ant3	94.71	0.24	0.9
NVNT	ac20	5745	Ant3	97.34	0.12	0.44
NVNT	ac20	5785	Ant3	97.34	0.12	0.44
NVNT	ac20	5825	Ant3	97.34	0.12	0.44
NVNT	ac40	5755	Ant3	94.72	0.24	0.9
NVNT	ac40	5795	Ant3	94.72	0.24	0.9
NVNT	ac80	5775	Ant3	89.65	0.47	1.86
NVNT	ax20	5745	Ant3	97.34	0.12	0.44
NVNT	ax20	5785	Ant3	97.34	0.12	0.44
NVNT	ax20	5825	Ant3	97.34	0.12	0.44
NVNT	ax40	5755	Ant3	94.72	0.24	0.9
NVNT	ax40	5795	Ant3	94.72	0.24	0.9
NVNT	ax80	5775	Ant3	89.65	0.47	1.86
NVNT	be20	5745	Ant3	97.34	0.12	0.44
NVNT	be20	5785	Ant3	97.3	0.12	0.44
NVNT	be20	5825	Ant3	97.34	0.12	0.44
NVNT	be40	5755	Ant3	94.72	0.24	0.9
NVNT	be40	5795	Ant3	94.72	0.24	0.9
NVNT	be80	5775	Ant3	89.65	0.47	1.86






Test Graphs

Duty Cycle NVNT a 5745MHz Ant3



Duty Cycle NVNT a 5785MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT a 5825MHz Ant3



Duty Cycle NVNT n20 5745MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT n20 5785MHz Ant3




Duty Cycle NVNT n20 5825MHz Ant3






Duty Cycle NVNT n40 5755MHz Ant3




Duty Cycle NVNT n40 5795MHz Ant3






Duty Cycle NVNT ac20 5745MHz Ant3



Duty Cycle NVNT ac20 5785MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac20 5825MHz Ant3



Duty Cycle NVNT ac40 5755MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac40 5795MHz Ant3



Duty Cycle NVNT ac80 5775MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax20 5745MHz Ant3



Duty Cycle NVNT ax20 5785MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax20 5825MHz Ant3



Duty Cycle NVNT ax40 5755MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax40 5795MHz Ant3



Duty Cycle NVNT ax80 5775MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT be20 5745MHz Ant3




Duty Cycle NVNT be20 5785MHz Ant3






Duty Cycle NVNT be20 5825MHz Ant3



Duty Cycle NVNT be40 5755MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT be40 5795MHz Ant3



Duty Cycle NVNT be80 5775MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5745	Ant4	94.56	0.24	0.91
NVNT	a	5785	Ant4	94.56	0.24	0.91
NVNT	a	5825	Ant4	94.65	0.24	0.91
NVNT	n20	5745	Ant4	97.33	0.12	0.44
NVNT	n20	5785	Ant4	97.29	0.12	0.44
NVNT	n20	5825	Ant4	97.29	0.12	0.44
NVNT	n40	5755	Ant4	94.71	0.24	0.9
NVNT	n40	5795	Ant4	94.71	0.24	0.9
NVNT	ac20	5745	Ant4	97.34	0.12	0.44
NVNT	ac20	5785	Ant4	97.34	0.12	0.44
NVNT	ac20	5825	Ant4	97.34	0.12	0.44
NVNT	ac40	5755	Ant4	94.72	0.24	0.9
NVNT	ac40	5795	Ant4	94.81	0.23	0.9
NVNT	ac80	5775	Ant4	89.82	0.47	1.86
NVNT	ax20	5745	Ant4	97.34	0.12	0.44
NVNT	ax20	5785	Ant4	97.34	0.12	0.44
NVNT	ax20	5825	Ant4	97.34	0.12	0.44
NVNT	ax40	5755	Ant4	94.72	0.24	0.9
NVNT	ax40	5795	Ant4	94.81	0.23	0.9
NVNT	ax80	5775	Ant4	89.65	0.47	1.86
NVNT	be20	5745	Ant4	97.34	0.12	0.44
NVNT	be20	5785	Ant4	97.3	0.12	0.44
NVNT	be20	5825	Ant4	97.34	0.12	0.44
NVNT	be40	5755	Ant4	94.72	0.24	0.9
NVNT	be40	5795	Ant4	94.72	0.24	0.9
NVNT	be80	5775	Ant4	89.82	0.47	1.86






Test Graphs

Duty Cycle NVNT a 5745MHz Ant4




Duty Cycle NVNT a 5785MHz Ant4






Duty Cycle NVNT a 5825MHz Ant4




Duty Cycle NVNT n20 5745MHz Ant4






Duty Cycle NVNT n20 5785MHz Ant4




Duty Cycle NVNT n20 5825MHz Ant4






Duty Cycle NVNT n40 5755MHz Ant4



Duty Cycle NVNT n40 5795MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac20 5745MHz Ant4



Duty Cycle NVNT ac20 5785MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac20 5825MHz Ant4



Duty Cycle NVNT ac40 5755MHz Ant4



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity