

SHENZHEN TENDA TECHNOLOGY CO., LTD.

Add: 6-8 Floor, Tower E3, No. 1001, Zhongshanyuan Road, Nanshan District, Shenzhen, China.
518052

Tel: 86-755-27657098 Fax: 866-755-27657178

E-mail: cert@tenda.cn

Attestation Letter

Date: 2024-06-17

FEDERAL COMMUNICATIONS COMMISSION

Authorization and Evaluation Division


7435 Oakland Mills Road

Columbia, MD 21046

Dear Sir or Madam:

Our product AX3000 Dual Band Gigabit Wi-Fi 6 Router, model: RX12L Pro, TX12L Pro, FCC ID: V7TRX12LP1, for marketing purpose, this product only supports 2.4G Wi-Fi (2412-2462MHz, 802.11b/g/n ht20/ax he20 modes, 2422-2452MHz, 802.11n ht40/ax he40), 5G Wi-Fi (5180-5240MHz, 802.11a/n ht20/ac vht20/ax he20 modes, 5190-5230MHz, 802.11n ht40/ac vht40/ax he40 modes, 5210MHz, 802.11ac vht80/ax he80 modes, 5260-5320MHz, 802.11a/n ht20/ac vht20/ax he20 modes, 5270-5310MHz, 802.11n ht40/ ac vht40/ax he40 modes, 5290MHz, 802.11ac vht80/ax he80 modes, 5250MHz, 802.11ac vht160/ax he160 modes, 5745-5825MHz, 802.11a/n ht20/ac vht20/ax he20 modes, 5755-5795MHz, 802.11n ht40/ac vht40/ax he40 modes, 5775MHz, 802.11ac vht80/ax he80 modes). 802.11ax mode only supports full RU and doesn't support partial RU. The other functions, bands and modes was disabled to use by manufacturer in the software, the end user has no capability to activate it.

Sincerely,



Printed Name: Shen Yue

Title: Engineer