


INTERTEK TESTING SERVICE

Report No.: 16030252HKG-001

Equipment Photographs

Model : 94141

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030252HKG-001

Equipment Photographs

Model : 94141

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030252HKG-001

Equipment Photographs

Model : 94141

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030252HKG-001

Equipment Photographs

Model : 94141

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030252HKG-001

Equipment Photographs

Model : 94141

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16030252HKG-001

Equipment Photographs

Model : 94141

(Internal)

