

INTERTEK TESTING SERVICE

Report No.: 16040642HKG-001

Equipment Photographs

Model : 94195

(Internal)



FCC ID: V9Q-94195R24



INTERTEK TESTING SERVICE

Report No.: 16040642HKG-001

Equipment Photographs

Model : 94195

(Internal)



FCC ID: V9Q-94195R24



INTERTEK TESTING SERVICE

Report No.: 16040642HKG-001

Equipment Photographs

Model : 94195

(Internal)



FCC ID: V9Q-94195R24



INTERTEK TESTING SERVICE

Report No.: 16040642HKG-001

Equipment Photographs

Model : 94195

(Internal)



FCC ID: V9Q-94195R24


INTERTEK TESTING SERVICE

Report No.: 16040642HKG-001

Equipment Photographs

Model : 94195

(Internal)



FCC ID: V9Q-94195R24