

Draytek Corporation
No. 26, Fu Shing Rd., Hukou County, Hsinchu
Industrial Park, Hsinchu 303 Taiwan

DECLARATION OF SIMILARITY

May 12, 2017

FEDERAL COMMUNICATIONS COMMISSIONS
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Dear Sir or Madam:

We Draytek Corporation hereby declare that product: VDSL2 & ADSL2+ Dual-WAN

Security Router, model(s): Vigor2862BLgVac, Series Model: Vigor2862Lac,

Vigor2862LVac,

Vigor2862LFac, Vigor2862LgVac, Vigor2862LgFac, Vigor2862LgFVac, Vigor2862LgFVac,

Vigor2862BLgVac, Vigor2862BLgFVac, Vigor2926Lac,

Vigor2926LVac, Vigor2926LFac, Vigor2926LgVac, Vigor2926LgFac, Vigor2926LgFVac,

Vigor2926LgFVac, Vigor2860Lac, Vigor2860LVac, Vigor2860LFac,

Vigor2860LgVac, Vigor2860LgFac, Vigor2860LgFVac,

Vigor2860BLgVac, Vigor2860BLgFVac, Vigor2925Lac,

Vigor2925LVac, Vigor2925LFac, Vigor2925LgVac, Vigor2925LgFac,

Vigor2925LgFVac, Vigor2862ac, Vigor2862Vac, Vigor2862Fac,

Vigor2862FVac, Vigor2926ac, Vigor2926Vac, Vigor2926Fac, Vigor2926FVac,

Vigor2860ac, Vigor2860Vac, Vigor2860Fac, Vigor2860FVac, Vigor2925ac,

Vigor2925Vac, Vigor2925Fa, Vigor2925FVac are electrically identical with the same

electromagnetic emissions and electromagnetic compatibility characteristics as model:

Vigor2862BLgFVac tested by BACL, the results of which are featured in BACL project:

RTWA170214001.

A description of the differences between the tested model and those that are declared similar are as follows:

2862 ,2860 ,2832,has dsl function

2926 ,2925 didn't has dsl function

2862 ,2860 ,2832 for different marketing

2926 ,2925 for different marketing

ac 2.4G Wi-fi function and 5G Wi-fi function
F Fiber function
V VoIP function
L LTE function
B Bonding VDSL function
g GPS function

Please contact me should there be need for any additional clarification or information.

Best Regards,



Abbott Yu/ HW manager

No. 26, Fu Shing Rd., Hukou County, Hsinchu Industrial Park, Hsinchu 303 Taiwan