


INTERTEK TESTING SERVICE

Report No.: 14010330HKG-005

Equipment Photographs

Model: ARSWP1

(Internal)



FCC ID:VIX-ARSWP1
IC:342H-ARSWP1



INTERTEK TESTING SERVICE

Report No.: 14010330HKG-005

Equipment Photographs

Model: ARSWP1

(Internal)



FCC ID: VIX-ARSWP1
IC: 342H-ARSWP1



INTERTEK TESTING SERVICE

Report No.: 14010330HKG-005

Equipment Photographs

Model: ARSWP1

(Internal)



FCC ID:VIX-ARSWP1
IC:342H-ARSWP1



INTERTEK TESTING SERVICE

Report No.: 14010330HKG-005

Equipment Photographs

Model: ARSWP1

(Internal)



FCC ID:VIX-ARSWP1
IC:342H-ARSWP1



INTERTEK TESTING SERVICE

Report No.: 14010330HKG-005

Equipment Photographs

Model: ARSWP1

(Internal)



FCC ID:VIX-ARSWP1
IC:342H-ARSWP1



INTERTEK TESTING SERVICE

Report No.: 14010330HKG-005

Equipment Photographs

Model: ARSWP1

(Internal)



FCC ID: VIX-ARSWP1
IC: 342H-ARSWP1

INTERTEK TESTING SERVICE

Report No.: 14010330HKG-005

Equipment Photographs

Model: ARSWP1

(Internal)



FCC ID:VIX-ARSWP1
IC:342H-ARSWP1

INTERTEK TESTING SERVICE

Report No.: 14010330HKG-005

Equipment Photographs

Model: ARSWP1

(Internal)



FCC ID:VIX-ARSWP1
IC:342H-ARSWP1