



INTERTEK TESTING SERVICE

Report No.: 14010330HKG-001

Equipment Photographs

Model: WPBT1

(Internal)



FCC ID:VIX-WPBT1
IC:342H-WPBT1


INTERTEK TESTING SERVICE

Report No.: 14010330HKG-001

Equipment Photographs

Model: WPBT1

(Internal)



FCC ID:VIX-WPBT1
IC:342H-WPBT1


INTERTEK TESTING SERVICE

Report No.: 14010330HKG-001

Equipment Photographs

Model: WPBT1

(Internal)



FCC ID:VIX-WPBT1
IC:342H-WPBT1


INTERTEK TESTING SERVICE

Report No.: 14010330HKG-001

Equipment Photographs

Model: WPBT1

(Internal)



FCC ID:VIX-WPBT1
IC:342H-WPBT1



INTERTEK TESTING SERVICE

Report No.: 14010330HKG-001

Equipment Photographs

Model: WPBT1

(Internal)



FCC ID:VIX-WPBT1
IC:342H-WPBT1


INTERTEK TESTING SERVICE

Report No.: 14010330HKG-001

Equipment Photographs

Model: WPBT1

(Internal)



FCC ID:VIX-WPBT1
IC:342H-WPBT1