

BINATONE TELECOM PLC

1 Apsley Way London NW2 7HF, United Kingdom.
Tel: +44(0) 20 8955 2700 Fax: +44(0) 20 8344 8877
e-mail: binatoneuk@binatonetelecom.co.uk



18 Sept, 2017

Application for Permissive Change of FCC ID: VLJ-MBP38SBU, IC : 4522A-MBP38SBU

Dear Sir/Madam:

The purpose of this document is to describe all the changes made on the certified transmitter with FCC ID: VLJ-MBP38SBU, IC: 4522A-MBP38SBU

Modification:

- Replace the CMOS sensor IC in the Camera.
- There is a minor change in the PCB layout of the Camera to fit the new CMOS sensor IC.
- Change the value of the de-coupling capacitors at CMOS signal.
- Remove the ferrite bead on the AC-DC adaptor.

Similarities between the certified equipment :

- No change in the RF part. RF IC, RF circuit, PCB layout of the RF circuit, RF Antennas are identical to the certified equipment.
- MCU are identical to the certified equipment.
- Functionality and intended usage are identical to the certified equipment.
- Outlook is identical to the certified equipment.
- Rating is identical to the certified equipment.

Sincerely,

A handwritten signature in black ink, appearing to read "KH Mueller", with a long horizontal stroke extending to the right.

(Grantee contact signature)

Name: Karl Heinz Mueller
Title: Chief Technical Officer