

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

Worst Case Position
Antenna (Horizontal: Z-axis/ Vertical:Z-axis)


X-axis



Y-axis




Z-axis




Worst Case Position
Module (Horizontal: X-axis/ Vertical:X-axis)


X-axis




Y-axis



Z-axis



Worst Case Position



30 mm Antenna (Worst)



300 mm Antenna

End of Report