

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


Worst Case Position

Below 1GHz (Horizontal: X-axis/ Vertical: X-axis)


1 – 10 GHz (Horizontal: X-axis/ Vertical: X-axis)

Above 10 GHz (Horizontal: Y-axis/ Vertical: Z-axis)


X-axis



Y-axis



Z-axis



End of Report