

21/11/18

Federal Communication Commission
Equipment Authorization Division, Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21048

Certification and Engineering Bureau
Industry Canada
Spectrum Engineering Branch
3701 Carling Avenue, Building 94
Ottawa, Ontario K2H 8S2

PCII Request / Re-assessment

PMN on original listing: RMI, FCC ID: *W4G-RMI6* granted on 2017-10-25
and IC: *8167A-RMI6* granted on 2017-10-25

TO WHOM IT MAY CONCERN

Pursuant to CFR § 2.1043 and RSP-100, Profoto Aktiebolag hereby requests a
Permissive Change Class II / Re-assessment.

Reason:

Modifications:

- no hardware changes
- the reason for the request is that the test software first used during certification testing contained a software bug which has been solved. The new software lowers the average output power only relevant for DSSS-Hopping (High Power Mode).


Profoto Aktiebolag
Box 1264 Landsvägen 57
SE-172 25 Sundbyberg
Sweden
Phone +46 (0) 8 447 53 00
Fax +46 (0) 8 447 53 20
www.profoto.com

 **Profoto**[®]
The light shaping company™

The following new exhibits will be uploaded:

- Test report on radiated measurements (DSS Equipment Class)
- RF Exposure Info
- External Photos, ...

Sincerely,



Tobias Lindbäck, VP Technology
Profoto Aktiebolag
Box 1264, 172 25 Sundbyberg, Sweden
Telephone: +46-70 526 9413



Profoto Aktiebolag
Box 1264 Landsvägen 57
SE-172 25 Sundbyberg
Sweden
Phone +46 (0) 8 447 53 00
Fax +46 (0) 8 447 53 20
www.profoto.com

 **Profoto**[®]
The light shaping company[™]