



SOLiD, Inc.

10,9th Floor, SOLiD Space 220 Pangyoyeok-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, Korea 463-400

Tel : +82-31-627-6290 Fax : +82-31-627-6209

Date : June 25, 2014

Federal Communications Commission
Authorization & Evaluation Division
7345 Oakland Mills Road
Columbia, Maryland 21046

To Whom It May Concern:

According to KDB 935210 D02, Part 90 Signal Booster
we as manufacturer, SOLiD declare that the warning below:

Part 90 Signal Boosters

WARNING. This is **NOT** a **CONSUMER** device. It is designed for installation by **FCC LICENSEES** and **QUALIFIED INSTALLERS**. You **MUST** have an **FCC LICENSE** or express consent of an FCC Licensee to operate this device. You **MUST** register Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.

Can be seen at:

- Product itself as label
- Packaging as label
- Manual
- All other electronic media where customer has access

A handwritten signature in black ink, reading "Kang-Yeob Bae". The signature is fluid and cursive, with the first letters of each name being capitalized and prominent.

Mr. Kang-Yeob, Bae / Director

SOLiD, Inc.