

SOLiD

nGENESIS FCC Label_Phoenix

Phoenix 개발팀

Rev No.	Data	Page	변경 내용	비고
V0.1	26.01.13		초안	
V0.2	26.02.04		Rainproof 추가 및 오타 수정	

nHRFM 명판 통합건 검토 (1/2)

대 외 비

NAME PLATE

한국 생산

Product : SOLiD GENESIS®

Model : nHRFM_7L

FCC ID : W6UNHRFM7L

Made in KOREA

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_8C

FCC ID : W6UNHRFM8C

Made in KOREA

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_17

FCC ID : W6UNHRFM17

Made in KOREA

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_19

FCC ID : W6UNHRFM19

Made in KOREA

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_23

FCC ID : W6UNHRFM23

Made in KOREA

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_25

FCC ID : W6UNHRFM25

Made in KOREA

 SOLiD, Inc

베트남 생산

Product : SOLiD GENESIS®

Model : nHRFM_7L

FCC ID : W6UNHRFM7L

Made in Vietnam

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_8C

FCC ID : W6UNHRFM8C

Made in Vietnam

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_17

FCC ID : W6UNHRFM17

Made in Vietnam

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_19

FCC ID : W6UNHRFM19

Made in Vietnam

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_23

FCC ID : W6UNHRFM23

Made in Vietnam

 SOLiD, Inc

Product : SOLiD GENESIS®

Model : nHRFM_25

FCC ID : W6UNHRFM25

Made in Vietnam

 SOLiD, Inc

nHRFM 명판 통합건 검토 (2/2)

대 외 비

NAME PLATE

한국 생산

Product : SOLiD GENESIS®

Model : nHRFM_34

FCC ID : W6UNHRFM34

Made in KOREA



Product : SOLiD GENESIS®

Model : nHRFM_40-20W

FCC ID : W6UNHRFM40-20W

Made in KOREA



Product : SOLiD GENESIS®

Model : nHRFM_40-40W

FCC ID : W6UNHRFM40-40W

Made in KOREA



베트남 생산

Product : SOLiD GENESIS®

Model : nHRFM_34

FCC ID : W6UNHRFM34

Made in Vietnam



Product : SOLiD GENESIS®

Model : nHRFM_40-20W

FCC ID : W6UNHRFM40-20W

Made in Vietnam



Product : SOLiD GENESIS®

Model : nHRFM_40-40W


FCC ID : W6UNHRFM40-40W

Made in Vietnam




nHRFM 명판 부착 위치 예시


대 외 비



(nHRFM_17,19,23)



(nHRFM_7L,8C,25,34,40)



	FCC 선언 문구 부착위치	FCC WARNING 문구
nHRFM_17, 19, 23, 25, 34, 40	This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC licensee to operate this device. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.	
nHRFM_7L, 8C	This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. Part 90 and Part 20 Signal Boosters THIS IS A 90.219 CLASS B DEVICE WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC licensee to operate this device. You MUST register, <u>Part 90</u> Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.	

The label attachment using permanent adhesive.
 The label will neither peel off nor fade during the expected lifespan.



FCC WARNING 문구

Sub-Band	Model Name	FCC WARNING 문구 (Band 구분 있음)
7L	nLRFM_7L nMRFM_7L nHRFM_7L	Part 90 and Part 20 Signal Boosters THIS IS A 90.219 CLASS B DEVICE WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Part 90 Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.
8C	nLRFM_8C nMRFM_8C nHRFM_8C	
17	nLRFM_17 nMRFM_17 nHRFM_17	WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.
19	nLRFM_19 nMRFM_19 nHRFM_19	
23	nLRFM_23 nMRFM_23 nHRFM_23	
25	nLRFM_25 nMRFM_25 nHRFM_25	
34	nLRFM_34 nMRFM_34 nHRFM_34	
40	nLRFM_40 nMRFM_40 nHRFM_40	

FCC선언 문구

Sub-Band	Model Name	FCC WARNING 문구 (Band 구분 없음)
7L	nLRFM_7L nMRFM_7L nHRFM_7L	This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.
8C	nLRFM_8C nMRFM_8C nHRFM_8C	
17	nLRFM_17 nMRFM_17 nHRFM_17	
19	nLRFM_19 nMRFM_19 nHRFM_19	
23	nLRFM_23 nMRFM_23 nHRFM_23	
25	nLRFM_25 nMRFM_25 nHRFM_25	
34	nLRFM_34 nMRFM_34 nHRFM_34	
40	nLRFM_40 nMRFM_40 nHRFM_40	

THANK YOU!

