



10. SETUP PHOTOS


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)




Reader powered with external 24VDC Supply




Reader powered with PoE adapter

RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)




Reader powered with external 24VDC Supply. For PoE the external supply is removed and power is applied via ethernet.

RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)




Reader powered with external 24VDC Supply



Reader powered with PoE adapter

RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)



Reader powered with external 24VDC Supply. For PoE the external supply is removed and power is applied via ethernet.

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



END OF REPORT