

### **APPENDIX 3: Photographs of test setup**

#### **Radiated Emission** **Below 1GHz**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

**Radiated Emission**  
**Above 1GHz**



**Photo 1**



**Photo 2**

**Worst case position**

**Below 1GHz**

Horizontal: X-axis / Vertical: Y-axis

**Above 1GHz**

Horizontal: X-axis / Vertical: Y-axis

**X-axis**



**Y-axis**



**Z-axis**



---

**UL Japan, Inc.**


**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

**Worst case position**



**Antenna OUT (Worst)**



**Antenna IN**

**End of Report**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124