


8. PHOTOGRAPHS OF MEASUREMENT



Note :

1.EUT: Slave ; 2.Master: AP