















ANT1_802.11ac_VHT20_UNII 2C






ANT1_802.11ac_VHT20_UNII 3






ANT2_802.11ac_VHT20_UNII 1






ANT2_802.11ac_VHT20_UNII 2A






ANT2_802.11ac_VHT20_UNII 2C






ANT2_802.11ac_VHT20_UNII 3






ANT3_802.11ac_VHT20_UNII 1






ANT3_802.11ac_VHT20_UNII 2A






ANT3_802.11ac_VHT20_UNII 2C






ANT3_802.11ac_VHT20_UNII 3






ANT4_802.11ac_VHT20_UNII 1





ANT4_802.11ac_VHT20_UNII 2A





ANT4_802.11ac_VHT20_UNII 2C






ANT4_802.11ac_VHT20_UNII 3



ANT1_802.11n_HT40_UNII 1



ANT1_802.11n_HT40_UNII 2A





ANT1_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (168) / (250) Pages






ANT1_802.11n_HT40_UNII 3



ANT2_802.11n_HT40_UNII 1



ANT2_802.11n_HT40_UNII 2A





ANT2_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (170) / (250) Pages






ANT2_802.11n_HT40_UNII 3



ANT3_802.11n_HT40_UNII 1



ANT3_802.11n_HT40_UNII 2A





ANT3_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (172) / (250) Pages






ANT3_802.11n_HT40_UNII 3



ANT4_802.11n_HT40_UNII 1



ANT4_802.11n_HT40_UNII 2A





ANT4_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (174) / (250) Pages





ANT4_802.11n_HT40_UNII 3




ANT1_802.11ac_VHT40_UNII 1



ANT1_802.11ac_VHT40_UNII 2A



ANT1_802.11ac_VHT40_UNII 2C





ANT1_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (176) / (250) Pages






ANT1_802.11ac_VHT40_UNII 3



ANT2_802.11ac_VHT40_UNII 1



ANT2_802.11ac_VHT40_UNII 2A





ANT2_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (178) / (250) Pages





ANT2_802.11ac_VHT40_UNII 3




ANT3_802.11ac_VHT40_UNII 1



ANT3_802.11ac_VHT40_UNII 2A



ANT3_802.11ac_VHT40_UNII 2C





ANT3_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (180) / (250) Pages






ANT3_802.11ac_VHT40_UNII 3



ANT4_802.11ac_VHT40_UNII 1



ANT4_802.11ac_VHT40_UNII 2A





ANT4_802.11ac_VHT40_UNII 2C




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2021-00840
Page (182) / (250) Pages





ANT4_802.11ac_VHT40_UNII 3




ANT1_802.11ac_VHT80_UNII 1




ANT1_802.11ac_VHT80_UNII 2A




ANT1_802.11ac_VHT80_UNII 2C





ANT1_802.11ac_VHT80_UNII 3




ANT2_802.11ac_VHT80_UNII 1




ANT2_802.11ac_VHT80_UNII 2A




ANT2_802.11ac_VHT80_UNII 2C





ANT2_802.11ac_VHT80_UNII 3




ANT3_802.11ac_VHT80_UNII 1




ANT3_802.11ac_VHT80_UNII 2A




ANT3_802.11ac_VHT80_UNII 2C





ANT3_802.11ac_VHT80_UNII 3




ANT4_802.11ac_VHT80_UNII 1



ANT4_802.11ac_VHT80_UNII 2A



ANT4_802.11ac_VHT80_UNII 2C



ANT4_802.11ac_VHT80_UNII 3