












ANT1_802.11ax_HE20_26T_UNII 1




ANT1_802.11ax_HE20_26T_UNII 2A






ANT1_802.11ax_HE20_26T_UNII 2C





ANT1_802.11ax_HE20_26T_UNII 3











ANT2_802.11ax_HE20_26T_UNII 1






ANT2_802.11ax_HE20_26T_UNII 2A






ANT2_802.11ax_HE20_26T_UNII 2C







ANT2_802.11ax_HE20_26T_UNII 3






ANT1_802.11ax_HE20_242T_UNII 1






ANT1_802.11ax_HE20_242T_UNII 2A






ANT1_802.11ax_HE20_242T_UNII 2C







ANT1_802.11ax_HE20_242T_UNII 3






ANT2_802.11ax_HE20_242T_UNII 1





ANT2_802.11ax_HE20_242T_UNII 2A





ANT2_802.11ax_HE20_242T_UNII 2C







ANT2_802.11ax_HE20_242T_UNII 3



ANT1_802.11n_HT40_UNII 1



ANT1_802.11n_HT40_UNII 2A





ANT1_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2022-03105
Page (134) / (281) Pages







ANT1_802.11n_HT40_UNII 3



ANT2_802.11n_HT40_UNII 1



ANT2_802.11n_HT40_UNII 2A





ANT2_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2022-03105
Page (136) / (281) Pages







ANT2_802.11n_HT40_UNII 3



ANT1_802.11ac_VHT40_UNII 1



ANT1_802.11ac_VHT40_UNII 2A





ANT1_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2022-03105
Page (138) / (281) Pages







ANT1_802.11ac_VHT40_UNII 3



ANT2_802.11ac_VHT40_UNII 1



ANT2_802.11ac_VHT40_UNII 2A





ANT2_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2022-03105
Page (140) / (281) Pages







ANT2_802.11ac_VHT40_UNII 3



ANT1_802.11ax_HE40_26T_UNII 1



ANT1_802.11ax_HE40_26T_UNII 2A





ANT1_802.11ax_HE40_26T_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2022-03105
Page (142) / (281) Pages







ANT1_802.11ax_HE40_26T_UNII 3



ANT2_802.11ax_HE40_26T_UNII 1



ANT2_802.11ax_HE40_26T_UNII 2A





ANT2_802.11ax_HE40_26T_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2022-03105
Page (144) / (281) Pages







ANT2_802.11ax_HE40_26T_UNII 3



ANT1_802.11ax_HE40_484T_UNII 1



ANT1_802.11ax_HE40_484T_UNII 2A





ANT1_802.11ax_HE40_484T_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2022-03105
Page (146) / (281) Pages







ANT1_802.11ax_HE40_484T_UNII 3



ANT2_802.11ax_HE40_484T_UNII 1



ANT2_802.11ax_HE40_484T_UNII 2A





ANT2_802.11ax_HE40_484T_UNII 2C




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2022-03105
Page (148) / (281) Pages





ANT2_802.11ax_HE40_484T_UNII 3




ANT1_802.11ac_VHT80_UNII 1




ANT1_802.11ac_VHT80_UNII 2A




ANT1_802.11ac_VHT80_UNII 2C




ANT1_802.11ac_VHT80_UNII 2C





ANT1_802.11ac_VHT80_UNII 3




ANT2_802.11ac_VHT80_UNII 1




ANT2_802.11ac_VHT80_UNII 2A




ANT2_802.11ac_VHT80_UNII 2C




ANT2_802.11ac_VHT80_UNII 2C





ANT2_802.11ac_VHT80_UNII 3





ANT1_802.11ax_HE80_26T_UNII 1



ANT1_802.11ax_HE80_26T_UNII 2A




ANT1_802.11ax_HE80_26T_UNII 2C




ANT1_802.11ax_HE80_26T_UNII 2C



ANT1_802.11ax_HE80_26T_UNII 3




ANT2_802.11ax_HE80_26T_UNII 1




ANT2_802.11ax_HE80_26T_UNII 2A



ANT2_802.11ax_HE80_26T_UNII 2C



ANT2_802.11ax_HE80_26T_UNII 2C



ANT2_802.11ax_HE80_26T_UNII 3