SYM.	ITEM OR PARTS NO	NAME	QTY.	MATERIAL & SIZE	TREATMENT	REMARK



ECE BASE

1. Model No.
2. Dialog Name
3. LU (ZB number/ZGS)
4. Diag ID
5. HW (HW number/ZGS)
6. HW
7. SW (SW number/ZGS)
8. SW
9. SW (SW number/ZGS)
10. SW
11. SW (SW number/ZGS)
12. SW
13. Q Status
14. Sales Code
15. Daimler serial number
16. HW sample level
17. SW sample level
18. Date of manufacture in format yyyy/mm/dd
19. QR code: LU number in format: A xxx xxx xx xx



ECE CD



USA

Notes
1.PLEASE SEE OTHER SHEET FOR THE CONTENTS WHICH ARE NUMBERED
(File:FROM_TGW_Parts No List)
(Sheet:Printing Instruction)
2.FOLLOWING FRAME SHOULD NOT PRINTED
(Shows reference position)

3.LASER CAUTION FRAME SHOULD FOLLOW THE FOLLOWING DIMENSIONS:



SYM.	DATE	REVISION	SIGN	CHECKED
3				
2				
1				

SYM.	ITEM OR PARTS NO.	NAME	QTY.	MATERIAL & SIZE	TREATMENT	REMARK

UNIT:MM

THIRD ANGLE SYSTEM

MATERIAL & SIZE		PROCESS		REMARK		
SCALE	DESIGN	DRAWN	CHECKED			APPROVED
1:1	R.Plasencia 24.10.2016	R.Plasencia 24.10.2016				

TYPE	NTG5 Star 2
DWG NAME	Main Label
DWG OR PART NO.	Printing for BT certification/K00
REF. NO.	

Panasonic Automotive Systems Europe Czech Enginnering Office

Label location