






22 Raise leg (D) and attach cable manager bracket (D1) as shown




23 Attached cap (D3) as shown







24 Slide hinges (M1) onto lid (M) as shown





25 Insert hinges (M1) into slots (M) as shown



26 Install hinge brackets (M2) with bushings (M4) as shown



27 Install springs (N1), screen brackets (N2), and bag hook (N3) as shown




28 Install leg cover (P) as shown


(S1)




#10 x 1" Pan Head Screw




29 Install cable manager (S) as shown



NOTE: Organize cables using the space behind the cable manager (S).




30 Install screens (R) to desk and tighten nuts to secure as shown




31 Install springs (N1) to the bottom of the left and right screens (P) as shown


NOTE: Slowly pull on spring assemblies (N1) when attaching to screens (P). **DO NOT** over extend.




32 Cut two mesh sleeves (Q) at 36" in length as shown




33 Wrap monitor power cord (J) and USB extention cable (Q3) with mesh sleeve (Q) as shown




34 Route power cord (J) and USB (Q3) and secure as shown



35 Route power cord (J) and USB cable (Q3) as shown



36 Install door (U1) as shown




HAWORTH

Myti


Assembly Instructions

Customer Supplied Accessories for Height Adjustable Workstation





1 Remove all zip ties (D5) and save as shown



NOTE: Zip ties (D5) are reusable.
DO NOT cut zip ties. Remove and save them for later use.




2 Remove cap (D3) as shown




Remove monitor tilt (D1) and remove monitor bracket (D2) as shown





4 Install monitor bracket (D2) as shown




5 Install monitor tilt (D1) as shown







6 Install camera (W) as shown




7 Route USB-C cable (Y) and insert mesh sleeve (Q) as shown




8 Install monitor tilt (D1) and install monitor cap (D3) as shown



9 Tilt monitor (W) as shown




10 Route and secure cabling as shown here and on the next page



11 Organize cables with a zip tie (D5) as shown

NOTE: The coloring shown is for clarity only.

NOTE: The image shown is for reference only. Plug locations will vary.



12 Install wireless charger (Z) and secure cables as shown

