

4.6 Photos of Radiation Measuring Setup

Adapter1:STD-05010U



Adapter2:HK-UA-050A 10-US



5.6 Photos of Conduction Measuring Setup

Adaptor1:STD-05010U



Adaptor2:HK-UA-050A100-US

