

INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)



FCC ID: XCY15204UMI15

IC: 8345A-15204UMI


INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)



FCC ID: XCY15204UMI15

IC: 8345A-15204UMI



INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)



FCC ID: XCY15204UMI15

IC: 8345A-15204UMI


INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)



FCC ID: XCY15204UMI15

IC: 8345A-15204UMI

INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)



FCC ID: XCY15204UMI15

IC: 8345A-15204UMI


INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)



FCC ID: XCY15204UMI15

IC: 8345A-15204UMI

INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)



FCC ID: XCY15204UMI15

IC: 8345A-15204UMI

INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)



FCC ID: XCY15204UMI15

IC: 8345A-15204UMI


INTERTEK TESTING SERVICE

Report No.: 15041705HKG-001

Equipment Photographs

Model : 15204

(Internal)



FCC ID: XCY15204UMI15

IC: 8345A-15204UMI