



Please refer to following plots:

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 18.NOV.2022 17:29:38

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 18.NOV.2022 17:29:53

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 18.NOV.2022 17:30:15

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 18.NOV.2022 17:30:33

Band 7_5 MHz_High_QPSK_RB25#0




Date: 18.NOV.2022 17:30:52

Band 7_5 MHz_High_16QAM_RB25#0




Date: 18.NOV.2022 17:31:13

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 18.NOV.2022 18:14:53

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 18.NOV.2022 18:15:12

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 18.NOV.2022 18:15:31

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 18.NOV.2022 18:15:50

Band 7_10 MHz_High_QPSK_RB50#0




Date: 18.NOV.2022 18:16:16

Band 7_10 MHz_High_16QAM_RB50#0




Date: 18.NOV.2022 18:16:38

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 18.NOV.2022 18:17:36

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 18.NOV.2022 18:18:00

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 18.NOV.2022 18:18:22

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 18.NOV.2022 18:18:43

Band 7_15 MHz_High_QPSK_RB75#0




Date: 18.NOV.2022 18:19:05

Band 7_15 MHz_High_16QAM_RB75#0




Date: 18.NOV.2022 18:19:29

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 18.NOV.2022 18:20:26

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 18.NOV.2022 18:20:48

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 18.NOV.2022 18:21:07

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 18.NOV.2022 18:21:32

Band 7_20 MHz_High_QPSK_RB100#0




Date: 18.NOV.2022 18:21:51

Band 7_20 MHz_High_16QAM_RB100#0




Date: 18.NOV.2022 18:24:28

Band 14_5 MHz_Low_QPSK_RB25#0




Date: 12.NOV.2022 18:24:50

Band 14_5 MHz_Low_16QAM_RB25#0




Date: 12.NOV.2022 18:25:11

Band 14_5 MHz_Middle_QPSK_RB25#0




Date: 12.NOV.2022 18:25:28

Band 14_5 MHz_Middle_16QAM_RB25#0




Date: 12.NOV.2022 18:25:51

Band 14_5 MHz_High_QPSK_RB25#0




Date: 12.NOV.2022 18:26:12

Band 14_5 MHz_High_16QAM_RB25#0




Date: 12.NOV.2022 18:26:32

Band 14_10 MHz_Middle_QPSK_RB50#0




Date: 12.NOV.2022 18:28:15

Band 14_10 MHz_Middle_16QAM_RB50#0




Date: 12.NOV.2022 18:28:35

Band 30_5 MHz_Low_QPSK_RB25#0




Date: 12.NOV.2022 18:29:03

Band 30_5 MHz_Low_16QAM_RB25#0




Date: 12.NOV.2022 18:29:19

Band 30_5 MHz_Middle_QPSK_RB25#0




Date: 12.NOV.2022 18:29:40

Band 30_5 MHz_Middle_16QAM_RB25#0




Date: 12.NOV.2022 18:30:00

Band 30_5 MHz_High_QPSK_RB25#0




Date: 12.NOV.2022 18:30:18

Band 30_5 MHz_High_16QAM_RB25#0




Date: 12.NOV.2022 18:30:38

Band 30_10 MHz_Middle_QPSK_RB50#0



Date: 13.DEC.2022 15:10:03

Band 30_10 MHz_Middle_16QAM_RB50#0



Date: 13.DEC.2022 15:13:37