


LI-ION RECHARGEABLE BATTERY PACK
LI-ION RECHARGEABLE BATTERY PACK
LI-ION RECHARGEABLE BATTERY PACK





02F248V10040
FT-181205
FUNCTION BOARD FOR K959 V1.00



LI-ION RECHARGEABLE BATTERY PACK
MODEL: DR-202W2
DC 10.8V 7800mAh 85Wh
CAUTION
ATTENTION





81Wh
Made in Taiwan
2 ft


LI-ION RECHARGEABLE BATTERY PACK
MODEL: DR-202W2
DC 10.8V 7500mAh 81Wh
Japone Technology Inc.
3ICR19/66-3
Made in Taiwan
CAUTION!
When damaged, replace only with the same or equivalent type of battery pack recommended by the manufacturer.
Do not attempt to open. Danger of explosion if battery is incorrectly placed near heat source or immerse in liquid.
Any misuse of battery pack could cause fire, explosion and personal injury.
ATTENTION
Maintenez la batterie éloignée de toute flamme. Évitez de la mettreen court-circuit.
N'essayez jamais de démonter la batterie. Utilisezles chargeurs prévus pour charger la batterie.
Risque d'explosion si la batterie est remplacée par un type incorrect.
Eliminez les batteries usagées conformément aux instructions.
警告！
電池損壞時,請更換與原廠規格相等的電池.
請勿打開電池外殼,且不要暴露於高溫、高熱處,不可放入液體中.
假如誤用可能會引起燃燒、爆炸或傷及人體.
Li-Ion
MH45563
JP1809130004






















D87U V1.10


0060EF2B95D9
0060EF2B95D8






Main
Aux
AW-CB304NF
WF MAC: D0C5D3AEEB79 B3H
BT MAC: D0C5D3AEEB78
S/N: H36Z013121
T11


B11


Realtek Model: RTL8821CE
FCC ID: TX2-RTL8821CE
IC: 6317A-RTL8821CE
CMIIT ID:2016AJ7893(M)
IFETEL: RCPRERT17-0354
Anatel: 06446-16-04076
CNC ID: C-17250
R-NZ
MSIP-CRM-RTK-RTL8821CE
CCAF16LP2410T3
CCAF16LP2411T5
R 201-163 301
T D16 0283 201
AzureWave Model: AW-CB304NF


TLA
AD4SSZ4GT2WB-FQGB
RoHS
4GB 260PIN DDR4-2400 201805000160001





CR2032
3V
25 2-2 26 2-3 27 2-4 28
4 5 6 7 8 9 70 1 2



25 2-2 26 2-3 27 2-4
4 5 6 7 8 9 70 1



TOSHIBA
DISK DRIVE MK3276GSX
HDD2J94 A SL01 T
DC+5V 1.0A DATE:22JUL2013
S/N 73MDCBV9T MT6 EC.A
8455MB (CYL16383,H16,S63)
320GB(LBA 625,142,448Sectors)
TOSHIBA CORPORATION
MADE IN PHILIPPINES
*DO NOT REMOVE ANY LABELS.
*DO NOT PUSH ON THE TOP COVER.
*RATTLE NOISE IS NORMAL.
*HANDLE ONLY BY SIDES OF BASE.
*AVOID GIVING SHOCK.
*DO NOT COVER BREATHING HOLE.


VOID WARRANTY IF SEAL BROKEN
001X01001
TOSHIBA
D26623









27 18
2 ft
2-1
25
2-2
26
2-3
1
2
3
4
5
6
7
8



HIT-5420-82350-2








PWR BUT\DUAL COLORS
FT-180820 V1.00
LED1
LED2



CN1
DOOR_SW
C2
02F244V10020
FT-180820
P070
BATTERY DOOR SENSOR
BOARD V1.00



E199875
Q2
C1



02P014V10040-
FT-120220
LED DRIVER BOARD V1.00
MADE IN TAIWAN



S401210185
NO:52P014V10000-G








T005V0
SUNON
ANT MB
V1.00C
ANT-001
ANT-002
ANT-011
ANT-012


L1
C6
L2
CN1
C1
C2
C3
C5
C4
SUNON
V1.00C


SUNION
MD-150M
V3.10A
HYCOM
HY30
TO15VO



FQC5
PASSED
QC
OK
MD-150M V3.13
R180725086



30
2-7
31
2-8
32
2-9
80






2-8
32
2-9
33
2-10
80
1
2
3
4
5







6PN>215B>703
CA434875
6PN>215B>703
CA434875
M215HGE-L21 Rev. C4
CHIMEI INNOLUX
04C4CYJ6BQ8001E
VIRO
RoHS
ZB
MADE IN CHINA
CML5E21DYYSCYNPC6BO008M


Don't
0407_V00
216PCT10A2280012
P/N:216PCT10A2
E89221 80928Q012




HD-1
94V-0
E355345
1829
AG5020B27-1.0


IDTECH MiniSmart II
Model:MINI2-50-F1 Rev.C
Firmware: V2.00.034
S/N:846T275171
RoHS
Country of Origin : Taiwan


H4 94V-0
44
G1846