






18:24:57 12.11.2023

Band2_5MHz_16QAM_18625_1RB#0_0.15~30_0.15~30




18:25:02 12.11.2023

Band2_5MHz_16QAM_18625_1RB#0_30~1000_30~1000




18:25:14 12.11.2023

Band2_5MHz_16QAM_18625_1RB#0_1000~3000_1000~3000
0




18:25:25 12.11.2023


Band2_5MHz_16QAM_18625_1RB#0_3000~20000_3000~2000
00




Band2_5MHz_QPSK_18900_1RB#0_0.009~0.15_0.009~0.15



Band2_5MHz_QPSK_18900_1RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_18900_1RB#0_1000~3000_1000~3000




Band2_5MHz_QPSK_18900_1RB#0_3000~20000_3000~2000

0




Band2_5MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.1


5



Band2_5MHz_16QAM_18900_1RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_19175_1RB#0_1000~3000_1000~3000




Band2_5MHz_QPSK_19175_1RB#0_3000~20000_3000~2000

0




Band2_5MHz_16QAM_19175_1RB#0_0.009~0.15_0.009~0.1


5




Band2_5MHz_16QAM_19175_1RB#0_0.15~30_0.15~30




Band2_5MHz_16QAM_19175_1RB#0_30~1000_30~1000




Band2_5MHz_16QAM_19175_1RB#0_1000~3000_1000~3000




Band2_5MHz_16QAM_19175_1RB#0_3000~20000_3000~20000




Band2_10MHz_QPSK_18650_1RB#0_0.009~0.15_0.009~0.15



Band2_10MHz_QPSK_18650_1RB#0_0.15~30_0.15~30




Band2_10MHz_QPSK_18650_1RB#0_30~1000_30~1000




Band2_10MHz_QPSK_18650_1RB#0_1000~3000_1000~3000

0




Band2_10MHz_QPSK_18650_1RB#0_3000~20000_3000~2000

00




Band2_3MHz_16QAM_18615_1RB#0_0.009~0.15_0.009~0.1


5




Band2_3MHz_16QAM_18615_1RB#0_0.15~30_0.15~30




Band2_3MHz_16QAM_18615_1RB#0_3000~20000_3000~20000




Band2_3MHz_QPSK_18900_1RB#0_0.009~0.15_0.009~0.15




Band2_3MHz_QPSK_18900_1RB#0_0.15~30_0.15~30




Band2_3MHz_QPSK_18900_1RB#0_30~1000_30~1000




Band2_3MHz_QPSK_18900_1RB#0_1000~3000_1000~3000




Band2_3MHz_16QAM_19185_1RB#0_0.009~0.15_0.009~0.15




Band2_3MHz_16QAM_19185_1RB#0_0.15~30_0.15~30




Band2_3MHz_16QAM_19185_1RB#0_30~1000_30~1000




Band2_5MHz_QPSK_18900_1RB#0_30~1000_30~1000




Band2_5MHz_16QAM_18900_1RB#0_30~1000_30~1000




Band2_5MHz_16QAM_18900_1RB#0_1000~3000_1000~3000
0




Band2_5MHz_16QAM_18900_1RB#0_3000~20000_3000~2000
00




Band2_5MHz_QPSK_19175_1RB#0_0.009~0.15_0.009~0.15




Band2_5MHz_QPSK_19175_1RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_19175_1RB#0_30~1000_30~1000




Band2_10MHz_16QAM_18650_1RB#0_0.009~0.15_0.009~0.1




Band2_10MHz_16QAM_18650_1RB#0_0.15~30_0.15~30




Band2_10MHz_16QAM_18650_1RB#0_30~1000_30~1000



Band2_10MHz_16QAM_18650_1RB#0_1000~3000_1000~30
00




Band2_10MHz_16QAM_18650_1RB#0_3000~20000_3000~20
000




Band2_10MHz_QPSK_18900_1RB#0_0.009~0.15_0.009~0.1


5




Band2_10MHz_QPSK_18900_1RB#0_0.15~30_0.15~30




Band2_10MHz_QPSK_18900_1RB#0_30~1000_30~1000




Band2_10MHz_QPSK_18900_1RB#0_1000~3000_1000~3000




Band2_10MHz_QPSK_18900_1RB#0_3000~20000_3000~20000




Band2_10MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.15



Band2_10MHz_16QAM_18900_1RB#0_0.15~30_0.15~30




Band2_10MHz_16QAM_18900_1RB#0_30~1000_30~1000



18:31:28 12.11.2023

Band2_10MHz_16QAM_18900_1RB#0_1000~3000_1000~30


00



18:31:40 12.11.2023

Band2_10MHz_16QAM_18900_1RB#0_3000~20000_3000~20


000



18:32:04 12.11.2023


Band2_10MHz_QPSK_19150_1RB#0_0.009~0.15_0.009~0.1

5




18:32:08 12.11.2023


Band2_10MHz_QPSK_19150_1RB#0_0.15~0.30_0.15~0.30




Band2_10MHz_QPSK_19150_1RB#0_30~1000_30~1000




Band2_10MHz_QPSK_19150_1RB#0_1000~3000_1000~3000



Band2_10MHz_QPSK_19150_1RB#0_3000~20000_3000~20000




Band2_10MHz_16QAM_19150_1RB#0_0.009~0.15_0.009~0.1




18:32:48 12.11.2023

Band2_10MHz_16QAM_19150_1RB#0_0.15~30_0.15~30




18:32:53 12.11.2023

Band2_10MHz_16QAM_19150_1RB#0_30~1000_30~1000




18:33:04 12.11.2023

Band2_10MHz_16QAM_19150_1RB#0_1000~3000_1000~30
00




18:33:16 12.11.2023

Band2_10MHz_16QAM_19150_1RB#0_3000~20000_3000~20
000




Band2_15MHz_QPSK_18675_1RB#0_0.009~0.15_0.009~0.1


5




Band2_15MHz_QPSK_18675_1RB#0_0.15~30_0.15~30




Band2_15MHz_QPSK_18675_1RB#0_30~1000_30~1000




Band2_15MHz_QPSK_18675_1RB#0_1000~3000_1000~3000




Band2_15MHz_QPSK_18675_1RB#0_3000~20000_3000~20000




Band2_15MHz_16QAM_18675_1RB#0_0.009~0.15_0.009~0.15



Band2_15MHz_16QAM_18675_1RB#0_0.15~30_0.15~30




Band2_15MHz_16QAM_18675_1RB#0_30~1000_30~1000



18:59:46 12.11.2023

Band2_15MHz_16QAM_18675_1RB#0_1000~3000_1000~3000


00



18:59:58 12.11.2023

Band2_15MHz_16QAM_18675_1RB#0_3000~20000_3000~20000


000



19:00:07 12.11.2023


Band2_15MHz_QPSK_18900_1RB#0_0.009~0.15_0.009~0.15

5




19:00:12 12.11.2023

Band2_15MHz_QPSK_18900_1RB#0_0.15~0.30_0.15~0.30




19:00:17 12.11.2023

Band2_15MHz_QPSK_18900_1RB#0_30~1000_30~1000




19:00:29 12.11.2023

Band2_15MHz_QPSK_18900_1RB#0_1000~3000_1000~3000



19:00:41 12.11.2023

Band2_15MHz_QPSK_18900_1RB#0_3000~20000_3000~20000



19:00:47 12.11.2023

Band2_15MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.1