






19:43:39 14.11.2023

Band66_1.4MHz_16QAM_132322_1RB#0_0.15~30_0.15~30




19:43:44 14.11.2023

Band66_1.4MHz_16QAM_132322_1RB#0_30~1000_30~1000




19:43:56 14.11.2023

Band66_1.4MHz_16QAM_132322_1RB#0_1000~3000_1000~3000




19:44:08 14.11.2023


Band66_1.4MHz_16QAM_132322_1RB#0_3000~20000_3000~20000




Band66_1.4MHz_QPSK_132665_1RB#0_0.009~0.15_0.009~0.15




Band66_1.4MHz_QPSK_132665_1RB#0_0.15~30_0.15~30




Band66_1.4MHz_QPSK_132665_1RB#0_30~1000_30~1000




Band66_1.4MHz_QPSK_132665_1RB#0_1000~3000_1000~3000




Band66_1.4MHz_QPSK_132665_1RB#0_3000~20000_3000~20000




Band66_1.4MHz_16QAM_132665_1RB#0_0.009~0.15_0.009~0.15




Band66_1.4MHz_16QAM_132665_1RB#0_0.15~30_0.15~30




Band66_1.4MHz_16QAM_132665_1RB#0_30~1000_30~1000




Band66_1.4MHz_16QAM_132665_1RB#0_1000~3000_1000
~3000




Band66_1.4MHz_16QAM_132665_1RB#0_3000~20000_3000
~20000




Band66_3MHz_QPSK_131987_1RB#0_0.009~0.15_0.009~0.15
15




Band66_3MHz_QPSK_131987_1RB#0_0.15~30_0.15~30




Band66_3MHz_QPSK_131987_1RB#0_30~1000_30~1000




Band66_3MHz_QPSK_131987_1RB#0_1000~3000_1000~300
0




Band66_3MHz_QPSK_131987_1RB#0_3000~20000_3000~2
0000




Band66_3MHz_16QAM_131987_1RB#0_0.009~0.15_0.009~0.
15




Band66_3MHz_16QAM_131987_1RB#0_0.15~30_0.15~30




Band66_3MHz_16QAM_131987_1RB#0_30~1000_30~1000



Band66_3MHz_16QAM_131987_1RB#0_1000~3000_1000~3000




Band66_3MHz_16QAM_131987_1RB#0_3000~20000_3000~20000




Band66_3MHz_QPSK_132322_1RB#0_0.009~0.15_0.009~0.


15



Band66_3MHz_QPSK_132322_1RB#0_0.15~30_0.15~30




Band66_3MHz_QPSK_132322_1RB#0_30~1000_30~1000




Band66_3MHz_QPSK_132322_1RB#0_1000~3000_1000~300


0




Band66_3MHz_QPSK_132322_1RB#0_3000~20000_3000~20000




Band66_3MHz_16QAM_132322_1RB#0_0.009~0.15_0.009~0.15




Band66_3MHz_16QAM_132322_1RB#0_0.15~30_0.15~30




Band66_3MHz_16QAM_132322_1RB#0_30~1000_30~1000




Band66_3MHz_16QAM_132322_1RB#0_1000~3000_1000~3000




Band66_3MHz_16QAM_132322_1RB#0_3000~20000_3000~20000




Band66_3MHz_QPSK_132657_1RB#0_0.009~0.15_0.009~0.15




Band66_3MHz_QPSK_132657_1RB#0_0.15~30_0.15~30




Band66_3MHz_QPSK_132657_1RB#0_30~1000_30~1000




Band66_3MHz_QPSK_132657_1RB#0_1000~3000_1000~300
0




Band66_3MHz_QPSK_132657_1RB#0_3000~20000_3000~2
0000




Band66_3MHz_16QAM_132657_1RB#0_0.009~0.15_0.009~0.
15




Band66_3MHz_16QAM_132657_1RB#0_0.15~30_0.15~30




Band66_3MHz_16QAM_132657_1RB#0_30~1000_30~1000



Band66_3MHz_16QAM_132657_1RB#0_1000~3000_1000~3000




Band66_3MHz_16QAM_132657_1RB#0_3000~20000_3000~20000




Band66_5MHz_QPSK_131997_1RB#0_0.009~0.15_0.009~0.


15



Band66_5MHz_QPSK_131997_1RB#0_0.15~30_0.15~30




Band66_5MHz_QPSK_131997_1RB#0_30~1000_30~1000




Band66_5MHz_QPSK_131997_1RB#0_1000~3000_1000~300


0




Band66_5MHz_QPSK_131997_1RB#0_3000~20000_3000~20000




Band66_5MHz_16QAM_131997_1RB#0_0.009~0.15_0.009~0.15




Band66_5MHz_16QAM_131997_1RB#0_0.15~30_0.15~30




Band66_5MHz_16QAM_131997_1RB#0_30~1000_30~1000




Band66_5MHz_16QAM_131997_1RB#0_1000~3000_1000~3000




Band66_5MHz_16QAM_131997_1RB#0_3000~20000_3000~20000



Band66_5MHz_QPSK_132322_1RB#0_0.009~0.15_0.009~0.15




Band66_5MHz_QPSK_132322_1RB#0_0.15~30_0.15~30




21:04:14 14.11.2023

Band66_5MHz_QPSK_132322_1RB#0_30~1000_30~1000




21:04:25 14.11.2023

Band66_5MHz_QPSK_132322_1RB#0_1000~3000_1000~300
0




21:04:37 14.11.2023

Band66_5MHz_QPSK_132322_1RB#0_3000~20000_3000~2
0000




21:04:43 14.11.2023

Band66_5MHz_16QAM_132322_1RB#0_0.009~0.15_0.009~0.
15




21:04:48 14.11.2023

Band66_5MHz_16QAM_132322_1RB#0_0.15~30_0.15~30




21:04:53 14.11.2023

Band66_5MHz_16QAM_132322_1RB#0_30~1000_30~1000




21:05:04 14.11.2023

Band66_5MHz_16QAM_132322_1RB#0_1000~3000_1000~3000




21:05:16 14.11.2023

Band66_5MHz_16QAM_132322_1RB#0_3000~20000_3000~20000




Band66_5MHz_QPSK_132647_1RB#0_0.009~0.15_0.009~0.


15



Band66_5MHz_QPSK_132647_1RB#0_0.15~30_0.15~30




Band66_5MHz_QPSK_132647_1RB#0_30~1000_30~1000




Band66_5MHz_QPSK_132647_1RB#0_1000~3000_1000~300


0




Band66_5MHz_QPSK_132647_1RB#0_3000~20000_3000~20000




Band66_5MHz_16QAM_132647_1RB#0_0.009~0.15_0.009~0.15



Band66_5MHz_16QAM_132647_1RB#0_0.15~30_0.15~30




Band66_5MHz_16QAM_132647_1RB#0_30~1000_30~1000




21:06:26 14.11.2023

Band66_5MHz_16QAM_132647_1RB#0_1000~3000_1000~3000




21:06:37 14.11.2023

Band66_5MHz_16QAM_132647_1RB#0_3000~20000_3000~20000




21:34:45 14.11.2023

Band66_10MHz_QPSK_132022_1RB#0_0.009~0.15_0.009~0.15




21:34:50 14.11.2023

Band66_10MHz_QPSK_132022_1RB#0_0.15~30_0.15~30




21:34:55 14.11.2023

Band66_10MHz_QPSK_132022_1RB#0_30~1000_30~1000




21:35:07 14.11.2023

Band66_10MHz_QPSK_132022_1RB#0_1000~3000_1000~3000
00




21:35:18 14.11.2023

Band66_10MHz_QPSK_132022_1RB#0_3000~20000_3000~20000
20000




21:35:24 14.11.2023

Band66_10MHz_16QAM_132022_1RB#0_0.009~0.15_0.009~0.15
0.15




21:35:29 14.11.2023

Band66_10MHz_16QAM_132022_1RB#0_0.15~30_0.15~30




21:35:34 14.11.2023

Band66_10MHz_16QAM_132022_1RB#0_30~1000_30~1000




21:35:46 14.11.2023

Band66_10MHz_16QAM_132022_1RB#0_1000~3000_1000~3000




21:35:58 14.11.2023


Band66_10MHz_16QAM_132022_1RB#0_3000~20000_3000~20000




Band66_10MHz_QPSK_132322_1RB#0_0.009~0.15_0.009~0.15




Band66_10MHz_QPSK_132322_1RB#0_0.15~30_0.15~30




Band66_10MHz_QPSK_132322_1RB#0_30~1000_30~1000




Band66_10MHz_QPSK_132322_1RB#0_1000~3000_1000~3000




Band66_10MHz_QPSK_132322_1RB#0_3000~20000_3000~20000




Band66_10MHz_16QAM_132322_1RB#0_0.009~0.15_0.009~0.15




Band66_10MHz_16QAM_132322_1RB#0_0.15~30_0.15~30




Band66_10MHz_16QAM_132322_1RB#0_30~1000_30~1000




Band66_10MHz_16QAM_132322_1RB#0_1000~3000_1000~3000




Band66_10MHz_16QAM_132322_1RB#0_3000~20000_3000~20000



Band66_10MHz_QPSK_132622_1RB#0_0.009~0.15_0.009~0.15




Band66_10MHz_QPSK_132622_1RB#0_0.15~30_0.15~30




21:37:53 14.11.2023

Band66_10MHz_QPSK_132622_1RB#0_30~1000_30~1000




21:38:05 14.11.2023

Band66_10MHz_QPSK_132622_1RB#0_1000~3000_1000~3000




21:38:17 14.11.2023

Band66_10MHz_QPSK_132622_1RB#0_3000~20000_3000~20000




21:38:23 14.11.2023

Band66_10MHz_16QAM_132622_1RB#0_0.009~0.15_0.009~0.15




21:38:28 14.11.2023

Band66_10MHz_16QAM_132622_1RB#0_0.15~30_0.15~30




21:38:32 14.11.2023

Band66_10MHz_16QAM_132622_1RB#0_30~1000_30~1000




21:38:44 14.11.2023

Band66_10MHz_16QAM_132622_1RB#0_1000~3000_1000~3000




21:38:56 14.11.2023

Band66_10MHz_16QAM_132622_1RB#0_3000~20000_3000~20000




22:06:17 14.11.2023

Band66_15MHz_QPSK_132047_1RB#0_0.009~0.15_0.009~0.15




22:06:22 14.11.2023

Band66_15MHz_QPSK_132047_1RB#0_0.15~30_0.15~30




22:06:27 14.11.2023

Band66_15MHz_QPSK_132047_1RB#0_30~1000_30~1000




22:06:38 14.11.2023


Band66_15MHz_QPSK_132047_1RB#0_1000~3000_1000~3000




Band66_15MHz_QPSK_132047_1RB#0_3000~20000_3000~20000




Band66_15MHz_16QAM_132047_1RB#0_0.009~0.15_0.009~0.15




Band66_15MHz_16QAM_132047_1RB#0_0.15~30_0.15~30




Band66_15MHz_16QAM_132047_1RB#0_30~1000_30~1000




Band66_15MHz_16QAM_132047_1RB#0_1000~3000_1000~3000




Band66_15MHz_16QAM_132047_1RB#0_3000~20000_3000~20000




Band66_15MHz_QPSK_132322_1RB#0_0.009~0.15_0.009~0.15




Band66_15MHz_QPSK_132322_1RB#0_0.15~30_0.15~30




Band66_15MHz_QPSK_132322_1RB#0_30~1000_30~1000



Band66_15MHz_QPSK_132322_1RB#0_1000~3000_1000~3000
00



Band66_15MHz_QPSK_132322_1RB#0_3000~20000_3000~20000



Band66_15MHz_16QAM_132322_1RB#0_0.009~0.15_0.009~0.15