

	Report No: R3392 Issue No: 1	FCC ID: XO9-MPF001-001 IC: 8906A -MPF01001	
	Test No: T5476	Test Report Photos File	Page: 1 of 3



dB Technology

|----- (Cambridge Ltd.) -----|

EMC
Testing

EMC
Consultancy

EMC
Training

23, Headington Drive,
Cambridge.
CB1 9HE
Tel : 01954 251974 (test site)
or : 01223 241140 (accounts)
Fax : 01954 251907
web : www.dbtechnology.co.uk
email: mail@dbtechnology.co.uk

Photos File For Test Report

Performed at:
TWENTY PENCE TEST SITE

**Twenty Pence Road,
Cottenham,
Cambridge
U.K.
CB24 8PS**

on

Sureflap Ltd

SureFeed

dated

22nd September 2014

Document History

Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	23/09/14		Initial release		

Based on report template:
v090319

*This report shall not be reproduced except in full, without the written approval of:
dB Technology (Cambridge) Ltd.*

	Report No: R3392 Issue No: 1	FCC ID: XO9-MPF001-001 IC: 8906A -MPF01001	
	Test No: T5476	Test Report Photos File	Page: 2 of 3



Photograph 1 Radiated Emissions - below 30MHz @10m




Photograph 2 Radiated Emissions - below 30MHz @10m

*This report shall not be reproduced except in full, without the written approval of:
dB Technology (Cambridge) Ltd.*

	Report No: R3392	FCC ID: XO9-MPF001-001 IC: 8906A -MPF01001	
	Issue No: 1		
Test No: T5476	Test Report Photos File		Page: 3 of 3



Photograph 3 Radiated Emissions - Carrier Extrapolation



Photograph 4 Radiated Emissions - above 30MHz

*This report shall not be reproduced except in full, without the written approval of:
dB Technology (Cambridge) Ltd.*