

March 23rd, 2026

WARNING LABELING ATTESTATION LETTER

FCC ID: XS5-H23437HP

Product Name: CAP H2 34T/37T

To whom it may concern,

With respect to FCC guideline KDB 935210 D02 "Signal Boosters Certification" v04r03, §IV, warning label messages will be also shown in online and point-of-sale marketing materials and on outside packaging of device.

Warning labelling information:

For Industrial Signal Boosters

WARNING. This is **NOT** a **CONSUMER** device. It is designed for installation by **FCC LICENSEES** and **QUALIFIED INSTALLERS**. You **MUST** have an **FCC LICENSE** or express consent of an FCC License to operate this device. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.

Sincerely,



Alexander Kopp

Senior Staff Engineer Compliance

Industriering 10

86675 Buchdorf, Germany