







DUT TFAH-ES70/80/50-17



Measurement Equipment



Test setup: Field Strength Emission <1 GHz @3m in the SAC



Test setup: Field Strength Emission >1 GHz @3m in the SAC