



tips: The processing techniques and materials must be certified by RoHS.

■ Pantone Black C

□ Pantone White C