



802.11n20_5745MHz_Chain 0




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 17:29:21

802.11n20_5745MHz_Chain 1




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 17:05:01

802.11n20_5785MHz_Chain 0




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 17:37:53

802.11n20_5785MHz_Chain 1




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 17:11:50

802.11n20_5825MHz_Chain 0




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 17:43:48

802.11n20_5825MHz_Chain 1




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 17:20:15

802.11n40_5755MHz_Chain 0




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 17:50:14

802.11n40_5755MHz_Chain 1




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 18:04:21

802.11n40_5795MHz_Chain 0




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 17:56:26

802.11n40_5795MHz_Chain 1




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 18:10:14

802.11ac80_5775MHz_Chain 0




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 21.OCT.2024 09:33:00

802.11ac80_5775MHz_Chain 1




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 21.OCT.2024 09:40:10


802.11ax20_5745MHz_RU_242/61_Chain 0




802.11ax20_5745MHz_RU_242/61_Chain 1




802.11ax20_5785MHz_RU_242/61_Chain 0




802.11ax20_5785MHz_RU_242/61_Chain 1




802.11ax20_5825MHz_RU_242/61_Chain 0




802.11ax20_5825MHz_RU_242/61_Chain 1




802.11ax40_5755MHz_RU_484/65_Chain 0




802.11ax40_5755MHz_RU_484/65_Chain 1




802.11ax40_5795MHz_RU_484/65_Chain 0




802.11ax40_5795MHz_RU_484/65_Chain 1



802.11ax80_5775MHz_RU_996/67_Chain 0




802.11ax80_5775MHz_RU_996/67_Chain 1




Duty Cycle

5150-5250MHz


802.11a_5200MHz_Chain 0
1.976ms,NAMs




802.11n20_5200MHz_Chain 0
5.424ms,NAMs




802.11n40_5190MHz_Chain 0
5.400ms,NAMs




802.11ac80_5210MHz_Chain 0
5.401ms,NAMs




802.11ax20_5200MHz_RU_242/61_Chain 0
5.436ms,NAMs



802.11ax40_5190MHz_RU_484/65_Chain 0
5.414ms,NAMs




802.11ax80_5210MHz_RU_996/67_Chain 0
5.406ms,NAmS




5250-5350MHz

802.11a_5280MHz_Chain 0
1.938ms,NAMs




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 22.OCT.2024 17:56:49

802.11n20_5280MHz_Chain 0
5.424ms,NAMs




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 23.OCT.2024 09:43:26

802.11n40_5270MHz_Chain 0
5.386ms,NAMs




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 23.OCT.2024 10:36:59

802.11ac80_5290MHz_Chain 0
5.358ms,NAMs




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 23.OCT.2024 13:22:09

802.11ac160_5250MHz_Chain 0
5.425ms,NAMs




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 30.OCT.2024 19:49:32

802.11ax20_5280MHz_RU_242/61_Chain 0
5.433ms,NAMs




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 23.OCT.2024 13:58:32

802.11ax40_5270MHz_RU_484/65_Chain 0
5.385ms,NAMs




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 23.OCT.2024 14:53:07

802.11ax80_5290MHz_RU_996/67_Chain 0
5.424ms,NAMs



ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 23.OCT.2024 15:49:27


802.11ax160_5250MHz_RU_2*996_Chain 0
5.382ms,NAMs



ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 23.OCT.2024 16:14:37


5470-5725MHz

802.11a_5580MHz_Chain 0
1.975ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 18.OCT.2024 09:37:19

802.11n20_5580MHz_Chain 0
5.426ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 18.OCT.2024 10:36:57

802.11n40_5550MHz_Chain 0
5.404ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 18.OCT.2024 14:39:46

802.11ac80_5530MHz_Chain 0
5.404ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 17.OCT.2024 14:14:14

802.11ac160_5570MHz_Chain 0
5.386ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 30.OCT.2024 20:32:28

802.11ax20_5580MHz_RU_242/61_Chain 0
5.087ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 18.OCT.2024 11:50:09

802.11ax40_5550MHz_RU_484/65_Chain 0
5.413ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 18.OCT.2024 16:06:46

802.11ax80_5530MHz_RU_996/67_Chain 0
5.385ms,NAmS



ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 14:50:58


802.11ax160_5570MHz_RU_2*996_Chain 0
5.362ms,NAmS



ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 15:47:43


5725-5850MHz

802.11a_5785MHz_Chain 0
1.974ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 16:13:31

802.11n20_5785MHz_Chain 0
5.358ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 16:14:45

802.11n40_5755MHz_Chain 0
5.361ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 16:16:45

802.11ac80_5775MHz_Chain 0
5.391ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 19.OCT.2024 16:18:24

802.11ax20_5785MHz_RU_242/61_Chain 0
5.439ms,NAmS




ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 21.OCT.2024 09:44:14

802.11ax40_5755MHz_RU_484/65_Chain 0
5.415ms,NAmS



ProjectNo.:2405X57681E-RF Tester:Ryan Zhang
Date: 21.OCT.2024 09:47:33

802.11ax80_5775MHz_RU_996/67_Chain 0
5.418ms,NAmS



Project: 2405X57681E-RF Tester: Ryan Zhang
Date: 21.OCT.2024 09:50:33

4 Test Setup Photo

Please refer to the attachment 2405X57681E Test Setup photo.

5 E.U.T Photo

Please refer to the attachment 2405X57681E External photo and 2405X57681E Internal photo.

---End of Report---