



Federal Communications Commission
Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, MD 21046

Subject: Class II Permissive Change Application for FCC ID: Y8K-CWS4

To Whom It May Concern,

We hereby request a Class II Permissive Change for FCC ID Y8K-CWS4 pursuant to FCC Rule Part 2.1043.


The modification concerns an update of the CWS4 hardware from version 4.1 to 4.6. The modifications consist of:

- replacement of the 100 μ F, 6.3 V bulk capacitor with a 1000 μ F, 10 V capacitor;
- removal of redundant components, including the fuse and certain pull-up resistors;
- replacement of the two LEDs with a single PLCC LED, maintaining the same red and green functionality; and
- minor component and PCB layout/routing modifications while maintaining the original functionality.

The PCB dimensions, housing, potting materials, antenna design, and antenna position remain unchanged.

We confirm that there are no changes to the fundamental frequency, output power, or RF characteristics, and that the device remains fully compliant with all applicable FCC rules.

Sincerely,


Guus Oostveen
14-9-2026

CowManager BV
Gerverscop 9
3481 LT Harmelen
The Netherlands
www.cowmanager.com
VAT: NL853405013B01
KvK: 59285273

