

433 MHz Version

315 MHz Version

Laser marking has to be checked for correct match of homologation numbers. 3

