






	
n41-PC3-30-80-M-16-N/A-N/A-N/A-CP-QPS K-Edge_1RB_Left-1@0-0.009-0.15--76.24--5 5-PASS	n41-PC3-30-80-M-16-N/A-N/A-N/A-CP-QPS K-Edge_1RB_Left-1@0-0.15-30--65.08--45-P ASS
	
n41-PC3-30-80-M-16-N/A-N/A-N/A-CP-QPS K-Edge_1RB_Left-1@0-30-1000--52.21--35- PASS	n41-PC3-30-80-M-16-N/A-N/A-N/A-CP-QPS K-Edge_1RB_Left-1@0-1000-3000--46.40--2 5-PASS

