






















	
n41-PC3-30-100-H-16-N/A-N/A-N/A-CP-QPS K-Edge_1RB_Left-1@0-0.009-0.15--76.16--5 5-PASS	n41-PC3-30-100-H-16-N/A-N/A-N/A-CP-QPS K-Edge_1RB_Left-1@0-0.15-30--64.97--45-P ASS
	
n41-PC3-30-100-H-16-N/A-N/A-N/A-CP-QPS K-Edge_1RB_Left-1@0-30-1000--52.80--35- PASS	n41A-PC3-30-100-H-16-N/A-N/A-N/A-CP-QP SK-Edge_1RB_Left-1@0-1000-3000--46.62-- 25-PASS

