B71_20M_16QAM_1@0_CH_133222




B71_20M_16QAM_100@0_CH_133222




B71_20M_QPSK_1@99_CH_133372




B71_20M_QPSK_100@0_CH_133372




B71_20M_16QAM_1@99_CH_133372




B71_20M_16QAM_100@0_CH_133372




B71_15M_QPSK_1@0_CH_133197




B71_15M_QPSK_75@0_CH_133197



B71_15M_16QAM_1@0_CH_133197




B71_15M_16QAM_75@0_CH_133197




B71_15M_QPSK_1@74_CH_133397




B71_15M_QPSK_75@0_CH_133397




B71_15M_16QAM_1@74_CH_133397




B71_15M_16QAM_75@0_CH_133397




B71_10M_QPSK_1@0_CH_133172




B71_10M_QPSK_50@0_CH_133172



B71_10M_16QAM_1@0_CH_133172




B71_10M_16QAM_50@0_CH_133172




B71_10M_QPSK_1@49_CH_133422




B71_10M_QPSK_50@0_CH_133422




B71_10M_16QAM_1@49_CH_133422




B71_10M_16QAM_50@0_CH_133422




B71_5M_QPSK_1@0_CH_133147




B71_5M_QPSK_25@0_CH_133147



B71_5M_16QAM_1@0_CH_133147




B71_5M_16QAM_25@0_CH_133147




B71_5M_QPSK_1@24_CH_133447

B71_5M_QPSK_25@0_CH_133447




B71_5M_16QAM_1@24_CH_133447




B71_5M_16QAM_25@0_CH_133447




B71_20M_64QAM_1@0_CH_133222




B71_20M_64QAM_100@0_CH_133222



B71_20M_64QAM_1@99_CH_133372




B71_20M_64QAM_100@0_CH_133372




B71_15M_64QAM_1@0_CH_133197




B71_15M_64QAM_75@0_CH_133197




B71_15M_64QAM_1@74_CH_133397




B71_15M_64QAM_75@0_CH_133397




B71_10M_64QAM_1@0_CH_133172




B71_10M_64QAM_50@0_CH_133172



B71_10M_64QAM_1@49_CH_133422




B71_10M_64QAM_50@0_CH_133422




B71_5M_64QAM_1@0_CH_133147




B71_5M_64QAM_25@0_CH_133147




B71_5M_64QAM_1@24_CH_133447




B71_5M_64QAM_25@0_CH_133447



# APPENDIX 1 PHOTOS OF TEST SETUP

See test photos attached in Appendix 1 for the actual connections between Product and support equipment.

# APPENDIX 2 PHOTOS OF EUT CONSTRUCTIONAL DETAILS

Refer to Appendix 2 for EUT external and internal photos.

*** End of Report ***

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of UnionTrust, this report can't be reproduced except in full.