










NTNV_N2_PC3_15_5_L_TID16_N/A_0.009_0.15
_#1


NTNV_N2_PC3_15_5_L_TID16_N/A_0.15_30_#1



NTNV_N2_PC3_15_5_L_TID16_N/A_30_1000_#1





NTNV_N2_PC3_15_5_L_TID16_N/A_1000_3000_#1





NTNV_N2_PC3_15_5_L_TID16_N/A_3000_12000_0_#1


NTNV_N2_PC3_15_5_L_TID16_N/A_12000_20000_00_#1











NTNV_N2_PC3_15_5_M_TID5_N/A_30_1000_#1

NTNV_N2_PC3_15_5_M_TID5_N/A_1000_3000_#1

NTNV_N2_PC3_15_5_M_TID5_N/A_3000_12000_#1

NTNV_N2_PC3_15_5_M_TID5_N/A_12000_20000_#1

