
















NTNV_N41_PC2_30_50_M_TID16_N/A_30_1000
_#1




NTNV_N41_PC2_30_50_M_TID16_N/A_1000_30
00_#1



NTNV_N41_PC2_30_50_M_TID16_N/A_3000_18
000_#1



NTNV_N41_PC2_30_50_M_TID16_N/A_18000_2
6500_#1





NTNV_N41_PC2_30_50_M_TID17_N/A_30_1000
_#1





NTNV_N41_PC2_30_50_M_TID17_N/A_1000_30
00_#1


















NTNV_N41_PC2_30_50_H_TID17_N/A_3000_18
000_#1NTNV_N41_PC2_30_50_H_TID17_N/A_18000_2
6500_#1

NTNV_N41_PC2_30_60_L_TID6_N/A_30_1000_#1

NTNV_N41_PC2_30_60_L_TID6_N/A_1000_300
0_#1NTNV_N41_PC2_30_60_L_TID6_N/A_3000_180
00_#1NTNV_N41_PC2_30_60_L_TID6_N/A_18000_26
500_#1

