














NTNV_N41_PC2_30_80_M_TID18_N/A_30_1000
_#1NTNV_N41_PC2_30_80_M_TID18_N/A_1000_30
00_#1NTNV_N41_PC2_30_80_M_TID18_N/A_3000_18
000_#1NTNV_N41_PC2_30_80_M_TID18_N/A_18000_2
6500_#1NTNV_N41_PC2_30_80_M_TID16_N/A_30_1000
_#1NTNV_N41_PC2_30_80_M_TID16_N/A_1000_30
00_#1




NTNV_N41_PC2_30_80_M_TID17_N/A_3000_18
000_#1




NTNV_N41_PC2_30_80_M_TID17_N/A_18000_2
6500_#1



NTNV_N41_PC2_30_80_H_TID6_N/A_30_1000_
#1





NTNV_N41_PC2_30_80_H_TID6_N/A_1000_300
0_#1





NTNV_N41_PC2_30_80_H_TID6_N/A_3000_180
00_#1


NTNV_N41_PC2_30_80_H_TID6_N/A_18000_26
500_#1

























NTNV_N41_PC2_30_90_M_TID6_N/A_30_1000_

#1




NTNV_N41_PC2_30_90_M_TID6_N/A_1000_300

0_#1



NTNV_N41_PC2_30_90_M_TID6_N/A_3000_180

00_#1



NTNV_N41_PC2_30_90_M_TID6_N/A_18000_26

500_#1



NTNV_N41_PC2_30_90_M_TID4_N/A_30_1000_

#1



NTNV_N41_PC2_30_90_M_TID4_N/A_1000_300

0_#1

