











NTNV_N71_PC3_15_15_H_TID5_N/A_3000_120
00_#1

NTNV_N71_PC3_15_15_H_TID5_N/A_12000_20
000_#1

NTNV_N71_PC3_15_15_H_TID18_N/A_0.009_0.
15_#1


NTNV_N71_PC3_15_15_H_TID18_N/A_0.15_30_
#1





NTNV_N71_PC3_15_15_H_TID17_N/A_0.009_0.

15_#1




NTNV_N71_PC3_15_15_H_TID17_N/A_0.15_30_

#1




NTNV_N71_PC3_15_15_H_TID17_N/A_30_1000

_#1



NTNV_N71_PC3_15_15_H_TID17_N/A_1000_30

00_#1



NTNV_N71_PC3_15_15_H_TID17_N/A_3000_12

000_#1

NTNV_N71_PC3_15_15_H_TID17_N/A_12000_2

0000_#1

