











NTNV_N77-3450-3550_PC2_30_15_M_TID5_N/A
_0.009_0.15_#1

NTNV_N77-3450-3550_PC2_30_15_M_TID5_N/A
_0.15_30_#1


NTNV_N77-3450-3550_PC2_30_15_M_TID5_N/A
_30_1000_#1

NTNV_N77-3450-3550_PC2_30_15_M_TID5_N/A
_1000_3000_#1


NTNV_N77-3450-3550_PC2_30_15_M_TID5_N/A
_3000_6000_#1




NTNV_N77-3450-3550_PC2_30_15_M_TID5_N/A
_6000_26000_#1



NTNV_N77-3450-3550_PC2_30_15_M_TID5_N/A
_26000_40000_#1



NTNV_N77-3450-3550_PC2_30_15_M_TID18_N/
A_0.009_0.15_#1



NTNV_N77-3450-3550_PC2_30_15_M_TID18_N/
A_0.15_30_#1

NTNV_N77-3450-3550_PC2_30_15_M_TID18_N/
A_30_1000_#1

