






NTNV_N77-3450-3550_PC2_30_15_H_TID16_N/
A_3000_6000_#1

NTNV_N77-3450-3550_PC2_30_15_H_TID16_N/
A_6000_26000_#1

NTNV_N77-3450-3550_PC2_30_15_H_TID16_N/
A_26000_40000_#1

NTNV_N77-3450-3550_PC2_30_15_H_TID17_N/
A_0.009_0.15_#1








NTNV_N77-3450-3550_PC2_30_20_L_TID6_N/A
_0.009_0.15_#1

NTNV_N77-3450-3550_PC2_30_20_L_TID6_N/A
_0.15_30_#1

NTNV_N77-3450-3550_PC2_30_20_L_TID6_N/A
_30_1000_#1

NTNV_N77-3450-3550_PC2_30_20_L_TID6_N/A
_1000_3000_#1

NTNV_N77-3450-3550_PC2_30_20_L_TID6_N/A
_3000_6000_#1NTNV_N77-3450-3550_PC2_30_20_L_TID6_N/A
_6000_26000_#1NTNV_N77-3450-3550_PC2_30_20_L_TID6_N/A
_26000_40000_#1NTNV_N77-3450-3550_PC2_30_20_L_TID4_N/A
_0.009_0.15_#1NTNV_N77-3450-3550_PC2_30_20_L_TID4_N/A
_0.15_30_#1NTNV_N77-3450-3550_PC2_30_20_L_TID4_N/A
_30_1000_#1



