






NTNV\_N77-3700-3980\_PC2\_30\_10\_L\_TID5\_NS\_01\_3000\_6000\_#1


NTNV\_N77-3700-3980\_PC2\_30\_10\_L\_TID5\_NS\_01\_6000\_26000\_#1


NTNV\_N77-3700-3980\_PC2\_30\_10\_L\_TID5\_NS\_01\_26000\_40000\_#1

NTNV\_N77-3700-3980\_PC2\_30\_10\_L\_TID18\_NS\_01\_0.009\_0.15\_#1











NTNV\_N77-3700-3980\_PC2\_30\_10\_L\_TID17\_NS  
\_01\_1000\_3000\_#1


NTNV\_N77-3700-3980\_PC2\_30\_10\_L\_TID17\_NS  
\_01\_3000\_6000\_#1


NTNV\_N77-3700-3980\_PC2\_30\_10\_L\_TID17\_NS  
\_01\_6000\_26000\_#1


NTNV\_N77-3700-3980\_PC2\_30\_10\_L\_TID17\_NS  
\_01\_26000\_40000\_#1














NTNV\_N77-3700-3980\_PC2\_30\_10\_M\_TID18\_N  
S\_01\_6000\_26000\_#1

NTNV\_N77-3700-3980\_PC2\_30\_10\_M\_TID18\_N  
S\_01\_26000\_40000\_#1

NTNV\_N77-3700-3980\_PC2\_30\_10\_M\_TID16\_N  
S\_01\_0.009\_0.15\_#1

NTNV\_N77-3700-3980\_PC2\_30\_10\_M\_TID16\_N  
S\_01\_0.15\_30\_#1

