

	1	2	3	4	5	6	
A	GENERAL INSTRUCTIONS: SUPPLIER TO INSURE CORRECT REVISION LEVEL DWG FOR PRODUCTION. CONTACT SB&D PURCHASING DEPT. FOR LATEST REVISION LEVEL DWG. CONTACT SB&D GRAPHICS DESIGN FOR ORIGINAL ARTWORK, COLOR STANDARDS AND CORPORATE GUIDELINES. PROOFS OF ALL REVISIONS THAT AFFECT ARTWORK AND ALL NEW COLOR FORMULATIONS MUST BE SUBMITTED TO SB&D GRAPHICS DESIGN FOR APPROVAL PRIOR TO MAKING PRODUCTION PARTS. SEE EP-1006. SUPPLIER TO PROVIDE SB&D GRAPHICS DESIGN WITH 6 SAMPLES OF ALL PRODUCTION PARTS. MARK B&D PART NO. AND REVISION LEVEL.						A
	COLOR VARIATIONS: NO COLOR - COPY LASER ETCHED						
B	INTEGRAL MARKING PROCESS: MARKING PROCESS TO BE USED... ☐ EMBOSSED: (molded in housing) RAISED COPY ☐ DEBOSSED: (molded in housing) RECESSED COPY ☐ INDIVIDUAL COLOR RUBBER DIE PRINTING PROCESS ☐ INDIVIDUAL COLOR HOT STAMP TAPE PROCESS ☐ SILK SCREEN PROCESS ☐ IN-MOLD DECORATIVE TRANSFER PROCESS ☐ HOT STAMP SYNTHETIC LABEL PROCESS ☐ PAD TRANSFER PRINTING ☒ LASER ETCH (RECESSED COPY) ☐ OTHER _____						